Response Action Contract Contract No. 68-W-98-228 PEPA United States Environmental Protection Agency

Five-Year Review Report (Third) Five-Year Review United Chrome Products Site Corvallis, Oregon March 2003

URS Greiner
In association with
CH2M HILL
White Shield, Inc.

Five-Year Review Report

(Third) Five-Year Review Report

for

United Chrome Products

ORD009043001

Corvallis

Benton County, Oregon

March 2003

PREPARED BY:

USEPA Region 10 Oregon Operations Office Portland, Oregon

Date:

Approved by:

Michael F. Gearheard

Director, Environmental Cleanup Office

U.S. EPA Region 10

Five-Year Review Summary Form

SITE IDENTIFICATION						
Site name (from WasteLAN): United Chrome Products Superfund Site						
EPA ID (from WasteLAN): ORD009043001						
Region: 10	egion: 10 State: OR City/County: Corvallis/Benton					
		SITE STATUS				
NPL status: 🛛 Fin	al Deleted Dothe	r (specify)				
Remediation statu	s (choose all that apply): Under Construction Operating Complete				
Multiple OUs?*	YES ⊠ NO	Construction completion date: 8 / 15 / 1988				
Has site been put	into reuse? 🛚 YES	☐ NO Small portion of site redeveloped for propane distribution				
		REVIEW STATUS				
Lead agency: 🛛 🛭	PA State Tribe	Other Federal Agency				
Author name: Ala	n Goodman					
Author title: Reme	edial Project Manager	Author affiliation: U.S. EPA, Region 10				
Review period:**	12 / 4 / 2002 to 3 / 24	/ 2003				
Date(s) of site ins	pection: 12/5/200	2 and 1 / 11 / 2003				
Type of review:						
	☐ Post-SARA ☐ Pre-SARA ☐ NPL-Removal only					
	☐ Non-NPL Remedial Action Site ☐ NPL State/Tribe-lead					
☐ Regional Discretion						
Review number: ☐ 1 (first) ☐ 2 (second) ☒ 3 (third) ☐ Other (specify)						
Triggering action:						
Actual RA On-site	Construction at OU #	· · · · · · · · · · · · · · · · · · ·				
☐ Construction Completion ☑ Previous Five-Year Review Report						
Other (specify)						
Triggering action date (from WasteLAN): 3 / 24 / 1998						
Due date (five years after triggering action date): 3 / 24 / 2003						

^{* [&}quot;OU" refers to operable unit.]

** [Review period should correspond to the actual start and end dates of the Five-Year Review in WasteLAN.]

Five-Year Review Summary Form, cont'd.

Issues:

Although no specific cleanup standard for soil was identified in the ROD, the upper zone remedy is not expected to achieve further chromium concentration reductions in upper zone soil. The levels currently present will prevent the site from achieving an unrestricted use and unrestricted exposure status.

Concerns have been expressed in the past about subsurface soil contamination that might be present beneath the concrete floor of the former United Chrome Products building. Subsurface soil sampling performed beneath the floor during a July 2000 investigation did not reveal the presence of elevated chromium concentrations (United Chrome – Phase 2 Upper Zone Groundwater Source Investigation Results (CH2M HILL, August 2000).

The deep aquifer remedy was not successful in blocking or controlling the drainage of chromium contaminated pore water from the upper aquitard. Consequently, it is unlikely that the ROD performance standard for deep aquifer groundwater can be achieved, and compliance demonstrated, at two of the eight remaining well locations.

Concerns regarding historical chromium contamination detected in offsite sediments have also been raised,

Recommendations and Follow-up Actions:

Evaluate the hydrogeology and contaminant transport between the soil, upper zone, upper aquitard, and lower aquifer as necessary to understand the causes of the recent groundwater contaminant trends. Based on the results of this evaluation, re-evaluate the clean-up levels and current remedial approach.

Place additional institutional controls for land use restrictions as needed.

Collect data on site-related contamination in the down-gradient drainage ditches and water bodies, and then evaluate the ecological risks posed by these sediments.

Protectiveness Statement(s):

A protectiveness determination of the remedy at the United Chrome Products site cannot be made at this time until further information is obtained. Further information to determine whether the remedy currently protects human health and the environment will be obtained by the data collection and ecological evaluation of the down-gradient drainage ditches and surface water. It is expected that these actions will take six months to complete, at which time a protectiveness determination will be made. The soil and lower aquifer remedy currently protects human health and the environment because the site is fenced and not being used and the area of the lower aquifer with contamination above the chromium MCL is not being used for drinking water. Additional actions described in the recommendations above are needed to ensure long-term protectiveness.

Other	Comm	ients:
-------	------	--------

Contents

Section	on		Page
Execu	ıtive S	Summary	ES-1
1.	Intr	roduction	1-1
	1.1	Objectives	
	1.2	Summary of Work Performed	
1.2.1	Doc	cument Review	
1.2.2		ndards Review	
1.2.3	Con	nmunity Interviews	1-2
1.2.4		Inspection1-2	
1.2.5		pare Five-Year Report	1-2
		Current Site Status	
2.	Site	Chronology	2-1
3.	Bac	kground	3-1
	3.1		
		3.1.1 Location Description	3-1
		3.1.2 Sensitive Habitat	3-1
		3.1.3 Hydrogeology	3-2
		3.1.4 Surface Water Hydrology	3-2
	3.2	Land and Resource Use	3-2
	3.3	History of Contamination	3-3
	v .	3.3.1 Discovery	3-3
	3.4	Initial Response	3-4
	3.5	Basis for Taking Action	3-4
		3.5.1 Public Health and Environmental Impacts	3-4
	3.6	Feasibility Study	3-5
4.	Ren	nedial Actions	4-1
	4.1	Remedy Selection	4-1
		4.1.1 ROD Amendments or Explanation of Significant Differer	nces4-1
		4.1.2 Remedial Action Objectives	4-1
		4.1.3 Remedy Description	4-2
	4.2	Remedy Implementation	4-2
		4.2.1 Phase I Design and Construction	4-3
•		4.2.2 Phase II Design and Construction	
		4.2.3 Supplemental Engineering and Institutional Controls	
	4.3	System Description and Operations	
		4.3.1 Groundwater Extraction Wells	
		4.3.2 Infiltration System	

		4.3.3	Groundwater Treatment System	4-9
		4.3.4	Performance Monitoring Program	4-11
	4.4	Respon	nsible Party Lead Actions	
	4.5	Operat	tion and Maintenance Costs	4-13
5.	Prog	gress Sir	nce the Last Five-Year Review	5-1
6.	Five	-Year R	eview Process	6-1
	6.1	Admin	istrative Components	6-1
	6.2	Comm	unity Involvement	6-1
	6.3	Review	of Applicable or Relevant and Appropriate Requirements	6-1
	6.4		nent and Data Review	
	6.5	Site Ins	spection	6-2
		6.5.2	Site Cover	6-3
		6.5.3	Groundwater Remedy	6-3
		6.5.4	Onsite Drainage	6-9
		6.5.5	Site Safety	6-9
	6.6	Comm	unity Interviews	6-10
		6.6.1	Site Operations Personnel	6-10
		6.6.2	Community Organizations	6-10
		6.6.3	Mailed Questionnaires	6-11
		6.6.4	Local Residents	6-11
7.	Tecl	hnical A	ssessment	7-1
	7.1	Is the F	Remedy Functioning as Intended?	7-1
		7.1.1	Remedial Action Performance	7-1
		7.1.2	System Operations	7-3
		7.1.3	Implementation of Institutional Controls and Other Measure	es 7-3
		7.1.4	Opportunities for Optimization	7-4
		7.1.5	Indicators of Potential Remedy Problems	7-5
	7.2	Have t	he Assumptions on Which the Remedy was Based Changed?	7-6
		7.2.1	Changes in Standards and to be Considered	7-6
		7.2.2	Changes in Cleanup Levels	7-7
		7.2.3	Changes in Exposure Pathways	7-7
	7.3	Has Ar	ny Other Information Come to Light that Could	
		Effect t	he Remedy's Protectiveness?	7-8
		7.3.1	DEQ Recommendations	7-9
	7.4	Techni	cal Assessment Summary	7-10
8.	Issu	es		8-1
9.	Rec	ommend	lations and Follow-up Actions	9-1
10	Prot	activane	ice Statement	10-1

11.	Next Review	11-1
12.	References	12-1
Appe	ndices	
Α	Site Interview and Inspection Summary	
В	Upper Zone Groundwater Pumping Data	
C	Deep Aquifer Groundwater Pumping Data	
D	United Chrome Deed Restriction	
Table	28 · · · · · · · · · · · · · · · · · · ·	
2-1	Site Chronology	2-1
3-1	Feasibility Study Alternatives Summary	
4-1	Treatment System Improvements	
4-2	Upper Zone Remedial Action Monitoring and Reporting Schedule	
4-3	Deep Aquifer Remedial Action Monitoring and Reporting Schedule	
4-4	Well Abandonment History	
5-1	Status of Recommendations Provided in Second Five-Year Review	
6-1	United Chrome Well Inventory – January 2003	
7-1	Comparison of Annual O&M Costs	
7-2	Comparison of Groundwater and Soil Cleanup Levels	
8-1	Issues Potentially Affecting Remedy's Current or Future Protectiveness.	
Figu	res	
_		
3-1	Vicinity Map	
3-2	Site Plan in 1992	
3-3	Generalized Hydrogeologic Cross-section	•
3-4	Initial Distribution of Cr(VI) in Upper Zone and Deep Aquifer	
4-1	Upper Zone Groundwater Extraction and Monitoring Well Network	
4-2	Upper Zone Extraction Well Installation Detail	
4-3	General Operations Data	
4-4	Deep Aquifer Groundwater Extraction and Monitor Well Network	
4-5	Groundwater Treatment System	
4-6	General Treatment System Operations Data	
6-1	Site Plan – December 2002	
7-1	Chromium Plume Boundary Changes in Upper Zone Groundwater – 1988, 1993, 1998, and 2002	
7-2a	Upper Zone Groundwater Chromium Concentration Trends	
7-2b	Upper Zone Groundwater Chromium Concentration Trends	
7-3	Chromium Plume Boundary Changes in Deep Aquifer Groundwater – 1991, 1993, 1998, and 2002	
7-4	Areas of Upper Zone Soil with Chromium Concentrations Greater than 1.0E-06 Protective Level for Residential Exposure	
7-5	Deep Aquifer Groundwater Chromium Concentration Trends	

CYO/030480004 V

Acronyms and Abbreviations

aka

Also known as

ARARs

Applicable or relevant and appropriate requirements

bgs

below ground surface

CERCLA

Comprehensive Environmental Response, Compensation, and

Liability Act

CERCLIS

Comprehensive Environmental Response, Compensation, and

Liability Act Information Systems

CIC

Community Involvement Coordinator

City

City of Corvallis

DEQ

Oregon Department of Environmental Quality

DW

Extraction Well (deep aquifer)

ESD

Explanation of Significant Difference

EW

Extraction Well (upper zone)

FAA

Federal Aviation Administration

FS

Feasibility study

gpm

gallon per minute

HDPE

high-density polyethylene

HSP

Health and Safety Plan

Kg

Kilogram

L

Liter

LTRA

Long-term Remedial Action

MCL

Maximum Contaminant Level

mg

Milligram

MSDS

Materials Safety Data Sheet

MW

Monitor Well

NPL

National Priorities List

O&M

Operation and Maintenance

OAR Oregon Administrative Rules

ORS Oregon Revised Statutes

OWRD Oregon Water Resources Department

PCOR Preliminary Closeout Report

POTW publicly owned treatment works

PPE personal protective equipment

PRG Preliminary Remedial Goal

PVC Polyvinyl Chloride

PZ Piezometer

RAC Remedial Action Contract

RCRA Resource Conservation and Recovery Act

RI remedial investigation

ROD Record of decision

RP Responsible Party

RPM Remedial Project Manager

SARA Superfund Amendment and Reauthorization Act

SSC site safety coordinator

SPLP Synthetic Precipitation Leaching Procedure

TCLP Toxicity Characteristic Leaching Procedure

USEPA or United States Environmental Protection Agency

EPA

USFWS United States Fish and Wildlife Service

Executive Summary

This report presents the findings of the third five-year review performed for the United Chrome Products Superfund site located in Corvallis, Oregon. The five-year review was performed to confirm that immediate threats to human health and the environment have been addressed through implementation of the selected remedy.

The five-year review, which was conducted in accordance with the *Comprehensive Five-year Review Guidance* (U.S. Environmental Protection Agency, June 2001), included the following activities:

- Review of changes to Federal, State and local regulations that could affect the remedy's overall protectiveness with respect to the performance standards specified in the Record of Decision.
- A site inspection to confirm that the remedy is operating and being maintained in accordance with expectations.
- Interviews with community representatives and local residents to obtain an independent appraisal of the cleanup effort and to identify any remaining concerns associated with the site.
- Review of performance monitoring data to determine compliance with the groundwater performance standards specified in the Record of Decision and to assess current and long-term protectiveness.

This five-year review has concluded that a protectiveness determination of the remedy at United Chrome cannot be made at this time until further information is obtained. The soil and lower aquifer remedy currently protects human health and the environment because the site is fenced and not being used and the area of the lower aquifer with contamination above the MCL is not being used for drinking water. Additional actions described in the recommendations in Section 8 are needed to ensure long-term protectiveness.

Based on the long-term protectiveness findings, it is recommended that the remedy and groundwater cleanup goals specified in the Record of Decision be re-evaluated in light of the current understanding of subsurface conditions, and expectations for future site land and groundwater beneficial uses. To determine if chromium contamination detected in historical sediment samples poses a risk to ecological resources, it is recommended that the results of surface water and sediment sampling recently completed by the responsible party be reviewed against potentially applicable standards.

CVO/030480004 ES-1

1. Introduction

1. Introduction

The United States Environmental Protection Agency (EPA) Region 10 has conducted a five-year review of completed and ongoing remedial action at the United Chrome Products Superfund site (United Chrome or the site) in Corvallis, Oregon, as required under §121 of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA). This five-year review, which is the third conducted for the site, was triggered by the March 24, 1998, signature date for the second five-year review. This five-year review has been identified as a policy review because the Record of Decision (ROD) for the site was signed on September 12, 1986, approximately one month prior to promulgation of the Superfund Amendment and Reauthorization Act (SARA).

1.1 Objectives

The primary objective for this five-year review is to confirm that immediate threats to human health and the environment have been addressed through implementation of the selected remedy. Since the site's long-term remedial actions are ongoing, the five-year review also evaluated specific elements of the remedy to verify that construction and operation are performing in accordance with expectations.

1.2 Summary of Work Performed

The five-year review was conducted between December 4, 2002, and February 24, 2003, by CH2M HILL in accordance with EPA Work Assignment # 102-FR-FE-1032. A majority of this work was performed by CH2M HILL's site manager, who has been involved in the project for 15 years, initially as a hydrogeologist and for the last 10 years as the site manager. CH2M HILL's work was reviewed by Alan Goodman, EPA's Remedial Project Manager (RPM) for United Chrome. Specific tasks related to the acquisition of information presented in subsequent chapters of this report are described in the following subsections.

1.2.1 Document Review

Because of the site manager's familiarity with United Chrome's historical record, no document review was needed for this five-year review effort.

1.2.2 Standards Review

The purpose for this task was to research and identify changes in applicable or relevant and appropriate requirements (ARARs), promulgated since the ROD was signed, that might effect the overall protectiveness of the remedy. Regulation changes were identified through reviews of the Federal Register, Oregon Revised Statues (ORS), Oregon Administrative Rules (OAR) and City of Corvallis and Benton County information.

CVO/030480004 1-1

1.2.3 Community Interviews

CH2M HILL interviewed a number of individuals with historical involvement at the site. These individuals included the current site operations and maintenance manager, the City of Corvallis Airport Manager (the United Chrome site lies within the airport complex), the Corvallis - Benton County Economic Development Council Manager, the Deputy Administrator for the Benton County Health Department, and several residents living within a 1.5-mile radius of the site. CH2M HILL also mailed questionnaires to individuals on the current United Chrome mailing list with no media or local government affiliation. The interview findings were documented in the *Site Inspection and Interview Report* (CH2M HILL Memorandum, January 29, 2003) included as Appendix A to this report.

1.2.4 Site Inspection

The purpose of this task was to conduct a technical compliance inspection focusing on those elements of the remedy necessary to protect human health and the environment. The inspection considered operator safety, the groundwater extraction system, fencing, cover integrity, current as-built conditions, and institutional controls. Field observations were recorded on an inspection form obtained from the *Comprehensive Five-Year Review Guidance* (EPA, June 2001). The site inspection was designed to complement a prior comprehensive inspection completed in 1999 and documented in the *United Chrome Site Inspection* (CH2M HILL, Memorandum, July 30, 1999).

1.2.5 Prepare Five-Year Report

This task included activities related to the preparation of the five-year review report, which documents how the implemented remedy protects human health and the environment. The five-year review report was generally organized in accordance with the format provided in Appendix E of the Comprehensive Five-Year Review Guidance (EPA, June 2001).

1.3 Current Site Status

United Chrome is the site of an ongoing, long-term remedial action (LTRA). The site remedy initially included groundwater pumping from 23 shallow wells and seven deep wells, and flushing of chromium-contaminated soil using two shallow infiltration basins. Extracted groundwater was pumped to an onsite chemical reduction and precipitation treatment system to convert soluble hexavalent chromium (Cr⁺⁶) to insoluble trivalent chromium (Cr⁺³) in a dry solid form. Solid-phase trivalent chromium was accumulated onsite in a roll-off box and transported every 90 days to the Chemical Waste Management facility in Arlington, Oregon.

The groundwater remedial action was initiated on August 15, 1988. Except for part-time operation during the startup phase, temporary shutdowns for cold weather, and a recent soil removal action, the system has operated continuously, logging 107,502 hours of operation for an overall efficiency of 85 percent. During this time, 32,004 pounds of chromium have been recovered from 78.7 million gallons of extracted groundwater.

1-2 CVO/030480004

The City of Corvallis, the responsible party (RP), has maintained full responsibility for operation of the groundwater extraction and treatment system, performance monitoring, and preparation of remedial action progress reports.

The remedial action has been highly successful and is currently in the final stages of operation. ROD performance standards have been achieved at all but three of the 30 extraction well locations, and at all 51 monitor well locations. EPA is currently reevaluating the appropriateness of site cleanup goals and will determine whether changes are warranted based on expectations for the site's future land and groundwater beneficial uses.

CVO/030480004 1-3

2. Site Chronology

This chapter provides a chronology (Table 2-1) of events related to the site's discovery, contamination history, and overall cleanup.

TABLE 2-1Site Chronology
United Chrome Products, Corvallis, OR

Activity	Start Date	End Date
United Chrome Products begins operations	1956	1985
Discovery	07/01/1979	-
Hazard Ranking Site (HRS) Assessment (Score = 31.7) and Site Inspection	06/27/1983	-
Proposed to National Priorities List (NPL)	09/09/1983	-
Final NPL Listing and Preliminary Assessment	09/21/1984	-
Remedial Investigation and Feasibility (RI/FS) Work Plan Approved	-	09/30/1984
Removal	07/02/1985	11/06/1985
Community Involvement	07/08/1985	08/28/1985
Remedial Investigation	03/11/1984	11/26/1985
Feasibility Study	11/1984	08/19/1985
Technical Assistance	04/19/1985	09/12/1986
Record of Decision	-	09/12/1986
Design Assistance	07/11/1985	09/11/1987
Remedial Design and Construction	02/04/1987	09/11/1987
Begin Upper Zone Groundwater Extraction and Treatment	08/15/1988	Ongoing
Administrative Order on Consent	-	08/07/1989
Removal Assessment	-	09/10/1990
Install Stage 1 and Stage 2 Deep Aquifer Monitor and Extraction Wells	09/01/1989	07/01/1990
Design and Construction of Surface Water Drainage Bypass Ditch Around the Site	09/1/1989	02/28/1990
Remedial Design/Remedial Action (RD/RA) Negotiations	03/05/1991	03/05/1991
NPL Responsible Party (RP) Search	11/29/1990	03/05/1991
Removal Assessment	-	07/24/1991
Explanation of Significant Differences	-	12/17/1991
Preliminary Closeout Report	-	12/19/1991
Consent Decree Negotiations and Section 107 Litigation	06/14/1992	09/21/1992
Lodging of Consent Decree by US District Court	-	06/29/1992
First Five-year Review	-	11/30/1992
Initiate Deep Aquifer Groundwater Extraction	08/15/1991	Ongoing
Deep Aquifer Groundwater Performance Standard Revised from	-	07/30/1992

TABLE 2-1 Site Chronology United Chrome Products, Corvallis, OR

Activity	Start Date	End Date
0.05 mg/L to 0.1 mg/L		
Removal Assessment	11/26/1993	11/26/1993
Management Assistance	08/01/1992	06/30/1996
Second Five-Year Review	-	03/24/1998
Phase 1 Upper Zone Groundwater Source Investigation	05/01/1998	10/15/1998
Phase 2 Upper Zone Groundwater Source Investigation	07/01/2000	08/28/2000
Upper Zone Soil Remedial Action Design Criteria Report	08/01/2000	08/31/2000
DEQ Human Health and Ecological Risk Screening	11/30/2001	08/20/2002
PRP Lead Activities		
Install Upper Zone Infiltration Trench	04/06/1990	06/30/1990
Local Pretreatment Limits Development (7-pound per discharge of partially (reduced) treated groundwater)	07/15/1991	01/01/1992
Discontinue Partially (Reduced) Treatment	02/03/1994	11/28/1994
Clean Chromium Contaminated Sediment from Onsite Culvert and Plug with Concrete	07/01/1991	10/01/1991
Abandon Upper Zone Wells EW-1, PL-2, PL-3, PL-4, PL-5, BG-2, MW-2A and Deep Aquifer Well DW-7. Convert Deep Aquifer Wells DW-9 and DW-10 from Injection to Extraction Wells.	06/01/1996	06/30/1996
Abandon Upper Zone Wells EW-19, EW-22, EW-24, EW-25, EW-26, SW-3, PZ-A, PZ-C and PZ-E.	05/01/1997	05/31/1997
Abandon Upper Zone Wells SW-2A and SW-4, and Deep Aquifer Wells DW-3A, DW-6 and DW-19	05/01/1998	05/31/1998
Abandon Upper Zone Wells EW-8, EW-28 and EW-29, and decommission Infiltration Basins 1 and 2 in Conjunction with Upper Zone Soil Removal.	08/15/2000	08/31/2000
Treatment Infrastructure Removed and Building Decommissioned	03/15/1999	04/15/1999
Upper Zone Soil Removal Action Work Plan Approved	-	09/13/2000
Upper Zone Soil Removal Project (1956 tons of Soil Excavated and Transported to Chemical Waste Management, Arlington, Oregon for Stabilization and Disposal)	09/11/2000	10/04/2000
Upper Zone Soil Removal Construction Report	-	01/15/2001
Abandon Upper Zone Wells EW-17, EW-18, EW-20, EW-21, BG-1, MW-1, PL-1, PZ-D, PZ-F and Deep Aquifer Wells DW-11, DW-14, DW-16 and DW-17.	06/01/2001	06/15/2001
Person-Down Alarm Discontinued due to Site Risk Reduction	•	01/31/2003

References:

- CERCLIS United Chrome Products Site, Corvallis, Oregon. United Chrome Products Region 10 Superfund Home Page.
- 2. CH2M HILL Files.
- 3. City of Corvallis Public Works Wastewater Treatment Plant Files.

2-2 CVO/030480004

3. Background

This chapter presents a brief overview of the United Chrome site's physical characteristics, discovery and contamination history, and investigations leading up to the understanding of site conditions as documented in the remedial investigation and feasibility study (RI/FS) report. The purpose of this chapter is to identify the threat posed to the public and the environment at the time of the ROD. New information obtained through the course of subsequent design investigations and LTRA operations, with the potential to effect the remedy's overall protectiveness, is presented in the Technical Assessment provided in Chapter 7 of this document.

3.1 Physical Characteristics

This section describes the United Chrome site's physical characteristics including geographic information, a description of the hydrogeologic strata underlying the site, and a description of surface water drainages hydraulically connected with the site's shallow groundwater flow system.

3.1.1 Location Description

The United Chrome site is a former industrial hard-chrome plating facility located at 2000 Airport Place (a.k.a. Ingalls St), in the Airport and Industrial Research Park (airport complex), approximately 3.5 miles south of Corvallis, Oregon (Figure 3-1). The 1.5-acre site is relatively flat, with an average ground surface elevation of 240 feet mean sea level (msl).

The site (Figure 3-2) is bounded by a City of Corvallis Airport runway and taxiway to the south and west; agricultural land, the bypass ditch, and CoEnergy (propane distributor) to the north; undeveloped property, airplane hangars, and Bertea Aviation to the east; and Ferrill Gas (propane distributor) to the south. The United Chrome site and all contiguous properties are owned by the City of Corvallis.

The site is situated in a sparsely populated section of Benton County, at the southern limits of the City of Corvallis' urban growth boundary. Benton County is located in the heart of the Willamette Valley in west-central Oregon. With approximately 78,000 residents, Benton County is the 11th largest county, in terms of population, in Oregon. The residential area nearest to the United Chrome site is located approximately 4,400 feet to the northeast alongside and east of State Highway 99W. There are approximately 50 homes in this area, all of which obtain their water from private wells.

3.1.2 Sensitive Habitat

Three national wildlife refuges - Ankeny, Baskett Slough and William L. Finley - are located within 5 miles of the United Chrome site. These refuges include a variety of wildlife habitats such as wetlands, prairies, riparian and upland forests, and cultivated farmlands. The refuges provide important wintering habitat for the dusky Canada goose, a species of concern within the Pacific Flyway, and six other subspecies of Canada geese. Several

CVO/030480004 3-1

endangered plants and the endangered Fender's blue butterfly also occur within the refuge boundaries. According to U.S. Fish and Wildlife Service (USFWS) information, the refuges receive about 180,000 visitors a year.

Although site soils and vegetation may exhibit one or more characteristics typical of a wetland, the United Chrome property was not identified as a wetland through the recently completed Oregon Division of Lands Local Wetland Inventory (National Wetland Inventory, Wetlands and Hydric Soils, Southern Corvallis, 2000). Recent mapping (Corvallis General Flood Hazard Map, 2000) also shows that the United Chrome site lies above the 100-year floodplain.

3.1.3 Hydrogeology

The hydrogeology beneath the United Chrome site is characterized by two water-bearing zones separated by an aquitard. The uppermost water-bearing zone (upper zone), which occurs at depths between ground surface and 20 feet, is comprised of silt and fine sand. Beneath the upper zone is the upper aquitard, a layer of stiff, silty clay varying in thickness from 1.5 to 5.5 feet. Beneath the upper aquitard is the lower water-bearing zone (deep aquifer), which occurs at depths of approximately 25 feet to 45 feet beneath the site, extending to a depth of 75 feet to the northeast (Figure 3-3). The deep aquifer is comprised of sand and silt-cemented gravel capable of supplying water for domestic, commercial, and industrial uses. Because of its low permeability and variable saturated thickness, there are no recognized beneficial uses for upper zone groundwater other than deep aquifer recharge.

Horizontal groundwater flow velocities in the upper zone are approximately 9 feet per year and 44 feet per year in the deep aquifer. Groundwater also flows vertically down from the upper zone to the deep aquifer at a rate of 11 feet per year. Groundwater in both zones flows in a northeasterly direction, ultimately discharging to the Willamette River about 2 miles away.

3.1.4 Surface Water Hydrology

In late 1989, a bypass ditch was constructed around the northern perimeter of the United Chrome site to isolate it hydraulically from the surface drainage network. Most onsite surface water now infiltrates down through the soil column to the upper zone.

Prior to construction of the bypass ditch, surface water runoff drained overland to shallow drainage ditches bordering the west and north site boundaries. Runoff from these drainage ditches discharged to a deep culvert passing beneath the site (see Figure 3-2). From this culvert, surface water flowed east to Airport Place and then north to Airport Avenue (a.k.a. Airport Road). The ditch parallels Airport Avenue for approximately 0.5-mile before flowing southeast beneath the railroad tracks and State Highway 99W where it discharges to Dry Creek. Dry Creek flows northeast for approximately 1,500 feet where it converges with the West Fork of the Booneville Slough. The Booneville Slough eventually merges with the Willamette River, which is a primary source of drinking water for the City of Corvallis.

3-2 CVD/030480004

3.2 Land and Resource Use

The land surrounding the United Chrome site currently supports agricultural (non-food grass seed), aviation, and light industrial use. The site is zoned under the City of Corvallis Comprehensive Land Use Plan as general industrial. According to the airport master plan (personal communication, January 11, 2003) this portion of the airport property has been designated as a fuel farm. After the cleanup has been completed, Ferrill Gas is expected to relocate their propane fueling station inside the United Chrome site fence.

With respect to current groundwater use, there are no known groundwater users within 0.5-mile of the site. The nearest residential drinking water wells are located approximately 4,400 feet northeast alongside and east of State Highway 99. It is estimated there are 50 wells in this area. The City also has two inactive water supply wells in the area. The nearest well, identified as CW-3, is located approximately 700 feet northeast of the site, and a second well approximately 3000 feet northeast. Although the wells are still in place, the pumps and wellhead piping have been removed.

Under Oregon Revised Statute (ORS) 536.340 and Oregon Administrative Rule (OAR) 690-500 to 520, the Oregon Water Resources Department (OWRD) may classify groundwater resources for current and future specific uses. The United Chrome site lies within the Mid-Willamette Basin, and as such, groundwater has been designated to support a broad array of uses including drinking. In conjunction with the requirements of a consent decree, (Civil Action No. 92-6232-H0, October 14, 1992), the City established a 1,250-foot by 1,250-foot groundwater pumping exclusion zone around the site. This institutional control prevents installation of any new wells within this designated area.

The Willamette River is a primary drinking water source for the City of Corvallis and supports warmwater fish, such as large mouth and small mouth bass, crappie, bluegill, catfish, and carp. The Willamette River also supports anadromous fish passage, which include Chinook salmon and steelhead trout.

3.3 History of Contamination

United Chrome Products leased the property from the City and began electroplating operations at the site in 1956. In the same year, the operators constructed a dry well disposal pit outside the southwest building corner. Between 1956 and 1975, the dry well disposal pit was reportedly used to dispose of floor drippings, washings, and product rinsate collected within a building sump. Quantities of waste disposed in this manner are unknown, but were estimated by the facility operator to be approximately 1,000 gallons per year. Other probable sources of contamination include leakage from the two plating tanks inside the building, and spillage from the acid and caustic storage tanks maintained outside the building, north of the dry well. United Chrome Products ceased operations in early 1985 and sold the equipment and building contents in May 1985.

3.3.1 Discovery

Contamination at the United Chrome Products site was initially discovered during Oregon Department of Environmental Quality (DEQ) Resource Conservation and Recovery Act

CVO/030480004 3-3

(RCRA) compliance inspections. These inspections resulted in subsequent surface water and sediment sampling by DEQ staff beginning in November 1982. Based on the results of this sampling, the site was referred to EPA for a Hazard Ranking Site Assessment in 1983, which yielded a score of 31.7 and eventual placement on the EPA National Priorities List (NPL).

3.4 Initial Response

Accumulated sludges from the two plating tanks were removed from the site in 1982 and disposed under DEQ guidelines. In 1983, following two DEQ Notices of Violation, United Chrome Products removed chromium sludge from the disposal pit area and placed it in drums that were later disposed of at a RCRA-permitted land disposal facility. EPA placed the site on the NPL on September 21, 1984, because of suspected surface water, soil, and groundwater contamination. EPA also conducted a removal action at the site from July to November 1985 that included removal of 8,130 gallons of chromium-contaminated liquid from tanks and containers, and 11,000 pounds of chromium-contaminated soil.

3.5 Basis for Taking Action

A CERCLA Remedial Investigation (RI) and Feasibility Study (FS) was completed in August 1985 by CH2M HILL and Ecology & Environment, Inc. Because the facility was still active during the RI, contamination beneath the facility building was not characterized. The RI confirmed that high levels of chromium were present in soil and groundwater, and in surface water and sediment downstream of the site.

Soil in the vicinity of the dry well had the highest levels of chromium observed onsite. Concentrations ranged from a high of 200,900 milligrams per kilogram (mg/kg) at the surface to 29,500 mg/kg at a depth of 12 to 15 feet below ground surface (bgs). At other soil sampling locations around the building, but away from the dry well, chromium levels were significantly lower, with a maximum observed concentration of 1,680 mg/kg at the surface and 1,350 mg/kg at a depth of 20 feet.

Groundwater samples collected from the upper zone revealed a plume extending approximately 400 feet northwest (downgradient) from the dry well with chromium concentrations ranging between 142 and 689 milligrams per liter (mg/L). Samples from the deep aquifer revealed a plume 400 feet in length with chromium concentrations between 0.7 and 6.5 mg/L (Figure 3-4).

Surface water samples collected from nearby drainage ditches and locations downstream of United Chrome revealed chromium concentrations between 0.08 and 4.3 mg/L. Sediment samples showed chromium concentrations between 48 mg/kg and 27,900 mg/kg. Chromium was detected in the surface water (0.08 mg/L) and sediment sample (52 mg/kg) collected from the Booneville Slough location.

3.5.1 Public Health and Environmental Impacts

Although a baseline risk assessment was not conducted for the RI, laboratory testing revealed chromium concentrations in groundwater at levels approximately 10,000 times higher than the 0.05 mg/L drinking water standard. Surface water samples revealed

3-4 CVO/030480004

chromium concentrations approximately 400 times higher than the chronic freshwater ambient water quality criteria of 0.011 mg/L. Accordingly, the principal threat posed by site conditions was offsite chromium migration, ingestion of contaminated groundwater by residents living northeast of the site, and adsorption of chromium present in surface water and sediment by ecological receptors.

3.6 Feasibility Study

The FS developed an array of technologies to address soil and groundwater contamination at the site by screening commercially available technologies and assembling the technologies into 12 remedial action alternatives. The twelve alternatives were subjected to an initial screening that considered technical feasibility, environmental and public health impacts, and cost, to eliminate the least suitable alternatives and narrow the list of potential remedial actions for further detailed analysis. From the list of 12, seven alternatives were carried forward (Table 3-1) for more detailed evaluation. From this list, alternative 5 was initially proposed, but based on DEQ and community feedback, alternative 12 was selected.

CVO/030480004 3-5

TABLE 3-1Feasibility Study Alternatives Summary United Chrome Products, Corvallis, OR

No.	Description	Capital Cost	Annual O&M Cost	Present Worth Cost 1987	Implementation Time (1)
1	No Action	\$0	\$	\$0	Not Applicable
2	Alternative Water Supply	\$172,000	None	\$172,000	Not Applicable
3	Soil Excavation	\$599,000	None	\$599,000	1 yr.
4	Upper Zone Groundwater Extraction	\$929,000	\$168,000	\$1,745,000	7 yr.
5	Soil Flushing and Upper Zone Groundwater Extraction	\$1,063,000	\$168,000	\$1,699,000	5 yr.
6	Soil Excavation and Alternate Water Supply	NS.	NS	\$800,000	NS.
7	Deep Aquifer Groundwater Extraction	NS	NS	\$2,000,000	NS
8	Soil Excavation and Deep Aquifer Groundwater Extraction	- NS	NS	\$2,500,000	NS
9 9	Upper Zone Groundwater Extraction and alternate Water Supply	NS	NS	\$2,300,000	NS
10	Upper Zone and Deep Aquifer Groundwater Extraction	\$1,452,000	\$261,000	\$2,724,000	7 yr.
11	Soil Flushing, Upper Zone Groundwater Extraction and Alternate Water Supply	NS	NS	\$1,900,000	NS
12	Soit Flushing and Upper Zone and Deep Aquifer Groundwater Extraction	\$1,580,000	\$261,000	\$2,570,000	5 yr.


Notes:

Shaded cells indicate alternatives eliminated by initial screening.

CVO/030480004

⁽¹⁾ Implementation time from O&M cost estimate duration.

⁽²⁾ NS = not specified in FS.










FIGURE 3-2 SITE PLAN IN 1992 UNITED CHROME PRODUCTS SITE CORVALUS, OREGON











4. Remedial Actions

4. Remedial Actions

This chapter discusses implementation of the United Chrome remedy beginning with the description presented in the ROD and continuing through design, construction, and remedial action.

4.1 Remedy Selection

The ROD is the regulatory instrument EPA uses to select a remedy to address risk to human health and the environment posed by hazardous substances, such as the chromium-contaminated soil and groundwater present at the United Chrome Products site. The United Chrome ROD was signed on September 12, 1986, by the EPA Region 10 Regional Administrator.

4.1.1 ROD Amendments or Explanation of Significant Differences

No ROD amendments have been prepared to date. An Explanation of Significant Differences (ESD) was completed on December 17, 1991.

4.1.2 Remedial Action Objectives

Three primary public health and environmental objectives were developed (ROD, EPA 1986) for the United Chrome site:

- Adequately protect the public against contact with and ingestion of contaminated groundwater.
- Minimize threats from and adequately protect the environment against the spread of contaminated groundwater.
- Adequately protect the public against contact with and ingestion of contaminated soil and sediments.

The purpose for remedial action at the United Chrome site, as described in the ROD, was to:

"remove contamination from the confined zone (deep aquifer) and control further migration of contamination from the upper unconfined zone (upper zone)."

The ROD states further that:

"The cleanup criteria for the confined aquifer (deep aquifer) is 0.05 mg/L chromium, the drinking water standard, because this aquifer is considered a drinking water source and in direct hydraulic connection with the local drinking water supply wells. The cleanup criteria for the unconfined zone (upper zone) is 10 mg/L chromium. This concentration represents the minimum cleanup required to protect the local drinking water supply. The drinking water standard of 0.05 mg/L was not used because the unconfined zone (upper zone) is not used as a drinking water source anywhere in the area and because the present level of contamination would likely make it technologically or economically infeasible to achieve this standard."

CVO/030480004 4-1

4.1.3 Remedy Description

The major components of the selected remedy described in the ROD included:

- 1. Installation of approximately 15 shallow wells (15 to 20 feet) to extract chromium-contaminated groundwater from the upper (unconfined) zone.
- 2. Installation of approximately five deep wells (35 to 40 feet) to extract chromium-contaminated groundwater from the deep (confined) aquifer.
- Installation of onsite treatment equipment (chemical reduction and precipitation) to remove chromium contamination from extracted groundwater prior to discharge to Muddy Creek or the City of Corvallis wastewater treatment facility.
- 4. Construction of two percolation basins in the areas of the former dry well and plating tanks to flush the contaminated soil above the shallow groundwater table. Approximately 350 tons of contaminated soil excavated during the construction of these basins was to be disposed at a permitted land disposal facility.
- 5. Installation of culverts in the adjacent open drainage ditch to isolate the surface drainage system from the inflow of contaminated surface water and groundwater from the site.

4.2 Remedy Implementation

On September 8, 1987, EPA and DEQ entered into a State Superfund Contract to proceed with remedial design and construction. This agreement separated the work into two phases. Phase I included design and construction of all upper zone related facilities, while Phase II included the surface drainage and deep aquifer extraction facilities. The estimated costs (Interim Closeout Report, EPA, 1991) for the Phase I and Phase II work were \$2.4 million and \$2.0 million (total of \$4.4 million) versus \$2.57 million estimated in the ROD.

Largely as a result of information developed during remedial design, several changes were made to the remedy. Theses changes, described in the December 17, 1991, ESD (EPA 1991) included:

- Demolition of the United Chrome Products building. At the time of the ROD it was
 decided to postpone a decision on the building's status until the remedial design phase.
- Rerouting of the surface drainage ditch in lieu of culvert installation.
- Installation of an infiltration trench, injection wells, and eight additional upper zone and two additional deep aquifer extraction and monitor wells.
- Discharge of treated water to the City of Corvallis publicly owned treatment works (POTW) and increased reliance on the POTW as a final treatment facility for extracted groundwater from the site.
- Modification of the deep aquifer groundwater cleanup standard from 0.05 mg/L to 0.1 mg/L to be consistent with the National Primary Drinking Water Regulation or maximum contaminant level (MCL).

A brief summary of the Phase I and Phase II work is provided in the following subsections.

4-2 CVO/030480004

4.2.1 Phase I Design and Construction

Phase I design and remedial construction included the following:

 Decontamination and demolition of the vacant United Chrome Products building (Photograph 1). Decontamination water was collected and stored in a temporary storage tank for treatment in the onsite treatment system. Demolition debris was transported to Valley Landfill's Coffin Butte facility in Corvallis, Oregon.



Photograph 1 - Demolition of the United Chrome Products building.

- Excavation and disposal of highly contaminated soil from the former dry well and
 plating tank areas. Approximately 800 tons (400 cubic yards) of soil was removed and
 transported to the Chemical Waste Management facility in Arlington, Oregon.
- Installation of 23 extraction wells (versus the 15 proposed in the ROD) and associated
 conveyance piping and well controls (Photograph 2) to pump contaminated
 groundwater from the upper zone to the onsite pretreatment system. Six piezometers
 and six monitor wells (non-pumping extraction wells) were also installed to allow for
 monitoring of remedial action progress.
- Construction of extracted groundwater influent and effluent holding tanks, installation
 of a skid-mounted chemical reduction and precipitation pretreatment system
 (Photograph 3), and setup of an office/laboratory trailer for use by operations and
 maintenance (O&M) staff. The City of Corvallis later modified the treatment system to
 add two 6,000-gallon sludge thickening tanks.

CVO(030480064 4-3



Photograph 2- Typical upper zone groundwater extraction well and onsite treatment system. Black tanks used for influent (groundwater) storage and white tanks for effluent (treated groundwater) storage.



Photograph 3 – Chemical reduction and precipitation treatment tank with totes containing treatment chemicals.

4.4

The Phase I design and construction work was performed between March 1987 and August 15, 1988, by EPA's contractor CH2M HILL, with support from Reidel Environmental Systems (civil, electrical, and mechanical), Wastewater Treatment Systems (treatment tank), and Geotech Explorations (well installation).

4.2.2 Phase II Design and Construction

Phase II design and remedial construction included:

- Installation of seven (versus five proposed in the ROD) deep aquifer extraction wells (DW-2, DW-8, DW-12, DW-13, DW-14, DW-15 and DW-16) and associated conveyance piping and well controls.
- Installation of two injection wells (DW-9 and DW-10) and two monitor wells (DW-18 and DW-19).
- Reconstruction of well DW-3 (DW-3A) and replacement of upgradient wells DW-4 and DW-5 with a new well DW-11.
- Construction of the bypass ditch (Photograph 4) to reroute surface water drainage around the site.
- Construction of a chemical storage building to house onsite treatment system chemicals.



Photograph 4 – Surface drainage bypass ditch shown on left. Infiltration basins at right-center of photograph.

The Phase II design and construction work was performed between November 1989 and August 15, 1991, by EPA's contractor CH2M HILL, with support from Onwego Drilling (well installation), Green and White (bypass ditch), Trico Electric (electrical), and Beaver Plumbing (mechanical).

CVG/030480004

4.2.3 Supplemental Engineering and Institutional Controls

The primary engineering controls at United Chrome are a chain-link site boundary fence enclosed by a chain-link airport property fence recently installed by the Federal Aviation Administration. Access to the site is available through the double, locked gates placed along the access road.

The Consent Decree between EPA and the City of Corvallis required the City to establish an approximate 40-acre groundwater pumping exclusion zone around the site. The purpose for the exclusion zone is to prevent installation and operation of water supply wells that could adversely affect groundwater remediation.

4.3 System Description and Operations

This section summarizes general information related to operation of the groundwater extraction wells, infiltration basins, and trench and injection wells, and the onsite treatment system. A majority of this information relates to historical site operations. At the time of this five-year review, site activity is limited to operation of a single upper zone well (EW-9) and two deep aquifer wells (DW-8 and DW-9).

4.3.1 Groundwater Extraction Wells

Upper Zone Well Description

The upper zone extraction system (Figure 4-1) was initially comprised of 23 wells. Each well is 5 inches in diameter and approximately 20 feet deep. The wells are equipped with electric submersible pumps for groundwater extraction and high and low water level sensors to control pump operation (Figure 4-2). A control panel adjacent to the well enclosure contains an hour meter to record the amount of time the pump operates and a cycle counter to record the number of times the pump cycles on and off. The wellhead is housed in an insulated enclosure to provide weather protection. The extraction wells are manifolded together with above ground, high-density polyethylene (HDPE) piping to convey groundwater from the wells to the onsite treatment facility.

Upper Zone Operations

Following 14.4 years of operation, the upper zone extraction system has yielded 30.6 million gallons of groundwater. Monthly groundwater extraction rates have varied from zero (July to September 2002) to 593,740 gallons (16 gallons per minute). The monthly extraction rate has declined steadily since May 1991 (Figure 4-3) as individual wells have been turned off after reaching the 10 mg/L chromium ROD performance standard. Shutting wells down in an incremental manner made recharge available to other well locations, thereby accelerating the overall cleanup rate.

Deep Aquifer Well Description

The deep aquifer system was initially comprised of seven extraction wells. Each well is 5 inches in diameter and varies in depth between 40 and 75 feet. The wells are equipped with electric submersible pumps for groundwater withdrawal, flow meters to show instantaneous flow rates and record total flow volume, and flow control valves to regulate

4-6 CVO/030480004

flow rates. The wells are housed in insulated enclosures to provide weather protection. The extraction and monitor wells are manifolded together (Figure 4-4) with above ground, HDPE piping to convey groundwater to the discharge point located at the northeast corner of the onsite treatment plant. Because of the low chromium concentration present in deep aquifer groundwater, treatment is not required. The deep aquifer conveyance piping also contains a side lateral that enables all, or a portion of the flow to be diverted to the upper zone infiltration basins. This capability has never been used.

One other feature that distinguishes the deep aquifer extraction well design from the upper zone is placement of the pumps, which were set high in the well casing near the top of the well screen at depths between 25 and 35 feet. The rationale for this action was to focus groundwater withdrawals at the top of the deep aquifer where chromium concentrations are highest.

Deep Aquifer Operations

After 11.5 years of operation, the deep aquifer extraction system has yielded 48.1 million gallons of groundwater. Monthly groundwater extraction rates (Figure 4-3) have varied from 123,970 to 778,840 gallons (2.8 to 17.4 gallons per minute). Extraction rates were highest when all seven wells were in operation and have gradually declined as individual wells met the 0.1 mg/L ROD performance standard and were turned off. By February 1997, well DW-8 was the only extraction well still in operation. Well DW-9 was brought online in February 2001 when it was discovered that chromium concentrations at this well had risen above the ROD performance standard.

The extraction system has operated full-time since the August 1991 startup except for a temporary shutdown between October 2000 and January 1, 2001, during the upper zone source removal action (see Section 4.4).

4.3.2 Infiltration System

Several different technologies were used at the site to introduce tap water to the upper zone and deep aquifer to accelerate the overall remediation effort. In the upper zone, two infiltration basins and an injection trench were employed, and in the deep aquifer two injection wells were used as described in the following subsections.

Upper Zone - Infiltration Basin Description

To facilitate flushing of soluble chromium from upper zone soil to the extraction system for recovery and treatment, two infiltration basins were constructed. Basin 1, the larger of the two at 4,500 square feet (80×56 feet) was constructed over the site of the former plating tanks (Figure 4-1). Highly contaminated soil from this area was excavated to a depth of 8 feet and the excavation backfilled with concrete rubble and pea gravel, providing a "root system" to more effectively deliver flushing water to subsurface soil. Infiltration Basin 2, with an area of 2,000 square feet (50×40 feet), was constructed over the site of the former dry well. In addition to flushing soluble chromium from upper zone soil, the infiltration basins helped sustain upper zone pumping during the summer and fall months when there is no natural recharge.

CVO/030480004 4-7

The basin walls (Photograph 5) were constructed of 30-inch-high concrete curbing lined with geotextile. The curbing was glued to a concrete footing, resulting in a leak-proof construction. Tap water was pumped into the basins through a 2-inch spigot and the water level maintained by a float valve. The water level inside the basins was initially maintained at a height 2 feet above ground surface but was subsequently lowered to a ground surface level to reduce vertical gradients between the upper zone and deep aquifer.



Photograph 5 - Upper zone infiltration basin Number 1.

Upper Zone - Infiltration Trench Description

In September 1990, the City constructed a 100-foot-long infiltration trench northeast of Basin 1 (Figure 4-1) to provide supplemental recharge to this area of the upper zone. The trench was placed at a depth of 6 feet and constructed of 4-inch-diameter slotted polyvinyl chloride (PVC) drain pipe encompassed by pea gravel. Tap water was pumped to the trench through a 4-inch-diameter riser, and the water level maintained at ground surface elevation by a float valve. The trench was used primarily during the summer and early fall months and was shut down in November 1994 following cleanup of this area.

Upper Zone - Infiltration Basin and Trench Operations

Between August 1988 and September 2000, 17.2 million gallons of tap water was flushed through upper zone soil using the infiltration basins and trench. This amount is equivalent to 56 percent of all groundwater pumped from the upper zone. Of the 17.2 million gallons of injection water, 59 percent (10.2 million gallons) was delivered through Basin 1, 22 percent (3.8 million gallons) through Basin 2, and 19 percent (3.2 million gallons) through the infiltration trench.

During the early phases of upper zone remediation, when all 23 extraction wells were in operation, infiltration rates varied from a low of 105,300 gallons per month during the winter months to as much as 548,664 gallons during the summer. However, as individual

4-8 CVO/030460004

extraction wells were shut down, the monthly infiltration rate has gradually declined (Figure 4-3). The infiltration basins were decommissioned in September 2000 in conjunction with a soil removal action. An attempt to reuse the Basin 1 footprint in January 2001 was unsuccessful due to the low permeability of material used to backfill the excavation (see Section 4.4). The infiltration trench was also temporarily restarted in September 2001 but was turned off once it was determined that the recharge did not benefit extraction at well EW-9.

Deep Aquifer - Injection Well Description

Deep aquifer wells DW-9 and DW-10, which initially did not contain chromium concentrations above the 0.1 mg/L ROD performance standard, were configured as injection wells during the Phase II construction. The design objective for the injection wells was to inject enough water to maintain a neutral vertical hydraulic gradient between the upper zone and deep aquifer to prevent recontamination of deep aquifer groundwater by upper zone groundwater that had met the 10 mg/L ROD performance standard. Wells DW-9 and DW-10 were designed primarily as monitor wells, and as such, the wells experienced frequent clogging problems even though clean tap water was used. The deep aquifer injection system was shut down in February 1994.

Deep Aquifer - Injection Well Operations

Between August 1991 and February 1994, 5.5 million gallons of groundwater was injected into the deep aquifer through wells DW-9 and DW-10; an amount equivalent to 11 percent of all groundwater pumped from the deep aquifer. An attempt was made to maintain injection rates at approximately 5 gallons per minute (gpm). However, the injection rate had to be decreased during the winter months to prevent artesian conditions. Monthly deep aquifer injection rates are shown on Figure 4-3.

4.3.3 Groundwater Treatment System

The groundwater treatment system was purchased as a package unit from Wastewater Treatment Systems in 1988 and installed during the Phase I construction effort. A process flow diagram for the system is shown in Figure 4-5. In 1992, after several years of upper zone pumping, treatment system operations were scaled back to eliminate the precipitation (sludge forming) step. All pretreatment of extracted groundwater was discontinued on March 2, 1995, and the treatment system decommissioned between March and April 1999.

While the treatment system was in operation, chromium removal from the groundwater influent stream was performed as follows:

- Step 1. Groundwater stored in the influent holding tanks was pumped to the first reaction chamber where sulfuric acid (acidification) was added to lower the pH to approximately 2.5. Sodium metabisulfite was also added in the acidification chamber to reduce the hexavalent chromium (Cr+6) to trivalent chromium (Cr+3).
- Step 2. Water then flowed into a second chamber (neutralization) where sodium
 hydroxide was added to raise the pH to 8.5, resulting in the formation of chromium
 hydroxide particles.

CVO/030480004 4-9

- Step 3. From the neutralization chamber water flowed into a third chamber that housed
 the lamella clarifier. Prior to entering the clarifier, anionic polymer was added to help
 the smaller chromium hydroxide particles aggregate into larger settable floc. The floc
 settled to the bottom of the lamella where it was then pumped to a thickening tank. The
 treated effluent was pumped from the clarifier to a clear well and through a bag filter
 (effluent polishing) into the effluent holding tanks.
- Step 4. Sludge formed in the thickening tanks was then pumped to a filter press, resulting in the formation of a blue-colored dry solid (Photograph 6). The dry solid was placed in a drum and transferred to a roll-off box for shipment to the Chemical Waste Management facility in Arlington, Oregon. Water removed by the filter press was returned to the influent holding tanks.

After several months of operations, the City, in cooperation with EPA, identified several process modifications to improve the treatment system throughput rate. These modifications are summarized in Table 4-1.



Photograph 6 - Chromium hydroxide precipitate collected from the filter press.

System Operations

Through March 1992 the groundwater treatment system was operated in a batch mode. During this phase of operations, extracted groundwater was accumulated in the influent tanks (the effluent tanks were converted to influent tanks in February and July 1991). When the tanks were completely full (48,000 gallons) the operators would process the water through the plant at rates up to 75 gpm.

In July 1991, the City of Corvallis proposed a 10-pound-per-day discharge limit (local limit) for the United Chrome site in accordance with National Categorical Pretreatment Limits

4-10 CVC/030480004

(40 CFR Chapter I, Subchapter N Part 403). In January 1992, EPA approved a 7-pound per day discharge limit. Under the local limit operations phase, up to 7 pounds per day of partially treated groundwater (14,000 gallons of upper zone groundwater or 3.8 million gallons of deep aquifer groundwater) could be discharged to the City of Corvallis publicly owned treatment works (POTW) for treatment. In March 1992, the treatment plant was modified to allow for full or partial (hexavalent to trivalent chromium reduction step) treatment and the plant operated in this mode until March 1995. On March 2, 1995, the reduction step was discontinued and all groundwater discharged directly to the POTW for treatment.

The chromium concentration in upper zone groundwater processed through the treatment plant dropped steadily during the first several years of operation from 1923 mg/L in August 1988 to 59 mg/L in March 1992. Between March 1992 and March 1995, when the treatment plant was operated primarily in the reduction only mode, chromium concentrations declined from 59 mg/L to 17 mg/L (Figure 4-6). Between March 1995 and December 2002, when no onsite pretreatment was performed, chromium concentrations generally varied between 10 and 15 mg/L.

Deep aquifer groundwater was treated onsite between August 1991 and March 1992. However, due to low chromium concentrations and higher volumes, deep aquifer groundwater was the primary benefactor of the 7-pound-per-day local discharge limit, and in March 1992, all deep aquifer groundwater was discharged to the POTW for treatment. As shown in Figure 4-6, chromium concentrations in deep aquifer groundwater dropped steadily from 1.6 mg/L in November 1991 to 0.06 mg/L in July 1996. However, concentrations began to increase, rising to 0.6 mg/L in January 2001. In February 2001, following startup of extraction well DW-9, the concentration dropped abruptly to 0.15 mg/L. Chromium concentrations had risen steadily to 0.35 mg/L by December 2002 (see Figure 4-6).

4.3.4 Performance Monitoring Program

Groundwater extraction and treatment system performance monitoring is conducted in accordance with the requirements of a pumping plan. The pumping plan has been revised five times since 1988. As experience with operation of the groundwater extraction and treatment system has grown, monitoring frequencies have generally been reduced. Additionally, when performance monitoring has shown that an extraction or monitor well has achieved the ROD performance standard, the monitoring frequency has been reduced or eliminated altogether.

The current performance monitoring program (*Pumping Plan*, CH2M HILL, May 2001) is summarized in Table 4-2 and Table 4-3.

4.4 Responsible Party Lead Actions

The City of Corvallis has also undertaken several actions to accelerate and improve the overall cleanup effort. These actions have included:

 Construction of a 100-foot-long infiltration trench in 1990 to deliver additional recharge to the upper zone northeast of Basin 1 (Photograph 7).

CVO/030480004 4-11



Photograph 7 - Construction of upper zone infiltration trench in June 1990 by the City.

- Removal of two abandoned buildings in April 1990 and May 1991 (yellow and green buildings in Photograph 4).
- Removal of chromium-contaminated sediment from the onsite culvert in 1991
 (Photograph 8). The culvert was also plugged at each end to prevent recontamination.
 The sediment was eventually transported to the Chemical Waste Management facility in Arlington, Oregon.
- In March 1999 the City retained a Contractor to remove the chemical storage building, the influent and effluent storage tanks, treatment plant, filter press and treatment building.
- As resources permit, the City has also decommissioned a number of inactive extraction and monitor wells (Table 4-4).

Following an EPA investigation performed between June 1998 and July 2000 to verify the infiltration basin's soil flushing effectiveness, the City implemented a removal action that resulted in the excavation of 1,956 tons of soil containing chromium concentrations greater than 6,000 mg/kg. This material was transported to the Chemical Waste Management facility in Arlington, Oregon. Concrete rubble removed from the excavation was supplemented with 1700 tons of clean fill material, compacted, and leveled to match the existing grade.

4/12 CVC 030480004



Photograph 8 – Chromium-contaminated sediment removed from onsite culvert in September 1991. The City attempted to stabilize the sediment with concrete to permit disposal at Subtitle D (nonhazardous) landfill, but was unable to blend the concrete and sediment into a stable solid.

4.5 Operation and Maintenance Costs

O&M costs were estimated in the Feasibility Study at \$261,000 per year for a five-year period. Based on cost information obtained from the City of Corvallis, actual operation and maintenance costs for United Chrome have declined from \$247,000 per year in 1990 to \$25,000 per year in year 2001, with the lower costs in proportion to a reduced level of site activity. An additional, one-time cost of approximately \$400,000 was incurred in year 2000 in conjunction with the upper zone soil removal.

CVD/030480004 4-13

TABLE 4-1 Treatment System Improvements United Chrome Products Corvallis, OR

Date	Modification	Description
Process Equ	uipment	
July 1989	Filter Press	Original 6-cubic-foot press removed, replaced with new 12-cubic-foot press.
July 1989	Sludge Pump	Original Wilden M-4 sludge pump replaced with Wilden M-8 to increase capacity.
Oct. 1989	Filter Press	Filter press filtrate line replumbed from the sludge thickening tank to the clarifier.
Dec. 1989	Air Compressor	Original compressor removed, replaced with larger unit to accommodate the new press.
Dec. 1989	Air Drier	Regenerative air drier added to dry process air, address freezing problems with wet process air.
Aug. 1990	Sludge Thickening	Replaced two 900-gallon sludge thickening tanks with two 6,000-gallon tanks.
Ancillary Eq	uipment	
Jan. 1989	Polishing Filters	Damaged by freezing, removed from process.
April 1989	Influent Flow Measurement	Reduced meter size to provide more accurate measurement.
Dec. 1989	Caustic Storage	NaOH/KOH mixtures are now used during cold months to inhibit freezing of caustic solution.
May 1990	Influent/Effluent Tank Area	Added permanent ladders, catwalks, and rails over the tanks.
•		Installed analog level measurement on all four tanks.
Jan. 1991	Influent/Effluent Pumps	Changed from 1-1/2- to 2-hp pumps.
Feb. 1991	Influent/Effluent Tanks	Tank No. 3 replumbed to use for influent rather than effluent storage.
July 1991	Influent/Effluent Tanks	Tank No. 4 replumbed to use for influent rather than effluent storage. Treatment plant effluent discharged directly to the sewer.
Facilities		
May 1990	Chemical Storage Building	Building designed and constructed.
May 1990	Locker Room	Building designed and constructed.

4-14 CVO/030480004

TABLE 4-2 Upper Zone Remedial Action Monitoring and Reporting Schedule United Chrome Products, Corvallis, OR

Component	Task	Locations	Frequency	Reporting Requirements ^a
Extraction System	Water levels in select wells	EW-01, EW-02, EW-03, EW-04, EW-05, EW-06, EW-07, EW-09, EW-10, EW-11, EW-12, EW-13, EW-14, EW-15, EW-16, EW-23, EW-27, PZ-B, SE-2A, MW-3	Quarterly	Quarterly
	Wellhead measurements ^b	All active extraction wells	Monthly	Quarterly
	Water quality - hexavalent chromium	All active extraction wells	Monthly	Monthly
	Flow rate, line pressure, effluent chromium conc ^e	At City POTW discharge point	Monthly	Quarterly
	Calculated flow rate and corrected ^c volume through well ^f	All active extraction wells	Monthly	Quarterly
Monitor Wells	Water quality hexavalent chromium	EW-01, EW-02, EW-03, EW-04, EW-05, EW-06, EW-07, EW-09, EW-10, EW-11, EW-12, EW-13, EW-14, EW-15, EW-16, EW-23, EW-27, PZ-B, SE-2A, MW-3	Semiannually ^d	Semiannually
Infiltration Trench (Phase 2 only)	Flow (gal), water elevation and vertical gradients	Vertical Gradient Clusters: SE-2A/DW-9, MW-3/DW-2	Quarterly	Quarterly
	Water Balance ^g	EW-2, EW-6, EW-10, EW-11, EW-12, EW-13, EW-14, EW-16	Monthly	Quarterly

Notes:

^aAll results may be requested at any time by the technical assistant in verbal format or draft.

^bPump cycles, pump hours, line pressure. Functional inspections will be performed more frequently.

^cCorrected volume = [calculated volume at well]* total measured flow (POTW Discharge Point)

total calculated flow (all extraction wells).

^dSampling will be conducted in December and June of each year.

^eSample shall be a grab sample.

If difference between calculated vs. measured flow exceeds 20%: 1) Influent flow meter, 2) Extraction well line pressures, and 3) orifice plate erosion will be checked and appropriate corrective measures implemented.

Infiltration rates shall be adjusted, as necessary, to maintain an infiltration/extraction ratio of 0.6 to 0.7.

TABLE 4-3 Deep Aquifer Remedial Action Monitoring and Reporting Schedule United Chrome Products, Corvallis, OR

	Task	Locations	Frequency ^b	Reporting Requirement
Extraction System	Well head measurements/inspection ^a	Active extraction wells	Monthly	Monthly
	Water quality sampling			
Monitor Wells and Inactive Extraction Wells	Water level measurements	DW-2, DW-8, DW-9, DW-10, DW-12, DW-13, DW-15	Quarterly	Quarterly
	Water quality sampling [Cr(VI)]	DW-2, DW-10, DW-12, DW-13, DW-15	Semiannually	Semiannually


Notes:


^aMeasurements include flow rate (gpm) and flow totalizer (gallons). Functional inspection to be performed weekly. ^bScheduled tasks will be performed at uniformly spaced intervals; semiannual = March and September.

TABLE 4-4Well Abandonment History
United Chrome Products, Corvallis, OR

Abandonment	Date Performed	Wells Abandoned		
Event		Upper Zone	Deep Aquifer	
Phase 1	June 1996	EW-1, PL-2, PL-3,PL-4, PL-5, BG-2, MW-2A	DW-7	
Phase 2	May 1997	EW-19, EW-22, EW-24, EW-25, EW-26, SW-3, PZ-A, PZ-C, PZ-E		
Phase 3	May 1998	SW-2A, SW-4	DW-3A, DW-6, DW-19	
Phase 4	September 1990	EW-8, EW-28, EW-29		
Phase 5	June 2001	EW-17, EW-18, EW-21, EW-20, BG-1, MW-1, PL-1, PZ-D, PZ-F	DW-11, DW-14, DW-16, DW-17	


CVO/030480004 4-17





J. \DIS\INDUST\CV069108\FIG2-8.DWG

97.50 (2)



NOTE: PROBE SETTINGS SHOWN REPRESENT INITIAL CONDITIONS AND HAVE BEEN CHANGED TO OPTIMIZE WELL YIELDS.

FIGURE 4-2

UPPER ZONE


EXTRACTION WELL


INSTALLATION DETAIL


UNITED CHROME PRODUCTS SITE

CORVALLIS, OREGON









DW-15

OW- 16

DISCHARGE TO CITY SEWER

DEEP AQUIFER GROUNDWATER COLLECTION PIPE SYSTEM

LEGEND:

DW-80 DEEP AQUIFER EXTRACTION WELL

INFIL TRATION TRENCH

> BASIN NO. 1

BASIN NO. 2

●DW-11

DEEP AQUIFER MONITORING WELL

DEEP AQUIFER INJECTION WELL

■ DISCHARGE POINTS

FIGURE 4-4
DEEP AQUIFER GROUNDWATER
EXTRACTION AND MONITOR
WELL NETWORK

UNITED CHROME PRODUCTS SITE CORVALLIS, OREGON








FIGURE 4-5
GROUNDWATER TREATMENT SYSTEN
UNITED CHROME PRODUCTS SITE
CORVALUS, OREGON

СНМНІ.





5. Progress Since the Last Five-Year Review

5. Progress Since the Last Five-Year Review

The second five-year review (*United Chrome Products Superfund Site Corvallis, Oregon Five-Year Review* Report, EPA, 1998) concluded that the United Chrome remedy was performing as designed, that all necessary O&M was being performed, and that continued operations would ensure protection of human health and the environment. Although no current protectiveness issues were identified, several with the potential to affect the remedy's ability to achieve cleanup levels and, therefore, long-term protectiveness were listed. These issues included:

- 1. Determine the effectiveness of soil flushing for chromium removal from the plating tank and dry well areas.
- Delineate the extent of chromium-contaminated soil that continues to act as a groundwater contaminant source.
- Evaluate methods for enhancing the existing groundwater remedy, or undertaking an alternate remedy, in order to attain the groundwater performance standards specified in the ROD.
- 4. Reevaluate surface water and sediments in the drainage ditches downstream of the site and within the Booneville Slough to ensure protectiveness of ecological resources.
- 5. Prior to closeout of the site and proposed deletion of the site from the NPL, review the levels of chromium remaining in soil on the site to ensure that any residual levels of contamination are protective of expected future site use.

Each of these recommendations (Table 5-1), except for the surface drainage sampling, has been addressed. The surface drainage sampling work had been completed at the time of this five-year review but the results had not been presented to EPA. Additional information relevant to these issues is provided in Chapter 7.

CVO/030480004 5-1

TABLE 5-1Status of Recommendations Provided in Second (1998) Five-Year Review *United Chrome Products, Corvallis, OR*

Issues from Previous Review	Recommendation	Party Responsible	Action Taken and Outcome	Action Completed
Ongoing upper zone groundwater contaminant source	Evaluate effectiveness of soil flushing	EPA	Phase I soil investigation performed, resulting in collection of 220 soil samples for total chromium, TCLP, and SPLP chromium analysis. Investigation revealed that high levels of chromium remain in soil. Phase 2 investigation recommended.	October 1998
	Delineate extent of chromium- contaminated soil	EPA	Phase II soil investigation performed, resulting in collection of 72 soil samples for total chromium analysis. Extent of contamination delineated to 6,000 mg/kg level obtained from Phase 1 TCLP testing.	August 2000
	Evaluate alternate methods for remedy	EPA	Removal action recommended. Design Criteria Report prepared to guide removal action.	August 2000
	enhancement	City of Corvallis	Removed 1,926 tons of contaminated soil with chromium concentrations in excess of 6,000 mg/kg. Work documented in a construction report prepared by the City and in an EPA closeout report.	October 2000
Offsite chromium- contaminated surface water and sediment	Reevaluate surface water drainages and Booneville Slough to ensure protectiveness	Oregon DEQ	Oregon DEQ evaluated historical surface water and sediment data and concluded that a DEQ Ecological Level I Risk Scoping and Level It Risk Screening should be performed. DEQ recommended surface water and sediment sample locations and laboratory analysis requirements.	July 2002
		City of Corvallis	Sediment samples collected	Oct 2002
			Ecological Level 1 Scoping Report	Nov 2002
			Surface water samples collected	Jan 2003
			Additional background sediment samples collected	Feb 2003
Chromium concentrations remaining in onsite soil	Screening level risk assessment	DEQ	DEQ performed a human health risk screening that concluded offsite soil is protective of residential use and onsite soil protective for industrial use with institutional controls.	August 2002

5-2

6. Five-Year Review Process

6. Five-Year Review Process

This chapter describes activities associated with completion of the five-year review.

6.1 Administrative Components

The approach used to conduct the five-year review followed the *Work Plan for Work Assignment No. 102-FR-FE-1032* (CH2M HILL, October 30, 2002). Specific work plan tasks included:

- Review of applicable or relevant and appropriate requirements (ARARs) (Task 3)
- Site interviews (Task 4)
- Site inspection (Task 5)
- Preparation and review of the five-year review report (Task 6)

The overall five-year review effort was led by the EPA Region 10 remedial project manager (RPM), Alan Goodman. Mr. Goodman was assisted by the EPA community involvement coordinator (CIC), Ms. Deborah Neal, and by EPA Region 10's Remedial Action Contract (RAC) contractor CH2M HILL. The five-year review work was performed between December 1, 2002, and February 24, 2003.

6.2 Community Involvement

Community involvement is an important component of the five-year review process. Steps taken to involve the community in this five-year review included preparation and distribution of an updated fact sheet by EPA providing specific information on the five-year review and its objectives, interviews with community leaders, and interviews with private citizens who may have a potential interest in the cleanup.

6.3 Review of Applicable or Relevant and Appropriate Requirements

The remedy selected in the ROD is intended to protect human health and the environment and to comply with ARARs. The objective for the ARARs review was to identify any newly promulgated federal or state regulatory standards that might affect the protectiveness of the remedy. Although ARARs are "frozen" at the time of ROD signature, EPA's Comprehensive Five-Year Review Guidance (EPA 2001) specifies that newly promulgated or revised regulatory standards that bear on the protectiveness of the remedy be identified and evaluated during the five-year review.

Summaries of newly promulgated and revised regulatory standards identified during the course of the five-year review are discussed in Chapter 7.

CVO/030480004 6-1

6.4 Document and Data Review

Although no formal document and data review was performed, CH2M HILL has an extensive file for the United Chrome project. Information contained in this file was used to prepare the five-year review report.

6.5 Site Inspection

Summary of Site Conditions

The site inspection was performed by the CH2M HILL site manager on December 5, 2002, and January 11, 2003, in accordance with the checklist contained in the five-year review guidance. The site inspection was also used to update the site's base map to reflect changes that have taken place over the past 10 years. A copy of the revised base map is shown in Figure 6-1.

Two security fences (Photograph 10) enclose the United Chrome site, with access obtained through gates located off Airport Place. The outer fence, maintained by the Federal Aviation Administration, encloses the Corvallis Airport and is labeled with no trespassing and warning signs approximately every 100 feet along its entire length. The inner fence encloses the United Chrome and CoEnergy sites (Figure 6-1), which lie within the Corvallis Airport property. A third fence separates the United Chrome and CoEnergy sites from one another, and separate locking gates control entry and egress from each. CoEnergy also uses two guard dogs to patrol their facility.



Photograph 10 - FAA security fence outside United Chrome site fence.

6-2 CVO 030482004

Although the City maintains the groundwater extraction equipment in good working order, the site receives only a nominal amount of landscaping maintenance, and therefore appears unkempt. Herbicide applied in October 2002 has killed much of the groundcover vegetation present at the site, and its decayed nature contributes to the site's lowly appearance. Additionally, following removal of the treatment system infrastructure, the City no longer has a covered area to store equipment associated with past well conversion and well abandonment work. This equipment has replacement and salvage value, and is currently stored on an asphalt surface near wells EW7 and EW10, and the decontamination pad.

Land use in the immediate vicinity of the site remains airport services (maintenance and parking), propane fueling (Ferril Gas and CoEnergy), and agricultural (grass seed farming). The United Chrome site is zoned under the City of Corvallis Comprehensive Land Use Plan as general industrial.

6.5.2 Site Cover

Although not widely discussed in prior documents, large areas of the site are covered with asphalt and concrete (Photograph 11). The main portion of the site is overlain with reinforced concrete approximately 25,000 square feet in area and 12 inches thick. This cover represents the floor of the former United Chrome Products building. An extensive floor trench system varying in depth from 4 to 12 inches is recessed within the floor. The trench is filled with gravel but appears to drain toward the southwest corner. The gravel was removed at one location and the trench inspected. The concrete floor and walls of the trench were in good condition and showed no evidence of chemical or physical degradation. There are also several drain openings in the floor, just south of the power transformer, that most likely discharge to an inactive septic system. An asphalt roadway (former County road) and parking area border the concrete to the north. Along the west, south, and east sides of the concrete, the surface is unpaved.

EPA and the DEQ have expressed concerns in the past about potential chromium contamination beneath the concrete slab. The results of this site inspection, and soil sampling performed in May 2000 indicate these concerns are probably not warranted. Additional information on this issue is presented in Chapter 7.

6.5.3 Groundwater Remedy

Groundwater Extraction System

The only extraction wells still in operation are upper zone well EW-9 and deep aquifer wells DW-8 and DW-9 (Photographs 12a and 12b). All other extraction wells have been converted to monitor wells, or have met the ROD performance standard and been abandoned per EPA approval. The status of all wells present at the start of the remedial action in 1988 is shown in Table 6-1. Wells still present at the site are shown on Figure 6-1. At the time of the inspection, wells EW-9, DW-8, and DW-9 were operating satisfactorily.

Insulated shelters enclose the upper zone and deep aquifer extraction wells. The shelters are in good condition and provide adequate weather protection. Although some evidence that the shelters have been used recently as nesting sites by birds or small animals was observed, this has been a recurring condition, and does not affect extraction well operation or groundwater monitoring activities.

CVO/030480004 6-3



Photograph 11 - Concrete cover and floor of former United Chrome Products building.



Photograph 12a - Upper zone extraction well EW-9.

5-4 CVO/036480004



Photograph 12b - Deep aquifer extraction well DW-8.

The above ground piping that conveys groundwater from extraction wells EW-9, DW-8, and DW-9 to the discharge point is in good shape. However, the bridge near wells EW-5 and DW-1 (Photograph 13), which allows vehicles to drive safely over the pipe, is in poor condition and should be repaired if future vehicle traffic through this area is required. The bridge was damaged by heavy truck traffic during the October 2000 upper zone source removal project.



Photograph 13 - HDPE aboveground pipe bridge near DW-1.

CVD.030480004

TABLE 6-1 United Chrome Well Inventory - January 2003 United Chrome Products, Corvallis, OR

		r Zone Wells				
	Extraction Wells			Monitor Wells		
nactive	Abandoned	Active	Inactive	Abandoned		
	EW-08	EW-01	EW-20	MW2A		
	EW-19	EW-02	***	EW1(a)		
	EW-22	EW-03		PZ-A		
•	EW-24	EW-04		PZ-C		
	EW-25	EW-05		PZ-E		
	EW-26	EW-06		PL5		
	EW-28	EW-07		PL3		
	EW-29	EW-10		PL4		
	EW-17	EW-11		SW-3		
	EW-18	EW-12		SW-4		
	EW-21	EW-13		MW 1		
		EW-14		мWз		
		EW-15		PZ-F		
		EW-16		PL1		
		EW-23		PL2		
		EW-27	•	SW-2A		
		MW-3		BG1		
		PZ-B		PZ-D		
		SE-2A		PZ-F		
/ells Initia	ally Present	51				
/ells Curr	ently Present	21				
	·					
		Aquifer Wells		·····		
tion Well			Monitor Well	5		
nactive	Abandoned		Inactive	Abandonec		
		DW-2	DW-1	DW-03A		
		DW-10		DW-4		
		DW-12		DW-5		
				D44-2		
		DW-13		DW-6		
		DW-13		DW-6		
		DW-13		DW-6 DW-7		
		DW-13		DW-6 DW-7 DW-11		
		DW-13		DW-6 DW-7 DW-11 DW-14		
		DW-13		DW-6 DW-7 DW-11 DW-14 DW-16		
	/ells Curr	EW-25 EW-26 EW-28 EW-29 EW-17 EW-18 EW-21	EW-25 EW-05 EW-26 EW-06 EW-28 EW-07 EW-29 EW-10 EW-17 EW-11 EW-18 EW-12 EW-13 EW-13 EW-14 EW-15 EW-16 EW-23 EW-27 MW-3 PZ-B SE-2A /ells Initially Present 51 /ells Currently Present 21 Deep Aquifer Wells ction Wells mactive Abandoned Active	EW-25 EW-06 EW-26 EW-06 EW-28 EW-07 EW-29 EW-10 EW-17 EW-11 EW-18 EW-12 EW-13 EW-14 EW-15 EW-16 EW-23 EW-27 MW-3 PZ-B SE-2A /ells Initially Present 51 /ells Currently Present 21 Deep Aquifer Wells mactive Abandoned Active Inactive		

6-6 CVO/030480004

Infiltration System

The infiltration basins (Basin 1 and Basin 2) were decommissioned in August 2000 in conjunction with the upper zone source removal work (Photograph 14). The decommissioning effort included removal of geotextile material, above-grade concrete walls, plumbing and valve controls. The infiltration trench is still operational but has not been used since January 1993, except for a short trial between August and October 2001. Given the limited nature of current upper zone pumping operations, it is unlikely the trench will be required in the future.



Photograph 14 - Footprint of former infiltration basin number 2.

Groundwater Monitoring Network

All of the groundwater monitor wells/piezometers shown on Figure 6-1 were located and appear to be in satisfactory condition for continued use as required by the Pumping Plan – Version 5 (CH2M HILL, May 2001). CH2M HILL had scheduled the site inspection for December 5, 2002, to correspond with the City's semiannual sampling of the upper zone monitor wells. Unfortunately, the City's sampling pump failed to operate as a result of freeze damage, and the sampling was not performed on this date.

Treatment System

The groundwater treatment system was removed between March and April 1999. The only components remaining are the secondary containment wall that enclosed the influent tank storage and treatment system areas, the partially enclosed shop, the electrical control panel, the decontamination pad, and the containment cell for the sludge thickening tanks. The secondary containment wall has been intentionally breached (Photograph 15) along the north side to prevent accumulation of large amounts of rainwater. The metered discharge point where extracted groundwater is discharged to the sanitary sewer is in satisfactory condition (Photograph 16).

CVO-030480004 6-7



Photograph 15 – Breach of secondary containment wall at site of former wastewater treatment system.



Photograph 16 - Upper zone and deep aquifer extracted groundwater discharge point.

Office and Laboratory Trailer

An office and laboratory trailer and locker room trailer, constructed as part of the groundwater remedial construction effort, are still maintained by the City of Corvallis (Photograph 17). All onsite testing is done in the laboratory trailer, but most document/data management is performed at the City of Corvallis POTW. The laboratory equipment appeared to be in good working condition, and the City provides copies of all calibration and quality assurance checks with the quarterly progress reports. Copies of the O&M manuals, health and safety plan, and historical site-related documents are also kept onsite. The O&M manual has not been updated since the treatment system was decommissioned in April 1999. However, to support an update to the site Health and Safety Plan, the City prepared a summary of significant site events (see Attachment 4 in Appendix A).



Photograph 17 - Office and laboratory trailer.

6.5.4 Onsite Drainage

Although the surface drainage ditch has been re-routed around the United Chrome site, portions of the former ditch are still visible and accumulate surface water during the winter months (Photograph 18).

6.5.5 Site Safety

United Chrome O&M personnel are 40-hour trained, in accordance with 40 CFR 1910.120, and are current with respect to 8-hour refresher training and annual medical examinations. Because of the limited nature of current site operations, a facility safety inspection was not performed.

CVO 030480004 6-9



Photograph 18 – Isolated portion of former site drainage ditch near United Chrome site.

6.6 Community Interviews

CH2M HILL personnel interviewed site operations and maintenance (O&M) personnel, selected community leaders, and local residents who live within 1.5 miles of the United Chrome site. CH2M HILL also mailed questionnaires to non-governmental and non-media affiliated individuals on the United Chrome mailing list. A brief summary of the interview findings is provided in the following subsections. Copies of the interview questionnaires are provided in Appendix A, Attachment 3.

6.6.1 Site Operations Personnel

CH2M HILL interviewed Bruce Curtis, the City of Corvallis Public Works employee responsible for site operations and maintenance. Mr. Curtis has had this responsibility since the cleanup work was initiated in August 1988, and worked full time at the site through 1995. With the reduced level of operations over the past several years, Mr. Curtis now spends between 4 and 8 hours per week at the site.

Mr. Curtis believes the cleanup effort has been very successful. As a result of his day-to-day experience, he has observed many changes at the site, most notably elimination of chromium discharge to surface water and overall improvements in groundwater quality. Mr. Curtis did not report any problems with the cleanup that would compromise its overall protectiveness.

6.6.2 Community Organizations

CH2M HILL conducted personal and telephone interviews with three community representatives as follows:

6-10 CVON30480004

- Corvallis Benton County Economic Development Council (Doug Sweetland –
 Manager). This organization was selected for an interview because it has expressed the
 greatest interest in the site in conjunction with its efforts to develop the property
 surrounding the airport. Doug Sweetland is the current manager and has been so since
 1995. Mr. Sweetland praised the overall cleanup effort and believes the City of Corvallis
 has done a good job of performing the work. He did not identify any community
 concerns and feels well informed on cleanup progress.
- City of Corvallis Municipal Airport (Buck Taylor Manager). The United Chrome site lies within the City of Corvallis Municipal Airport property. Accordingly, this organization was interviewed because it will oversee future development of the site. Buck Taylor is the current manager and has been so since 1998. Mr. Taylor believes the cleanup has been very successful and offered as evidence the lack of concern expressed by Ferril Gas and CoEnergy, who lease property adjacent to the site. Mr. Taylor indicated that the Airport Master Plan designates the United Chrome site as the location of a future fuel farm. According to Mr. Taylor, Ferril Gas, a commercial propane distributor, will most likely relocate onto the United Chrome site when the cleanup is complete.
- Benton County Health Department Environmental Health Division (Bill Emminger –
 Deputy Administrator). This organization, which has responsibility for public drinking
 water protection in the rural areas of Benton County, was interviewed to determine if
 any concerns or inquiries about the United Chrome cleanup had been received. Mr.
 Emminger, who has been the Deputy Administrator for the past 8 months, was not
 familiar with United Chrome and returned CH2M HILL's telephone call after consulting
 with his staff. Although they still have a file on United Chrome, Mr. Emminger said
 there were no outstanding issues relevant to the cleanup.

6.6.3 Mailed Questionnaires


CH2M HILL obtained a copy of the most recent mailing list from the City of Corvallis and mailed questionnaires to individuals on the list with no governmental or media affiliation. Seven questionnaires accompanied by a transmittal letter and the November 2002 United Chrome Superfund Fact Sheet were mailed on December 6, 2002 (see Appendix A, Attachment 3). Over a 30-day period, two of the questionnaires were returned as undeliverable, and no response was received for the other five. The telephone directory showed current listings for only three of the seven people on the mailing list, all with the same address used to mail the questionnaires. No attempt was made to telephone these individuals.


6.6.4 Local Residents

Four local residents, who live approximately 1.5 miles northeast of the site, were also interviewed. Three of the four residents, who were interviewed in person, were selected at random to provide geographic coverage for this area. The fourth individual, who works at CH2M HILL, was interviewed over the telephone. Although the residents had heard of United Chrome through historical newspaper coverage, none were familiar with the current situation and did not have a favorable or unfavorable opinion on the cleanup effort.

CVO/030480004 6-11

6-12 CVO/030480004





7. Technical Assessment

7. Technical Assessment

This chapter presents a technical assessment of the remedy performance as implemented at the United Chrome Products site. This assessment was prepared to answer the following questions:

- Is the remedy functioning as intended by the decision documents?
- Are the exposure assumptions, toxicity data, cleanup levels and remedial action objectives used at the time of remedy selection still valid?
- Has any other information come to light that could call into question the protectiveness of the remedy?

Information used to answer the above questions is discussed in the following sections.

7.1 Is the Remedy Functioning as Intended?

As EPA's design engineer, construction manager, and oversight contractor for the United Chrome Products remedial action, CH2M HILL has developed a comprehensive understanding of site conditions, facility operations and overall cleanup progress. Most of this knowledge has been acquired through 15 years of observing the remedial action and reviewing monthly, quarterly and annual performance monitoring data published by the City of Corvallis.

As described in the ROD, the primary objective for the remedial action was: "to remove contamination from the confined zone (deep aquifer) and to control further migration of contamination from the upper unconfined zone (upper zone)." The ROD also defined a cleanup level of 10 mg/L chromium for upper zone groundwater and 0.05 mg/L chromium for deep aquifer groundwater. As described in Section 7.2, the deep aquifer ROD performance standard was changed to 0.1 mg/L in 1992 to align with the new EPA drinking water MCL.

7.1.1 Remedial Action Performance

Control of Upper Zone Contaminant Migration

Control of contaminant migration in upper zone groundwater has been achieved through operation of 23 groundwater extraction wells. This system, which through December 2002 had removed 30.5 million gallons of groundwater containing 31,882 pounds of chromium, has resulted in a significant reduction in the magnitude and size of the chromium plume. Average chromium concentrations in upper zone groundwater decreased from 1923 mg/L in 1988 to 15 mg/L in 2002. The size of the chromium plume, as defined by the 10 mg/L upper zone groundwater ROD performance standard, has decreased from 70,000 square feet to 2,500 square feet (Figure 7-1).

CVO/030480004 7-1

Upper Zone Groundwater Cleanup Progress

Groundwater cleanup progress with respect to the 10 mg/L ROD performance standard has generally been good, although the rate of cleanup has been slower than the five year timeline suggested in the ROD. Cleanup levels have been achieved at all locations except wells EW-5 and EW-9, where chromium concentrations of 12 mg/L and 15 mg/L were observed in December 2002. As shown in Figure 7-2a, chromium concentrations at EW-5 have remained at or slightly above 10 mg/L since November 1999. At well EW-9, chromium concentrations have remained above 10 mg/L since April 2002.

Containment of the Upper Zone Plume

To confirm containment of the upper zone plume, chromium concentrations were initially tracked at wells EW-17, EW-18, EW-21 and EW-23 located along the plume's northeast (downgradient) boundary. As shown in Figure 7-1 the plume boundary has contracted significantly since 1988. Therefore, wells EW-17 and EW-18 were replaced by EW-10, EW-13, EW-14 and EW-15, which are located further upgradient (southwest).

As shown on Figure 7-2b, chromium concentrations in the first set of boundary wells have remained below the 10 mg/L ROD performance standard for the past 12 years. Based on these results, wells EW-17 and EW-18 were abandoned in 2001. The current boundary well group shows that chromium concentrations have remained below the 10 mg/L ROD performance standard at each location since 1998, except for well EW-15, where chromium concentrations temporarily rose above the 10 mg/L ROD performance standard between June 2001 and August 2002. This increase most likely resulted from the August and October 2001 infiltration trench trial.

Contaminant Removal from the Deep Aquifer

Contaminant removal from the deep aquifer has been achieved through operation of a seven well groundwater extraction system. Through December 2002, this system has removed 48.1 million gallons of groundwater containing 122.5 pounds of chromium.

The reduction in contaminant mass is reflected in the reduced size of the plume (Figure 7-3) and the overall decline in the average groundwater concentration from 1.9 mg/L in August 1991 to 0.35 mg/L in December 2002.

Deep Aquifer Cleanup Progress

Groundwater cleanup progress with respect to the 0.1 mg/L ROD performance standard was initially very good. Following the August 1991 startup, chromium concentrations declined fairly rapidly at all locations except for DW-8 (Figure 7-5). At DW-8, the chromium concentration declined steadily from 0.72 mg/L in July 1993 to 0.1 mg/L in December 1996. However, beginning in January 1997, chromium concentrations began to increase, rising to 0.28 mg/L by August 1998. Chromium concentrations remained stable between August 1998 and June 1999, but began to rise again reaching 0.61 mg/L in January 2001.

In February 2001 pumping at well DW-9 was initiated. This action was taken to intercept contaminated pore water believed to be seeping from the upper aquitard between DW-8 and DW-9 resulting in recontamination of DW-8. Routine monitoring of DW-9 has revealed

7-2 CVO/030480004

increasing chromium concentrations, which have risen from 0.13 mg/L to as high as 0.47 mg/L. Additional information on this issue is provided in Section 7.4.

7.1.2 System Operations

Site operation, maintenance and monitoring requirements are prescribed in the *Scope of Work* (CH2M HILL, 1995) and *Pumping Plan* (CH2M HILL, 2001) included as attachments to the Consent Decree. The procedures given in these documents were designed to provide City personnel with the information necessary to assure the remedial action's effectiveness. The overall scope of the monitoring program has been revised on five occasions to reflect changes in site operations. The most recent revision to the Scope of Work was completed in 1995. The Pumping Plan was last revised in 2001.

Compliance with the procedures specified in these documents is assessed through quarterly meetings at the site and through review of monthly, quarterly and annual progress reports prepared by the City. Monitoring activities currently performed at the site are listed in Tables 4-2 and 4-3.

Cost of System Operations

Exclusive of the costs associated with the upper zone soil removal, monthly O&M costs have varied between \$25,141 and \$34,809 per year over the past five years. These costs are not expected to decline further, and may rise towards the upper end of this range once the performance monitoring programs shifts into the compliance phase.

To assess overall O&M cost with respect to mass of chromium recovered, historical O&M cost information for the 1988 to 2001 timeframe was compiled and compared to the mass of chromium recovered each year. All O&M costs, including those provided in the feasibility study, were converted to year 2001 dollars. These comparisons (Table 7-1) show that although the O&M timeframe has been significantly longer than the five-year timeline estimated in the feasibility study, total O&M costs of \$2.67 million are approximately 10 percent lower than the \$3.07 million estimate provided in the feasibility study. Annual O&M costs per pound of chromium recovered, in year 2001 dollars, varied from a low of \$18 in 2000, when the upper zone soil removal work was performed, to a high of \$515 in 2001, when only 49 pounds of chromium was recovered at an O&M cost of \$25,141.

7.1.3 Implementation of Institutional Controls and Other Measures

Institutional controls were instituted at the site in 1989 and have continued to date. These controls include securing the site with a 6-foot chain link fence and locking security gate to prevent unauthorized access to the site. Additional fencing recently installed by the FAA, which encloses the entire airport complex, provides additional security to guard against unauthorized entry. In accordance with the consent decree, in 1992 the City placed a deed restriction on the United Chrome property, which is owned by the City, to restrict groundwater use and well pumping (see Appendix D). The deed restriction runs with the land. The groundwater use restriction easement areal extent includes all upper zone and deep aquifer groundwater which exceeds the chromium drinking water MCL.

CVO/030480004 7-3

TABLE 7-1 Comparison of Annual O&M Costs United Chrome Products, Corvallis, OR

Year 			Actual Cost (\$)					Cost per Pound of Chromium Removed
	FS Cost (\$) ¹		Costs Estimated by CH2M HILL ²		Costs Reported by the City of Corvallis ^{3,4}		Pounds of Chromium Removed	
	1985	2001 ⁵	Annual	2001 ⁵	Annual	2001 ⁵	•	
1985	261,000		<u> </u>					
1988	118,968	214,331	92,580	158,343			3501	\$45
1989	317,247	569,730	246,880	422,249			9875	\$43
1990	333,109	569,730	246,880	422,249			10,940	\$39
1991	349,765	569,730	246,880	402,142			3579	\$112
1992	367,253	569,730	246,880	382,992			1868	\$205
1993	385,616	569,730			100,985	149,201	677	\$220
1994					46,948	66,061	434	\$152
1995					49,292	66,056	324	\$204
1996					25,000	31,907	206	\$155
1997					26,084	31,706	170	\$187
1998					34,809	40,296	140	\$287
1999					25,507	28,121	121	\$232
2000					424,124	445,330	24,618	\$18
2001					25,141	25,141	49	\$515
Total (2001		\$3,072,983				\$2,671,792	56,542 lbs.	
Average								\$172

References:

7.1.4 Opportunities for Optimization

Optimization has been a constant focus for EPA and the City operations staff. The City has pursued measures that have permitted greater control over operation costs. Treatment system modifications (Table 4-1) increased the throughput rate allowing more groundwater to be treated in less time, thereby reducing the number of labor hours per gallon of groundwater treated. Development of the 7-pound-per-day local limit, and installation of a

7-4 CVO/030480004

¹ BOD EPA 1986

^{2.} Performance Evaluation for Upper Zone Operations 1989 to 1991, CH2M HILL, 1991.

^{3.} United Chrome Process Modification Request, City of Corvallis, 1994.

^{4.} Personal communication, CH2M HILL, 2002.

^{5.} Year 2001 cost assumes 5% interest rate.

man-down alarm, allowed the City to staff the site with one person further reducing operation costs. These savings are evident by reduced O&M costs, which declined from an estimated \$247,000 in 1989 to \$25,000 in 2001.

Although EPA has also supported cost saving optimization efforts, most notably those available through reduced monitoring frequencies, EPA's primary focus has been to find opportunities for accelerating and achieving a more thorough cleanup effort. The EPA sponsored upper zone source investigation was the most important of these efforts. This action, which resulted in the excavation of 1956 tons of contaminated soil, is believed to have removed 24,540 pounds¹ of sparingly soluble chromium. Based on the chromium recovery rate of 75 pounds per year observed between January and December 2000, it would have taken over 300 years to recover this amount of chromium from the upper zone groundwater extraction system.

7.1.5 Indicators of Potential Remedy Problems

Upper Zone

In June 1998, following several years with no measurable decline in upper zone and deep aquifer chromium concentrations, EPA conducted an investigation to assess the effectiveness of soil flushing operations. This investigation revealed the presence of solid phase chromium at concentrations up to 23,200 mg/Kg in upper zone soil despite 12 years of infiltration basin flushing. Toxicity characteristic leaching procedure (TCLP) and synthetic precipitation leaching procedure (SPLP) testing indicated that if soil containing chromium concentrations greater than 6,000 mg/Kg were removed the upper zone groundwater ROD performance standard of 10 mg/L could be achieved. Based on the findings of this investigation, in October 2000 the City excavated 1,956 tons of soil from the upper zone adjacent to and underlying the former dry well and plating tank sites.

Despite the excavation effort, chromium concentrations at two wells EW-5 and EW-9 continue to hover at or slightly above the 10 mg/L upper zone ROD performance standard. Initially it was believed that small amounts of dissolved phase chromium remained in the area between the excavation boundaries and the well, and this contamination would eventually be flushed out with continued pumping. While pumping at EW-9 continues, it's possible that small pockets of contaminated soil (Figure 7-4) present in the vicinity of soil borings PT-18 (5810 mg/Kg) and PT-25 (5700 mg/Kg), with chromium concentrations slightly below the 6000 mg/Kg upper zone groundwater protective level, may be inhibiting attainment of the groundwater cleanup standard at these two well locations.

Deep Aquifer

In the deep aquifer, the cleanup standard has been achieved at all wells except DW-8 and DW-9. After approaching the 0.1 mg/L ROD performance standard in January 1997, chromium concentrations at these two wells have trended up (see Figure 7-5) and are currently at 0.24 mg/L and 0.44 mg/L respectively. This trend coupled with laboratory analysis of samples collected in 1991 indicates that chromium contaminated pore water is draining from the upper aquitard into the deep aquifer. Current information indicates that approximately 0.5 pounds of chromium are discharged from the upper aquitard and

CVO/030480004 7-5

¹ Pounds of chromium = 1956 tons * 2000 lbs/ton * 1 kg/2.2 lbs * 6265 mg chromium/Kg * 1 lb/454,000 mg = 24,540 lbs.

recovered by deep aquifer pumping each month. The estimated concentration of the pore water after mixing with deep aquifer groundwater is 3.2 mg/L. This estimate, obtained from Figure 4-5 of the *Deep Aquifer Performance Evaluation Report* (CH2M HILL 1995), is similar to recent depth discrete groundwater sampling results collected by the City from wells DW-8 and DW-9 which revealed chromium concentrations of 2.3 and 1.2 mg/L in samples collected at depths corresponding to the boundary between the upper aquitard and deep aquifer.

7.2 Have the Assumptions on Which the Remedy was Based Changed?

7.2.1 Changes in Standards and to be Considered

Federal regulations identified in the ROD included the Safe Drinking Water Act (SDWA), the Resource Conservation and Recovery Act (RCRA), and the Clean Water Act (CWA). State of Oregon guidelines referenced in the ROD included the Oregon Groundwater Quality Protection policy.

The SDWA has been revised on several occasions since 1986 to incorporate changes associated with regulation of additional contaminants, and to incorporate new information developed from toxicity studies. In 1991 the drinking water MCL for chromium was revised upward from 0.05 mg/L to 0.1 mg/L. The basis for this change is not known, but it may have been related to studies showing that hexavalent chromium has a reduced toxicity through the ingestion pathway. This change does not have a measurable effect on the protectiveness of the deep aquifer cleanup.

The primary changes in RCRA that have occurred since the ROD, that have affected removal actions at the site, were the land disposal restrictions which require treatment of chromium contaminated soil excavated after May 8, 1992, to a level of 0.6 mg/L (measured as TCLP chromium) prior to landfill placement.

The Oregon Groundwater Quality Protection Policy was promulgated in 1989 as Oregon Administrative (OAR) 340-40 Groundwater Quality Protection. Although the rule contains a chromium standard of 0.05 mg/L, removal and remedial actions administered under other State programs are not subject to the rule.

In 1995 the State of Oregon implemented the Hazardous Substance Remedial Rules (OAR 340-122), which require remedial actions to achieve acceptable risk levels for human and ecological receptors. Based on existing information, the current site cleanup goals for upper zone and deep aquifer groundwater meet the acceptable risk level requirement (see Table 7-2).

7-6 CVO/030480004

TABLE 7-2
Comparison of Groundwater and Soil Cleanup Levels
United Chrome Products, Corvallis, OR

	MCL		Site Specific ²		Year 2002 PRGs ³	
Media	1985	2002	1985	2002	Residential	Industrial
Groundwater (mg/L)						
- Upper Zone	NA ¹	NA	10	10	NA	NA
- Deep Aquifer	0.05	0.1	NA	NA	0.11	NA
Soil (mg/kg)	NA	NA	NA	428	210	450

Notes:

7.2.2 Changes in Cleanup Levels

The 0.05 mg/L deep aquifer groundwater cleanup level specified in the ROD was set based on the drinking water MCL applicable in 1986. A cleanup level of 10 mg/L was specified for upper zone groundwater, because due to low and unreliable yield, it did not represent a drinking water source. The 10 mg/L cleanup level, is a site-specific standard designed to protect deep aquifer groundwater at a water supply well located 3000 feet northeast of the site.

On January 31, 1991, EPA revised the drinking water MCL from 0.05 mg/L to 0.1 mg/L (56 FR 3526, USEPA, 1991). Accordingly the deep aquifer cleanup level was changed to 0.1 mg/L in 1991 to align with the new MCL (Interim Closeout Report, EPA 1991). No corresponding change was made to the 10 mg/L upper zone cleanup level.

No further changes to the chromium drinking water MCL have been made since 1991.

7.2.3 Changes in Exposure Pathways

A baseline risk assessment for the United Chrome site was not completed in conjunction with preparation of the RI/FS report. However, from language contained in the ROD, ingestion of contaminated groundwater was the primary exposure pathway of concern. Drinking water for the airport industrial park is now obtained from the City of Corvallis Taylor Water Treatment Plant. Therefore, there are no current groundwater users. Additionally, local ordinances and the groundwater pumping exclusion zone (see Appendix D) established around United Chrome by the Consent Decree would prevent installation of future drinking water wells within the airport industrial park.

Exposure to contaminated soil through ingestion, inhalation and dermal contact was not addressed in the ROD. To determine if residual risk associated with contaminated soil

CVO/030489004 7-7

^{1.} NA = not applicable

^{2.} Site-specific upper zone groundwater cleanup level from ROD (EPA 1986). Soil cleanup level calculated by DEQ (2002) based on site-specific hexavalent chromium to total chromium ratio.

^{3.} PRG = Region 9 preliminary remediation goals are risk-based screening concentrations corresponding to a 1.0E-06 human health cancer risk or non-cancer hazard index of 1.0. The PRGs are based on conservative assumptions, which may differ from site conditions.

remaining at the site is present, the Oregon DEQ conducted a screening level risk assessment in 2002. In their risk screening, the DEQ evaluated the following exposure scenarios:

- Industrial /Commercial Worker. Future workers engaged in site activity could come in contract with contaminated surface soil (0-3ft bgs). These workers are assumed to be onsite for 250 days a year for 25 years.
- Excavation Worker. Future excavation workers could come in contact with contaminated surface and subsurface soil (0 to 12.5-ft bgs) during maintenance or alteration of existing landscape, or to install and repair underground utilities and building foundations. These workers are assumed to be on-site for 9 days for one year.
- Residential Scenario. To evaluate an "unrestricted use scenario", it is assumed that the
 United Chrome Products site could become a residential setting in the future. Children
 and adults were assumed to be exposed to contaminated surface soil for 350 days per
 year over a 30-year timeframe.

The results from DEQ's risk screening are summarized below. The risk calculations are based on DEQ exposure assumptions and exposure concentrations of 4040 mg/kg chromium (onsite surface soil) and 4962 mg/kg (onsite subsurface soil).

Industrial/Commercial Worker

Cancer and noncancer risks associated with exposure to the chromium reasonable maximum exposure (RME) concentration in surface soil by an industrial/commercial worker are 6E-05 and 0.7, respectively. Thus, noncancer risks are within the acceptable levels (less than 1.0) for Oregon. However, cancer risks exceed the acceptable risk level of 1E-06. The cancer and noncancer risk levels are acceptable per EPA requirements.

Excavation Worker

Cancer and noncancer risks associated with exposure to the chromium RME concentration in subsurface soil by a future industrial/commercial worker are 5E-08 and 0.06, respectively. Thus, the cancer and noncancer risks are within the acceptable levels for Oregon. They would also be acceptable under EPA requirements.

Resident

To assess United Chrome site risk under an unrestricted use and unrestricted exposure scenario, cancer and noncancer risks associated with exposure to the chromium RME concentration in onsite surface soil by a resident were calculated resulting in a cancer and noncancer risk of 1E-04 and 18, respectively. The cancer risk exceeds Oregon requirements and is at the lower end of that preferred by EPA. The noncancer risk exceeds both Oregon and EPA requirements.

7-8 CVO/030480004

7.3 Has Any Other Information Come to Light that Could Effect the Remedy's Protectiveness?

Although the surface water monitoring program was discontinued in 1991 following construction of the bypass ditch and review of monitoring data collected between 1989 and 1991 (Performance Evaluation of Site Remediation for the United Chrome Products Site April 1989 to May 1991, CH2M HILL 1991) concerns about residual chromium in the drainage ditch sediment remain.

In July 2002 the DEQ completed a review of surface water data collected in the vicinity of the United Chrome Products site in 1984, 1989, 1991, and 1993 (*Recommendations for Evaluating Ecological Risk at the United Chrome Superfund Site*, Corvallis, Oregon, DEQ 2002). This review concluded that:

- Surface water samples collected in 1984 showed aluminum, barium, chromium, copper, iron, lead, manganese, mercury, and vanadium concentrations above DEQ's Level II Aquatic Screening Benchmark Values (SBVs) (DEQ, 1998).
- Surface water samples collected between April 1989 and March 1991, prior to completion of the bypass ditch, showed elevated levels of hexavalent chromium at locations between the site culvert, Dry Creek, and the Booneville Slough.
- Surface water samples collected adjacent to and downstream of the site in June 1993 showed cadmium, chromium, hexavalent chromium, copper, lead, and zinc in surface water at concentrations greater than the DEQ aquatic SBVs.

Surface water, sediment, flora, and fish tissue data were also collected by DEQ in 1988 as part of the "Drinking Water Impact Investigation" (DEQ, 1988). This investigation analyzed for dissolved chromium and hexavalent chromium in surface water, and total chromium and lead in surface water, sediment, vegetation, and fish. Sample locations SWS19, SWS12 in Dry Creek contained elevated levels of chromium and lead in surface water. Chromium was detected in sediments at concentrations above the Threshold Effect Level (TEC) (MacDonald, 2000) at all locations along the West Fork Booneville Channel (SWS12, SWS13, SWS14, and SWS16).

7.3.1 DEQ Recommendations

Based on the existing surface water and sediment data, DEQ concluded that site related metal contamination once extended from United Chrome to the West Fork Booneville Channel. However, the current extent and magnitude of this contamination, approximately 12 years after the construction of the by-pass ditch, is unknown. To determine if ecological risk is still present, DEQ recommended the following:

- Conduct a Level I Risk Scoping per current DEQ guidance (DEQ, 1998).
- Conduct a Level II Risk Screening per current DEQ guidance. This would include sampling to determine the current extent and magnitude of the surface water and sediment contamination. Proposed sampling locations and analysis parameters are described in Recommendations for Evaluating Ecological Risk at the United Chrome Superfund Site, Corvallis, Oregon (DEQ, 2002).

CVO/030480004 7-9

These recommendations were communicated to the City in an August 22, 2002 meeting. At the time of this review, the Level I Scoping Report had been completed, and surface water and sediment samples collected and analyzed in accordance with DEQ's recommendations. The scope of further ecological risk evaluation work will be determined following EPA review of the City's surface water and sediment analysis results.

7.4 Technical Assessment Summary


The United Chrome Products remedy has been very successful. Through December 2002, groundwater cleanup standards have been achieved at 47 of 49 upper zone and 15 of 17 deep aquifer well locations. Unfortunately, remediation of a small portion of the upper zone plume in the vicinity of well EW-9, and a low-volume, natural discharge of chromium contaminated pore water from the upper aquitard to the deep aquifer have prevented cleanup levels from being attained at the remaining well locations.


Verification sampling performed during the October 2000 source removal work indicates that residual chromium contamination between 20 mg/Kg (background) and 6000 mg/Kg remains in upper zone soil. Although this material is not expected to prevent the upper zone groundwater 10 mg/L ROD performance standard from being achieved, it will prevent the site from attaining an unrestricted use and unrestricted exposure status under both Federal and State regulations.

Long-term management of waste material, such as that remaining in the upper zone and upper aquitard, was not foreseen in the ROD. The description of the selected remedy, which was a combination of feasibility study alternatives 5 and 9, indicates that "these two remedial activities [soil flushing/unconfined zone groundwater extraction] will complement each other to remove all sources of confined aquifer contamination".


Given sufficient time, natural flushing and elements of the remedy still in operation at the site will most likely restore chromium concentrations in upper zone and upper aquitard soil and deep aquifer groundwater to levels that would be protective under most reasonable exposure scenarios. However, the rate of remediation will be slow and the cost potentially disproportional to the overall environmental benefit.

7-10 CVO/030480004





Chromium Concentration Trends at Interior Wells



Chromium Concentration Trends at Interior Wells






Figure 7-2a
Upper Zone Groundwater Chromium Concentration Trends


United Chrome Products Site
Corvalis, Oregon





Chromium Concentration Trends at Year 1992 to 2000 Boundary Wells




Chromium Concentration Trends at Year 2000 to 2002 Boundary Wells










Chromium Concentration Trends at Year 2000 to 2002 Boundary Wells










Chromium Concentration Trends



Chromium Concentration Trends





Figure 7-5


Deep Aquifer Groundwater Chromium Concentration Trends

United Chrome Products Site
Corva, 's, Oregon

Chromium Concentration Trends



Chromium Concentration Trends



8. Issues


Three issues were identified that may affect the remedy's ability to achieve the performance standards specified in the ROD, and therefore, its future protectiveness. In addition, the third issue needs to be addressed before EPA can determine whether the remedy is protective in the short-term. These issues (see Table 8-1) include:

- Chromium concentrations in upper zone soil are higher than considered protective for direct contact for industrial land uses.
- Chromium concentrations in the lower aquifer are increasing in two wells in the source area, after decreasing for many years.
- 3. It is not known whether or not there is an unacceptable ecological risk from chromium in downgradient drainage ditch sediment.

Issues number 1 and 2 do not affect current protectiveness and will not affect future protectiveness because no one is drinking groundwater from the lower aquifer within the affected area and the site is not currently being used for industrial land uses.

TABLE 8-1 Issues Potentially Affecting Remedy's Current or Future Protectiveness United Chrome Products, Corvallis, OR

Issue	Affects Current Protectiveness (Y/N)	Affects Future Protectivenes (Y/N)		
Chromium concentrations in upper zone soil are higher than considered protective for direct contact for industrial land uses.	No	Yes		
Chromium concentrations in the lower aquifer are increasing in two wells in the source area, after decreasing for many years.	No	Yes.		
3. It is not known whether or not there is an unacceptable ecological risk from chromium in downgradient drainage ditch sediment.	Yes	Yes		



9. Recommendations and Follow-up Actions

The following recommended actions address the issues identified in Section 8.

Recommendations/Follow-up Actions	Party Responsible	Oversight Agency	Milestone Date	Follow-up Actions: Affects Protectiveness (Y/N)	
				Current	Future
1. Evaluate the hydrogeology and contaminant transport between the soil, upper zone, upper aquitard, and lower aquifer as necessary to understand the causes of the recent groundwater contaminant trends (addresses issue 2)	EPA	EPA	October 1, 2003	no	yes
2. Based on the results of the above evaluation, re-evaluate the clean-up levels and current remedial approach (addresses issue 2)	EPA and City of Corvallis	EPA	March 31, 2004	no	yes
3. Place additional institutional controls for land use restrictions as needed (addresses issue 1)	City of Corvallis	EPA and DEQ	March 31, 2004	no	yes
4. Collect data on site-related contamination in the downgradient drainage ditches and water bodies, and then evaluate the ecological risks posed by these sediments (addresses issue 3)	City of Corvallis	EPA and DEQ	October 1, 2003	yes	yes

CVO/030480004 9-1

Work has already begun to address these recommendations. For example, the City of Corvallis has collected and analyzed data on the surface water and sediment quality in the drainage ditches as requested by Oregon DEQ, though this information has not been published yet nor presented to DEQ or EPA. In addition, EPA's consultant, CH2M Hill has prepared a preliminary memorandum to consider some of the issues in the second recommendation.

Some of the questions that may be addressed as part of the re-evaluation in the second recommendation include:

- Are the clean-up levels established in the ROD and related decision documents for the upper soil and groundwater sufficient to protect the lower aquifer?
- Should the current groundwater pumping approach/regime be changed?

10. Protectiveness Statement

10. Protectiveness Statement

A protectiveness determination of the remedy at the United Chrome Products site cannot be made at this time until further information is obtained. Further information to determine whether the remedy currently protects human health and the environment will be obtained by the data collection and ecological evaluation of the down-gradient drainage ditches and surface water. It is expected that these actions will take six months to complete, at which time a protectiveness determination will be made. The soil and lower aquifer remedy currently protects human health and the environment because the site is fenced and not being used and the area of the lower aquifer with contamination above the MCL is not being used for drinking water. Additional actions described in the recommendations above are needed to ensure long-term protectiveness.

CVC/030480004 10-1

11. Next Review

The next review will be conducted prior to March 2008.

CVO/030480004 11-1

12. References

CH2M HILL. 1999a. United Chrome Site Inspection. CH2M HILL memorandum, July 30, 1999, Corvallis, Oregon.

CH2M HILL. 1995b. Scope of Work (Attachment to the Consent Decree)

CH2M HILL. 2001. Pumping Plan, Version 5.

CH2M HILL. 2002a. Work Plan for Work Assignment No. 102-FR-FE-1032. October 30, 2002.

CH2M HILL. 2002b. Re-Evaluation of United Chrome Cleanup Goals and Selected Remedy. Draft memorandum, December 9, CH2M HILL, Corvallis, Oregon.

CH2M HILL. 2003. Site Inspection and Interview Report. CH2M HILL memorandum, January 29, 2003, Corvallis Oregon. Appendix A, this document.

City of Corvallis, Corvallis General Flood Hazard Map. 2000.

EPA. 1986. United Chrome Record of Decision.

EPA. 1991a. United Chrome Explanation of Significant Differences.

EPA 1991b. Interim Closeout Report.

EPA. 1998. United Chrome Products Superfund Site, Corvallis, Oregon, Five-Year Review.

EPA. 2001. Comprehensive Five-Year Review Guidance. EPA/540/R-01/007. OSWER Directive 9355.7-03B, June 2001.U.S. Environmental Protection Agency, Office of Emergency and Remedial Response, Washington, D.C.

http://www.epa.gov/superfund/resources/5year/index.htm.

National Wetlands Inventory. 2000. Wetlands and Hydric Soils, Southern Corvallis. Oregon Division of Lands.

CVO/030480004 12-1

Appendix A Site Interview and Inspection Summary

MEMORANDUM CH2MHILL

United Chrome Site Inspection and Interview Summary

TO:

Alan Goodman/EPA Region 10

COPIES:

Nancy Gramlich/Oregon DEQ

FROM:

Scott McKinley

DATE:

January 29, 2003

This memorandum summarizes findings from an inspection of the United Chrome site and community interviews performed in conjunction with the third Five-Year review. The work was conducted between December 5 and January 21, 2003 in accordance with information provided in the Comprehensive Five-Year Review Guidance (EPA, April 1999) and individuals listed in Interview Candidates for the United Chrome Five-Year Review (CH2M HILL Memorandum November 26, 2002). An updated site map (Attachment 1), site inspection form (Attachment 2), community interview forms and selected interview correspondence (Attachment 3), and a summary of significant site events are provided as attachments to this memorandum. Site photographs will be included with the five-year review report.

1.0 Site Inspection

Two security fences enclose the United Chrome site, with access obtained through gates located off Airport Place. The outer fence, maintained by the Federal Aviation Administration, encloses the Corvallis Airport and is labeled with no trespassing and warning signs approximately every 100-feet along its entire length. The inner fence encloses the United Chrome and CoEnergy sites (see Figure 2), which lie within the Corvallis Airport property. A third fence separates the United Chrome and CoEnergy sites from one another, and separate locking gates control entry and egress from each. CoEnergy also uses two guard dogs to patrol their facility 24-hours per day.

Although the City of Corvallis (the City) maintains the groundwater extraction equipment in good working order, the site receives only a nominal amount of landscaping maintenance, and therefore, appears unkempt. Herbicide applied in October 2002 has killed much of the blackberry type vegetation present at the site, and its decayed nature contributes to the site's marginal appearance. Additionally, following removal of the treatment system infrastructure, the City no longer has a covered area to store equipment associated with past well conversion and well abandonment work. This equipment has replacement or salvage value and is currently being stored on an asphalt surface near wells EW7 and EW10, and near the decontamination pad.

Land use in the immediate vicinity of the site remains airport services (maintenance and parking, propane fueling (Ferril Gas and CoEnergy) and agricultural (grass seed farming). The United Chrome site is zoned under the City of Corvallis Comprehensive Land Use Plan

175923.SI.01

CVO/INSPECT SUMMARY.DOC 1

as general industrial. The City of Corvallis Airport Manager reports that Ferril Gas will most likely relocate onto the United Chrome site following completion of the remedial action.

1.1 Site Cover

Although not widely discussed in prior documents, large portions of the site are covered with asphalt and concrete. The main portion of the site is overlain with reinforced concrete approximately 25,000 square feet in area and 12-inches thick. This cover represents the floor of the former United Chrome Products building. An extensive floor trench system varying in depth from 4 to 12 inches is recessed within the floor. The trench has been filled with gravel but appears to drain towards the southwest corner. I removed the gravel at one location to inspect the trench and it appeared to be in very good condition. There are also several drain openings in the floor, just south of the power transformer, that most likely discharge to an inactive onsite septic system.

An asphalt roadway (former County Road) and parking area border the concrete to the north. Along the west, south and east sides of the concrete, the surface is unpaved.

1.2 Groundwater Remedy

Groundwater Extraction System

The only extraction wells still in operation are upper zone well EW-9 and deep aquifer wells DW-8 and DW-9. The remaining extraction wells have been converted to monitor wells, or have met the cleanup standard and been abandoned per EPA approval. The status of all wells initially present at the start of the remedial action in 1988 is shown on Table 1. Only those wells still present are shown on Figure 2. At the time of the inspection, wells EW-9, DW-8 and DW-9 were operating satisfactorily.

Insulated shelters enclose the upper zone and deep aquifer extraction wells. The shelters are in good condition and provide adequate weather protection. Although there was some evidence that the shelters have been recently used as nesting sites by birds or other small animals, this has been a re-occurring condition, and does not affect extraction well operation, or ground water monitoring activities.

The above ground piping that conveys groundwater from extraction wells EW-9, DW-8 and DW-1 to the discharge point is in good shape. However, the bridge near DW-1, which allows vehicles to drive safely over the pipe, is in poor condition and should be repaired if future vehicle traffic through this area is required. The bridge was damaged by heavy truck traffic during the October 2000 upper zone source excavation work.

Injection System

Infiltration basins (Basin 1 and Basin 2) were decommissioned in August 2000 in conjunction with the upper zone source excavation work. The decommissioning work included removal of geotextile material, above-grade concrete walls, plumbing and valve controls. The injection trench is still operational but has not been used, except for a short trial in November 2000, since January 1993. Given the limited nature of current upper zone pumping operations, it's unlikely the trench will be required in the future.

Groundwater Monitoring Network

All of the groundwater monitor wells/piezometers shown on Figure 2 were located and all appear to be in satisfactory condition for continued use as required by the Pumping Plan – Version 5 (CH2M HILL, May 2001). CH2M HILL had scheduled the site inspection for December 4, 2002 to correspond with the City's semiannual sampling of the upper zone monitor wells. Unfortunately, the City's sampling pump failed to operate due to freeze damage, and therefore, the sampling was not performed on this date.

Treatment System

The ground water treatment system was removed in April 1999. The only components remaining are the secondary containment wall which enclosed the tank storage and treatment system areas, the partially enclosed shop, the electrical control panel, the decontamination pad, and the containment cell for the sludge thickening tanks. The secondary containment wall has been intentionally breached along the west and north walls to prevent accumulation of large amounts of rainwater. The metered discharge point, where extracted ground water is discharged to the sanitary sewer is in satisfactory condition.

Office and Laboratory Trailer

An office and laboratory trailer and locker room trailer, constructed as part of the groundwater remedial construction effort, are still maintained by the City of Corvallis. All onsite testing is done in the laboratory trailer, but most document/data management is performed at the City of Corvallis wastewater treatment plant. The laboratory equipment appeared to be in good working condition, and the City provides copies of all calibration and quality assurance checks with the quarterly progress reports. Copies of the O&M Manuals, health and safety plan, and historic site related documents are also kept onsite. The O&M manual has not been updated since the treatment system was decommissioned in April 1999. However, to support an update to the site Health and Safety Plan, the City prepared a summary of significant site events. This summary is provided in Attachment 4.

2.0 Community Interviews

Telephone and personal interviews were conducted, and questionnaires mailed to the individuals as shown in Table 2. In general, many of the interviewee's with current knowledge about the cleanup effort were complimentary. Of the local residents interviewed, each had very little knowledge of the site and did not have a favorable or unfavorable opinion on cleanup progress or protectiveness.

PZ-E

PZ-F

PZ-F

SW-2A SW-3

SW-4

Table 1					
United Chrome Well Inventory – January 2003					
	***************************************	Upper	Zone Wells	***************************************	
	Extraction W	elis		Monitoring W	ells
Active	Inactive	Abandoned	Active	Inactive	Abandoned
EW-09		EW-08	EW-01	EW20	BG-1
77711		EW-17	EM-05		EW1(a)
		EW-18	EW-03		MW-1
11.00		EW-19	EW-04		MW-2A
		EW-21	EW-05		MW-3
		EW-22	EW-06		PL1
		EW-24	EW-07		PL2
		EW-25	EW-10		PL3
		EW-26	EW-11		PL4
		EW-28	EW-12		PL5
		EW-29	EW-13		PZ-A
			EW-14		PZ-C
			EW-15	-	PZ-D

EW-16

EW-23

EW-27

MW-3

PZ-B SE-2A

51

21

CVO/INSPECT SUMMARY.DOC

Total Number of Wells Initially Present

Total Number of Wells Currently Present


		Table 1	(continued)		
	,	United Chrome Well	Inventory - Jani	uary 2003	
		Deep A	quifer Wells		
	Extraction W	ells		Monitoring W	ells
Active	Inactive	Abandoned	Active	Inactive	Abandoned
DW-8			DW-2	DW-1 (a)	DW-03A
DW-9	·		DW-10		DW-4
			DW-12		DW-5
			DW-13		DW-6
			DW-15		DW-7
					DW-11
					DW-14
					DW-16
					DW-17
					DW-18
***************************************		***************************************			DW-19
Total Number of Wells Initially Present		19			
Total Number of Wells Currently Present		8		, , , , , , , , , , , , , , , , , , ,	

Notes:

(a). This well approved for abandonment during June 2001 (Phase 5) work. However, due to diameter of conductor casing, the drilling contractor was unable to complete the work.

Table 2						
	Interview List					
		ird Five-Year Revie				
Name	Title and Affiliation	Interview Date	Interview Method			
Bruce Curtis	United Chrome Site Operations – City of Corvallis	12/11/2002	Personal interview conducted at United Chrome site			
Buck Taylor	Airport Manager - City of Corvallis	01/10/03	Telephone interview			
Doug Sweetland	Manager - Corvallis and Benton Economic Development Council	1/10/03	Personal interview conducted at CH2M HILL Corvallis office			
Bill Emminger	Manager – Benton County Health Department	1/9, 1/21/2003	Telephone interview			
(b) (6)	On Mailing List	12/16/2003	Mailed Questionnaire – did not respond			
	On Mailing List	12/16/2003	Mailed Questionnaire returned as undeliverable			
	On Mailing List	12/16/2003	Mailed Questionnaire did not respond. Not listed in telephone directory.			
	On Mailing List	12/16/2003	Mailed Questionnaire – returned as undeliverable			
	On Mailing List	12/16/2003	Mailed Questionnaire – did not respond. Not listed in telephone directory.			
	On Mailing List	12/16/2003	Mailed Questionnaire – did not respond. Not listed in telephone directory.			
	On Mailing List	12/16/2003	Mailed Questionnaire —did not respond.			
	Resident -(b) (6)	12/04/2002	Telephone interview			
	Resident -	1/11/2003	Personal Interview			
Confidential	Resident -	01/11/2003	Personal Interview			
Confidential	Resident -	01/11/2003	Personal Interview			


Attachment 1 - Updated Base Map



СЕМНІП

SITE PLAN

UNITED CHROME PRODUCTS SITE
CORVALUS, OREGON



Attachment 2 - Site Inspection Form

Please note that "O&M" is referred to throughout this checklist. At sites where Long-Term Response Actions are in progress, O&M activities may be referred to as "system operations" since these sites are not considered to be in the O&M phase while being remediated under the Superfund program.

Five-Year Review Site Inspection Checklist (Template)

(Working document for site inspection. Information may be completed by hand and attached to the Five-Year Review report as supporting documentation of site status. "N/A" refers to "not applicable.")

I. SITE INFORMATION			
Site name: United Chrone	Date of inspection: $1/1/03$		
Location and Region: Corvellis, OR Region 10	EPA ID: ORD 6090 43001		
Agency, office, or company leading the five-year review: (#2m #)	Weather/temperature: Raining 40°F		
Remedy Includes: (Check all that apply) Landfill cover/containment			
Attachments: Inspection team roster attached	Site map attached		
II. INTERVIEWS	· · · · · · · · · · · · · · · · · · ·		
1. O&M site manager Bruce Cu-tis Site Manager 12/5/02 Name Title Date Interviewed M at site at office by phone Phone no. Problems, suggestions; M Report attached			
2. O&M staff Same A5 #1 above Name Interviewed □ at site □ at office □ by phone Phone Problems, suggestions; □ Report attached	e no		

3.	Local regulatory authorities and response agencies (i.e., State and Tribal offices, emergency response office, police department, office of public health or environmental health, zoning office, recorder of deeds, or other city and county offices, etc.) Fill in all that apply.				
	Agency Bertan (ounts Health Contact Bill Emminger Name Problems; suggestions; Report attached		1/13/03 Date	766 - 6835 Phone no.	
	Agency City of Corvalls - Aires Contact Buck Taylor Name Problems; suggestions; \$\$ Report attached	Manager Manager Title	1/1./03 Date	Phone no.	
	Agency Cocyallis - Bester County Contact Doing Sweetland Name	Economic Deuclopment Managen Title	Council 1/16/63 Date	Phone no.	
	Agency Name		Date	Phone no.	
	Problems; suggestions; ☐ Report attached _			THOSE IIO.	
4	Other interviews (optional) A Report attac	hed.	· - · · · ·		
			* ***		
		•			
				· .	

	III. ON-SITE DOCUMENTS & RECORDS VERIFIED (Check all that apply)]
1.	O&M Documents O&M manual	
2.	Site-Specific Health and Safety Plan Readily available Up to date N/A Remarks City Cuttodly updating plan to compact "deal-man" alarm (quitement.)	
3.	O&M and OSHA Training Records	
4.	Permits and Service Agreements Air discharge permit	pretro-line
5.	Gas Generation Records	
6.	Settlement Monument Records □ Readily available □ Up to date N/A Remarks	-
7.	Groundwater Monitoring Records Readily available YUp to date N/A Remarks	<u>-</u>
8.	Leachate Extraction Records ☐ Readily available ☐ Up to date ☐ N/A Remarks	.
9.	Discharge Compliance Records ☐ Air ☐ Readily available ☐ Up to date ☐ N/A Water (effluent) Remarks ☐ Readily available ☐ Up to date ☐ N/A	
10.	Daily Access/Security Logs	7

	IV. O&M COSTS				
1.	O&M Organization ☐ State in-house ☐ Contractor for State ☐ PRP in-house ☐ Contractor for PRP ☐ Federal Facility in-house ☐ Contractor for Federal Facility ☐ Other				
2.	Readily available [X Up to date X				
3.	Unanticipated or Unusually High O&M Costs During Review Period Describe costs and reasons: An additional Cost of \$397, 051, 25 Was incurred in October 2000 in Conjunction with the Upper Zone Soil Source excaustion project.				
	V. ACCESS AND INSTITUTIONAL CONTROLS A Applicable I N/A				
A. Fei	ncing				
1.	Fencing damaged A Location shown on site map A Gates secured IN/A Remarks Double Cose Site Score and FAA Score				
B. Ot	her Access Restrictions				
1.	Signs and other security measures D Location shown on site map D N/A Remarks Sign Accept at gate but does not warn or advise against diesseuss, or identity a confact present. No diesseuss				

Sicas No FAA fince.

C. Inst	itutional Controls (ICs)		·	
1.	Implementation and enforcement Site conditions imply ICs not properly implemented Site conditions imply ICs not being fully enforced Type of monitoring (e.g., self-reporting, drive by) Self-m	☐ Yes X No ☐ Yes X No	□ N/A □ N/A	
	Frequency Wickly Responsible party/agency City of Coultis	<u>. J</u>		<u>:</u>
	Contact Den Hentherns WWTD Manager Name Title	1/8/03 Date	541-754-(757 Phone no.	
	Reporting is up-to-date Reports are verified by the lead agency	MYes □ No MYes □ No		
	Specific requirements in deed or decision documents have been met Violations have been reported Other problems or suggestions:	Yes DNo	▲	
2.	Adequacy Remarks Question has been raised by a whether TC needs to be modified to experience to soil Isodiment Continuous from	control pol	ONA conter on cotial In Amely dear	nge ditak
D. Gen	eral .			
1.	Vandalism/trespassing ☐ Location shown on site map No Remarks	vandalism evident		
2.	Land use changes on site N/A Remarks Onsite and use world to airp according to Argent Master Plan	not and pre	pane feeling	
3.	Land use changes off site □ N/A Remarks / 10			
·	VI. GENERAL SITE CONDITIONS		·	
A. Roa	ds MApplicable □ N/A			
1.	Roads damaged	ds adequate	□ N/A	

Γ					
B. Ot	B. Other Site Conditions				
	Remarks At this time general site appearance is poor. Herbicide				
	Was applied in Oct 2002 to control briars (blackberry)				
1	which have taken root awithin unpavel areas of				
	the site. Much of the facility above-ground laterastemeters				
•	(i.e. blas) was decommissioned in MarlApr 1999. Consequently				
İ	there is no place to store equipment ensite. Unused pumps				
	and piping from abandoned wells is stored uncovered.				
	VII. LANDFILL COVERS				
, y .					
A. La	ndfill Surface				
1.	Settlement (Low spots)				
	Areal extent Depth				
	Remarks				
2.	Cracks ☐ Location shown on site map ☐ Cracking not evident				
	Lengths Widths Depths				
	Remarks				
3.	Erosion				
	Areal extent Depth Remarks				
	Remarks				
4.	Holes □ Location shown on site map □ Holes not evident				
* .	Areal extent Depth Depth				
ļ	Remarks				
5.	Vegetative Cover ☐ Grass ☐ Cover properly established ☐ No signs of stress				
l '	☐ Trees/Shrubs (indicate size and locations on a diagram)				
i	Remarks				
6.	Alternative Cover (armored rock, concrete, etc.)				
	Remarks				
	D. L				
7.	Bulges ☐ Location shown on site map ☐ Bulges not evident Areal extent ☐ Height ☐ Dulges not evident				
	Areal extent Height Remarks				

8.	Wet Areas/Water Damage ☐ Wet areas ☐ Ponding ☐ Seeps ☐ Soft subgrade Remarks	 □ Wet areas/water damage not evident □ Location shown on site map Areal extent
9.	Slope Instability ☐ Slides Areal extent Remarks	☐ Location shown on site map ☐ No evidence of slope instability
В.	(Horizontally constructed mounds	N/A of earth placed across a steep landfill side slope to interrupt the slope of surface runoff and intercept and convey the runoff to a lined
1.	Flows Bypass Bench Remarks	☐ Location shown on site map ☐ N/A or okay
2.	Bench Breached Remarks	☐ Location shown on site map ☐ N/A or okay
·3.	Bench Overtopped Remarks	☐ Location shown on site map ☐ N/A or okay
C.	Letdown Channels	ol'mats, riprap, grout bags, or gabions that descend down the steep side he runoff water collected by the benches to move off of the landfill
1.	Settlement	ation shown on site map No evidence of settlement Depth
2.	Material Degradation ☐ Loca Material type Remarks	ation shown on site map No evidence of degradation Areal extent
3.	Erosion	ation shown on site map No evidence of erosion Depth

4.	Undercutting
5.	Obstructions Type DNo obstructions D Location shown on site map Areal extent Size Remarks
6.	Excessive Vegetative Growth No evidence of excessive growth Vegetation in channels does not obstruct flow Location shown on site map Remarks
D. Cov	er Penetrations 🛘 Applicable 🛕 N/A
1.	Gas Vents □ Active □ Passive □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition □ Evidence of leakage at penetration □ Needs Maintenance □ N/A Remarks □ N/A
2.	Gas Monitoring Probes ☐ Properly secured/locked☐ Functioning ☐ Routinely sampled ☐ Good condition ☐ Evidence of leakage at penetration ☐ Needs Maintenance ☐ N/A Remarks
3.	Monitoring Wells (within surface area of landfill) ☐ Properly secured/locked☐ Functioning ☐ Routinely sampled ☐ Good condition ☐ Evidence of leakage at penetration ☐ Needs Maintenance ☐ N/A Remarks
4.	Leachate Extraction Wells ☐ Properly secured/locked ☐ Functioning ☐ Routinely sampled ☐ Good condition ☐ Evidence of leakage at penetration ☐ Needs Maintenance ☐ N/A Remarks
5.	Settlement Monuments

E. G	as Collection and Treatme	nt □ Applicable	A N/A
1.	Gas Treatment Facilitie ☐ Flaring ☐ Good condition Remarks	☐ Thermal destruction ☐ Needs Maintenance	□ Collection for reuse
2.	Gas Collection Wells, M ☐ Good condition Remarks_	Ianifolds and Piping ☐ Needs Maintenance	
3.	☐ Good condition		adjacent homes or buildings) □ N/A
F. Co	over Drainage Layer	☐ Applicable	XN/A
1.	Outlet Pipes Inspected Remarks	☐ Functioning	D N/A
2.	Outlet Rock Inspected Remarks	☐ Functioning	DN/A
G. D	etention/Sedimentation Por	nds Applicable	X N/A
1.	Siltation Areal extent ☐ Siltation not evident Remarks	<u>-</u>	CJ N/A
2.	☐ Erosion not evident	xtentD	•
3.	Outlet Works Remarks	☐ Functioning ☐ N/A	
4.	Dam Remarks	☐ Functioning ☐ N/A	



H. Retaining Walls		☐ Applicable	N/A	
1.	Deformations Horizontal displacement_ Rotational displacement_ Remarks			☐ Deformation not evident ement
2.	Degradation Remarks	□ Location show	n on site map	☐ Degradation not evident
I. Peri	neter Ditches/Off-Site Di	scharge	Applicable	O N/A
1.	Siltation Jaca Areal extent Remarks Byeass Ack water flow.	tion shown on site Depth Carstand.	send Site in	n 1989 to co-soute surface
2.	Vegetative Growth Vegetation does not im Areal extent Remarks Vegetation Accord pede flow	•	Dypass ditch constructed impede flow.	
3.	Erosion Areal extent Remarks		n on site map	Erosion not evident
4.	Discharge Structure Remarks	☐ Functioning	t X N/A	
	VIII. VER	TICAL BARRIE	R WALLS	Applicable N/A
1.	Settlement Areal extent Remarks	☐ Location show Depth	n on site map	☐ Settlement not evident
2.	Performance Monitoring Performance not monit Frequency Head differential Remarks	ored	Evidence	•

	IX. GROUNDWATER/SURFACE WATER REMEDIES SApplicable N/A
A.	Groundwater Extraction Wells, Pumps, and Pipelines Applicable 🗆 N/A
1.	Pumps, Wellhead Plumbing, and Electrical ☐ Good condition ☐ All required wells properly operating ☐ Needs Maintenance ☐ N/A Remarks
2.	Extraction System Pipelines, Valves, Valve Boxes, and Other Appurtenances M Good condition D Needs Maintenance Remarks Pipe bridges which project deep agailer above grand Pipery in Merginal Condition at Took Crossings near DW-1.
3.	Spare Parts and Equipment ☐ Readily available
В.	Surface Water Collection Structures, Pumps, and Pipelines Applicable X N/A
1.	Collection Structures, Pumps, and Electrical ☐ Good condition ☐ Needs Maintenance Remarks
2.	Surface Water Collection System Pipelines, Valves, Valve Boxes, and Other Appurtenances Good condition Needs Maintenance Remarks
3.	Spare Parts and Equipment ☐ Readily available ☐ Good condition ☐ Requires upgrade ☐ Needs to be provided Remarks

C.	Treatment System	
1	Treatment Train (Check components that apply) Metals removal Oil/water separation Bioremediation Air stripping Carbon adsorbers Filters Additive (e.g., chelation agent, flocculent) Others Good condition Needs Maintenance Sampling ports properly marked and functional Sampling/maintenance log displayed and up to date Equipment properly identified Quantity of groundwater treated annually Quantity of surface water treated annually Remarks Treatment system forward in April 1949.	
		_
2.	Electrical Enclosures and Panels (properly rated and functional) N/A Good condition	-
3.	Tanks, Vaults, Storage Vessels	nce
4.	Discharge Structure and Appurtenances □ N/A	_
5.	Treatment Building(s) N/A Good condition (esp. roof and doorways) Chemicals and equipment properly stored Remarks Blas removed (except office/laberators / lacker bla)	
6.	Monitoring Wells (pump and treatment remedy) □ Properly secured/locked & Functioning	
D.	Monitoring Data	
1.	Monitoring Data X Is routinely submitted on time X Is of acceptable quality	
2.	Monitoring data suggests: A Groundwater plume is effectively contained Contaminant concentrations are declining	

D. M	onitored Natural Attenuation
1.	Monitoring Wells (natural attenuation remedy) ☐ Properly secured/locked ☐ Functioning ☐ Routinely sampled ☐ Good condition ☐ All required wells located ☐ Needs Maintenance ☐ N/A Remarks
	X. OTHER REMEDIES
	If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.
	XI. OVERALL OBSERVATIONS
A.	Implementation of the Remedy
	Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.). Upper Zone (emody obsigned to flush Chronium from Soil to extration System for comove), and to remove Soluble Chromium Calcody present and that dissibility Idesability from Soil and nexaminant chromium Solub phase. Remedy to resters grown-to Chromium Concentrations to 10 mg/L in upper Zone and 0.1 mg/L in deep against Upper Zone (emodulium has been very Successful, Deep against comodulium has been solub.) Chromium Contentration for Comodulium has been solub. Chromium Contentration fore water denining from apper against.
B.	Adequacy of O&M
	Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy. Despite 5ite approximates, City's O-M fregram has been satisficity, All extensions wells are operable and excellent progress has been make to date.

C.	· Early Indicators of Potential Remedy Problems
	Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs, that suggest that the protectiveness of the remedy may be compromised in the future. Nens Costc
D.	Opportunities for Optimization
	Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy. Optimization has here anguing and these opportunities have here implemented where possible, and where remedy protectiveness can be main tained.

Attachment 3 - Interview Forms

United C	Chrome Five-Year Review Interview R	ecord	***************************************	
Site Name: United Chrome Products, 2000 Airport Rd. Corvallis, OR 97330 EPA ID No. ORD009043001				
Interview Type: Telephone Visit	Other	Date:	Time:	
Location of Visit: United Chrome	<u> </u>	12/11/02	1000	
	Contact Made By Suff	MUKINIO		
Name:	Title: Project Manager 0	rganization: ぐりつ	m Hill	
	Individual Contacted			
Name: Bruce Curtis	Title: Untal Chance Site Openhis O	rgenization: $C_i J_i$	ef Grundli	
Telephone:	Address:	<u> </u>		
	Summary of Conversation	,	·····	
What is your overall impression of the	- •			
Personally, very interest	my project. Cleaning is	Consistent w	ith desire	
to protest/restore 12	hing project. Cleaning is a convergence. Wants to projects is oren of expert up) had on the surrounding community?	see cleary c	Drytoke	
2) What affects have site operations (clean	projects 15 Orea of experts up) had on the surrounding community?	44.		
Nine to his K	nowledge.			
	-			
Are you aware of any community conc	erns regarding the site or its operation? If so, plear	to commende vous con	worm a	
*		· · ·	4.	
•	location makes the cleany	4 1683 AISIN	دد _. ۲۷۵۰	
Much media attenti	in .			
4) Do you feel well informed about the sit	e's activities and progress?			
ycs.				
Jey.				
5) Do you have any comments, suggestion	ns, or recommendations regarding the site's manag	gement or operation?		
City has always	felt that EPA has one	rneget feeds	back.	
Additional questions for Bruce Curtis		·		
6) Is the remedy functioning as expected?	How well is the remedy performing?			
yes. Upper Zone	performing well. Disappor	inted that	privisions	
for addressing ditch	performing well. Disapper. Were not done in Ro	De Saving it	to end.	
	nize O&M or sampling efforts? If so please describ	•		
UCS. Modified PLTS	, discharge to 10TW.	Have Muta	ally agreed	
	ductions and well abandon		• •	
	iculties or costs at the site since start-up or in the la			
	heads, risk of freeze damps	. Wellings	- 1/~	
Components. Vulnerable				
የቤታላ ተ				

United C	Chrome Five-Year Review Interview	ew Record		
Site Name: United Chrome Products, 2000	Airport Rd. Corvallis, OR 97330	EPA ID No. ORDO	09043001	
Interview Type: Telephone Visit Other: Mail Location of Visit: Date: Time: First low Am		Time: First low Am	Loft Ma	
Lecation of Visit.	Contact Made By	1 /10/03		
N Coott Makinlay	Title: Project Manager	Organization: CH2M		
Name: Scott McKinley	L	Organization: Ch2W		
	Individual Contacted	Ta		
Name: Buck Taylor	Address:	Organization: (4	of Corvallis	
Telephone: 766-6723	L	······		
What is your overall impression	Summary of Conversation of the project?			
long-time coming				
	•			
What affects have site operation.	s (cleanup) had on the surrounding c	ommunity?		
none what	60-cur			
VVIII VVIII				
Are you aware of any community concerns.	ry concerns regarding the site or its o	peration? If so, please	summarize your	
no				
The Deaple h	why were aware of Master Olan (alls to the site's activities and progress?	the site	hax	
Mould DO	Master Olan Calls of	ar use as	Sula Men	
4) Do you feel well informed abou	t the site's activities and progress?	excellent site	. Likes gates .	and the
905				
	<i>,</i>	•		
			ļ	
5) Do you have any comments, sur operation?	zgestions, or recommendations regar	ding the site's manage	ment or	
Went very w	ell, in his view.			
1	1			

United (Chrome Five-Year Review Interview	/ Record		
Site Name: United Chrome Products, 2000	Airport Rd. Corvallis, OR 97330	EPA ID No. ORD009	043001	
Interview Type: Telephone Visit	Other: Mail	Date:	Time:	
Location of Visit: CH2M H.II.	(coo Doug was in the off.	e 1/10/63	936	
	Contact Made By			
Name: Scott McKinley	Title: Project Manager	Organization: CH2M H	IILL	
	Individual Contacted			
Name: Doug Sweetland	Title: Manager	Organization: Benten	. Co. Economic I	أدرج
Telephone: 757 - 1507	Address:			
	Summary of Conversation			
1) What is your overall impression	of the project?			
Gone well , vo	ry detailed. Co En ith being next t	eran not con	word	
at all w	ith being next +	NPL SH	c	
	s (cleanup) had on the surrounding cor		·	
None				
Are you aware of any communiconcerns.	ty concerns regarding the site or its ope	ration? If so, please su	ımmarize your	
None.				
4) Do you feel well informed abou	t the site's activities and progress?			
yes.			·	
5) Do you have any comments, su operation?	ggestions, or recommendations regardi	ng the site's managem	ent or	
None.				

United C	Chrome Five-Year Review Inte	rview Record		
Site Name: United Chrome Products, 2000	Airport Rd. Corvallis, OR 97330	EPA ID No.	ORD0090430	001
Interview Type: Telephone Visit Location of Visit:	Other: Mail	Date:	1	me: 015 Am
	Contact Made By			
Name: Scott McKinley	Title: Project Manager	Organization:	CH2M HILL	
<u>, , , , , , , , , , , , , , , , , , , </u>	Individual Contacted			·····
Name: Bill Emminger	Title: Manger	Organization:	Bento (Const. He
Telephone: 766 - 6435	Address:			
	Summary of Conversation			
1) What is your overall impression	of the project?		•	
Part Vma M	uch about it. Onl	laces on	110	
100 ter 8-1	renths. Will discuss	with other	staff	anl
Call buck.			•	•
What affects have site operation:	e (cleanum) had on the currounding	e community?		
	s (cleanup) mad out the surrouncan	8		
*	s (cleanup) had on the suitounian	· · · · · · · · · · · · · · · · · · ·		
No concerns.	s (cleanup) nad on the surrounces	8		
				
No Concerns. 3) Are you aware of any community.	ty concerns regarding the site or it		olease sumn	narize your
No Concerns. 3) Are you aware of any communic concerns.	ty concerns regarding the site or it	ts operation? If so, p		
No Concerns. 3) Are you aware of any communic concerns.	ty concerns regarding the site or it	ts operation? If so, p		
No Concerns. 3) Are you aware of any communic concerns.		ts operation? If so, p		
No Concerns. 3) Are you aware of any communic concerns.	ty concerns regarding the site or it	ts operation? If so, p		
No Concerns. 3) Are you aware of any community concerns. No Complaints of has been detected.	ty concerns regarding the site or it	ts operation? If so, p File in		
No Concerns. 3) Are you aware of any community concerns. No Complaints of has been delected. 4) Do you feel well informed about	ty concerns regarding the site or it Franciscos Expressol, I in Surface Well t the site's activities and progress:	ts operation? If so, p	deates	
No Concerns. 3) Are you aware of any community concerns. No Complaints of has been delected. 4) Do you feel well informed about	ty concerns regarding the site or it of Concerns Expressel, l in Surface Well	ts operation? If so, p	deates	
No Concerns. 3) Are you aware of any community concerns. No Complaints of has been delected. 4) Do you feel well informed about	ty concerns regarding the site or it Franciscos Expressol, I in Surface Well t the site's activities and progress:	ts operation? If so, p	deates	
No Concerns. 3) Are you aware of any community concerns. No Complaints of has been delected. 4) Do you feel well informed about	ty concerns regarding the site or it Franciscos Expressol, I in Surface Well t the site's activities and progress:	ts operation? If so, p	deates	
No Concerns. 3) Are you aware of any community concerns. No Complaints of has been delected. 4) Do you feel well informed about No, but ox	ty concerns regarding the site or it Franciscos Expressol, I in Surface Well t the site's activities and progress:	File in	deates	Chronium
No Concerns. 3) Are you aware of any community concerns. No Complaints of has been detected. 4) Do you feel well informed about No, but of the properties. 5) Do you have any comments, suggestion?	ty concerns regarding the site or it of Concerns Expressed, I in Surface Wede t the site's activities and progress: he's new to	s operation? If so, p File in 1.15 Postion garding the site's m	d cates	Chromum

United	d Chrome Five-Year Review Interv	iew Record	
Site Name: United Chrome Products, 20	00 Airport Rd. Corvallis, OR 97330	EPA ID No. ORDOO	9043001
Interview Type: Telephone V Location of Visit:	Date: 12/4/02	Time: 300	
	Contact Made By		
Name: Scott McKinley	Title: Project Manager	Organization: CH2M	HILL
	Individual Contacted		
Name: (b) (6) Telephone: (b) (6)	Title: Resident Address: (b) (6)	Organization:	
	Summary of Conversation		
2) What affects have site operation Not aware of	ons (cleanup) had on the surrounding	community?	
concerns.	out the site's activities and progress?	operation: 11 50, please 5	
Site has not	received Much Media EPA's Superfund Web site	Coverage No	; 1
5) Do you have any comments, operation?	suggestions, or recommendations rega	arding the site's managen	nent or
None			

United C	hrome Five-Year Review Interview	v Record		
Site Name: United Chrome Products, 2000 A	sirport Rd. Corvallis, OR 97330	EPA ID No. ORDO	09043001	
Interview Type: Telephone Visit Location of Visit:	Other: Mail	Date: 1/11/63	Time: 1445	
	Contact Made By			
Name: Scott McKinley Title: Project Manager Organization: CH2M HILL				
	Individual Contacted			
Name: (b) (6)	Title: Resident (b) (6)	Organization:		
Telephone: WA	Address;			
What is your overall impression	Summary of Conversation			
GazeHe. Times 2) What affects have site operations Not aware of	He site from the No impression approximately and the surrounding control of the surrounding control of the site or its open some site or its open site or its o	mmunity?		
Satisfactory	the site's activities and progress?			
5) Do you have any comments, sug operation?	gestions, or recommendations regard	ing the site's manager	ment or	

		·····	and the same of th	<u></u>
United C	chrome Five-Year Revi	ew Interview F	lecord	,
Site Name: United Chrome Products, 2000 /	Airport Rd. Corvallis, OR 9733)	EPA ID No. ORDO	09043001
Interview Type: Telephone (Visit	Other; Mail		Date:	Time:
Location of Visit: in field			1/11/03	1530
	Contact Made	Ву		·
Name: Scott McKinley	Title: Project Manager	c	rganization: CH2M	HILL
	Individual Conta	icted		
Name: Confidential	Title: Resident Address: (b) (6)	C	rganization:	
Telephone: NA	Address: (D) (6)			
	Summary of Conve	ersation		
What is your overall impression	of the project?			.
A21 C		1		
Not tamilia	with the	5Hc		
05 747 + 66 + 1	71 33 1 H	1-		•
What affects have site operations	s (cleanup) nad on the sui	rounding comm	iunity?	
NA				
NA				
3) Are you aware of any communit	y concerns regarding the	site or its operat	ion? If so, please :	summarize your
concerns.		•	•	,
. 1				
No				
4) Do you feel well informed about	the cite's activities and n	vograce?		
7) Do you leer wen nitorined about	the site's activities and p	iogiessi	•	
No	•			
,,,,,				
		Manager 22	41	
Do you have any comments, sug operation?	gestions, or recommenda	nons regarding	tne site's manager	nent or
No				

1

United	Chrome Five-Year Review Inter	view Record	
Site Name: United Chrome Products, 2000	EPA ID No. ORD009043001		
Interview Type: Telephone (Visit) Other: Mail Location of Visit: in Field		Date:	Time: [545
	Contact Made By		
Name: Scott McKinley Title: Project Manager		Organization: CH2M HILL	
	Individual Contacted		
Name: Confidential	Title: Resident Organization:		
Telephone:	(b) (6)		
	Summary of Conversation		
1) What is your overall impression	of the project?		
Not fundam	with cleanup		
2) What affects have site operation	ns (cleanup) had on the surroundin	g community?	
Unaware of	any		
Are you aware of any commun concerns.	ity concerns regarding the site or it	s operation? If so, pleas	e summarize your
\mathcal{N}_{o}			
4) Do you feel well informed abou	ut the site's activities and progress?		
No			
5) Do you have any comments, su operation?	nggestions, or recommendations re	garding the site's manag	gement or
NA			· · · · · · · · · · · · · · · · · · ·

Interview Candidates for United Chrome Five-Year Review

TO:

Alan Goodman/EPA Region 10

COPIES:

Paul "Max" Rosenberg

FROM:

Scott McKinley

DATE:

November 26, 2002

This memorandum presents a proposed list of community representatives to be interviewed by CH2M HILL as part of the United Chrome March 2003 five-year review report. The overall purpose of these interviews is to obtain a third party perspective on cleanup progress and protectiveness.

Background

The five-year review guidance recommends that interviews be conducted to complement information obtained from the site inspection and other sources. Interviews should include the operation and maintenance (O&M) site manager, O&M staff, local regulatory authorities and response agencies, community action groups or associations, site neighbors, and other stakeholders. Interviews can be conducted over the telephone, face-to-face of via mail.

List of Interview Candidates

CH2M HILL proposes that the following individuals be interviewed:

- Corvallis Benton County Economic Development Partnership (Doug Sweetland). This
 organization's primary mission is to attract new business to the Corvallis and Benton
 County areas. I assisted them several years ago in describing potential long-term
 environmental affects associated with the United Chrome site. This information was
 used to address concerns raised by Federal Express when they were screening sites near
 the airport for a new shipping facility. This organization should provide a good
 perspective on the cleanup relative to the site's development potential. A telephone
 interview (telephone: 541-757-1507) is proposed.
- City of Corvallis Airport Manager (Buck Taylor). The Airport Manager is the primary
 custodian of the United Chrome property, and as such, can provide information on how
 the cleanup, when complete, will fit into the airport's long-term master plan. A
 telephone interview (telephone: 541-766-6783) is proposed.
- Benton County Environmental Health Department (Bill Emminger). This organization
 has overall responsibility for public health in the vicinity of the airport complex and
 rural areas of Benton County, and should provide a community perspective on cleanup
 protectiveness. A telephone interview (telephone: 541-766-6835) is proposed.
- City of Corvallis Public Works (Bruce Curtis). Although the City of Corvallis is the PRP and O&M operator, I believe Bruce will provide candid feedback on the remedial

CVO/INTERVIEW LIST.DOC 1 175923.04.01

design, its operation and effectiveness. Bruce has been involved with site operations since startup and has unique knowledge of the site. A face-to-face interview is proposed.

Local Residents. The nearest private residences are located approximately 1.5 miles
northeast of the United Chrome site, along Highway 99 and the streets (Corliss Avenue,
Meda Street and 3 Mile Avenue) extending off Highway 99. Because it's been a number
of years since the United Chrome site has received any media coverage, its unknown if
the nearby residents have any knowledge of the cleanup effort. If desired, CH2M HILL
will contact 3-5 residents in this area via a door-to-door survey.

A copy of the current United Chrome mailing list was also obtained from the City of Corvallis. A majority of the individuals on the list are either City of Corvallis employees, Council members or media representatives. Seven individuals with no known City of Corvallis affiliation appear on the list. These individuals and their last known address are shown in Table 1. If desired questionnaires can be mailed to these individuals.

7	Table 1		
List of Individuals on United Chrome Mailing List with No City of Corvallis or Media Affiliation			
Name	Address (all in Corvallis, Oregon)		
b) (6)			

Interview Questions

An interview questionnaire (see Attachment 1) will be used to guide each interview and the responses documented on the questionnaire form. The questions shown on the questionnaire were selected from samples provided in the five-year review guidance.

United (Chrome Five-Year Review Interview	v Record	
Site Name: United Chrome Products, 2000	Airport Rd. Corvallis, OR 97330	EPA ID No. C	DRD009043001
Interview Type: Telephone Visi	Other: Mail	Date:	Time:
Location of Visit:			
	Contact Made By		
Name: Scott McKinley	Title: Project Manager	Organization: Cl	H2M HILL
	Individual Contacted		
Name:	Title:	Organization:	
Telephone:	Address:		
	Summary of Conversation		
1) What is your overall impression	of the project?		
0. 717 . 4 . 1			
2) What affects have site operation	s (cleanup) had on the surrounding cor	nmunity?	
Are you aware of any communi	ty concerns regarding the site or its ope	eration? If so, ple	ease summarize vour
concerns.		, I	,
			;
4) Do you feet well informed abou	t the site's activities and progress?		
5) Do you have any comments, sup operation?	ggestions, or recommendations regardi	ng the site's man	nagement or
* * ***			
·			



December 16, 2002

175923.SV.01

CH2M HILL

2300 NW Walnut Blvd.

Corvallis, OR

97330-3538

Mailing address:

- J-PO2Box 428 J-2-2

Corvails; OH

97339-0428

Tel 541.752.4271

Fax 541.752.0276

Margaret Melvin 5311 SW Airport Pl. Corvallis, OR 97333

Subject: United Chrome Five-Year Review

Dear Ms. Melvin:

I am assisting the United States Environmental Protection Agency (EPA) in conducting a review to evaluate the protectiveness of groundwater and soil cleanup activities completed at the United Chrome Superfund site located near the Corvallis Airport. This is the third such review and follows others completed in 1993 and 1998.

alberger plane plane

"最高","我们,我们是不是,我的我们的,我们就是不是在我们的。"

An important element of the review process is to seek input from community representatives who have expressed a prior interest in cleanup activities at the site. Because your name appears on EPA's mailing list, I am contacting you to seek your feedback. Your participation is entirely voluntary and your name will not appear in any published document unless requested by you.

Attached for your consideration is a questionnaire and a recent fact sheet on United Chrome cleanup activities. Please feel free to respond to the questions provided on the questionnaire or to provide any other feedback. If you elect to participate, please return the questionnaire to me by January 3, 2003, using the enclosed stamped self-addressed envelope. If you would like to complete the interview over the telephone, please feel free to contact me at 758-0235 extension 3514.

Sincerely, CH2M HILL

Scott McKinley, P.E.

Enclosure

CVO\023500013

	United Chrome Five-Year Review Interview Record										
Site	Name: United Chrome Products, 2000	Airport Rd. Corvallis, OR 97330		EPA ID No. ORD009	043001						
Inte	rview Type: Telephone Visit	Other: Mail		Date:	Time:						
Loc	ation of Visit:										
		Contact Made By	·· <u>·</u>								
Nan	ne: Scott McKinley	Title: Project Manager	Or	ganization: CH2M H	ILL_						
		Individual Contacted									
Nan	ne:	Title:	Or	ganization:							
Tele	ephone:	Address:									
		Summary of Conversation									
1)	What is your overall impression	of the project?									
2)	What affects have site operations	s (cleanup) had on the surrounding cor	mmi	mity?							
-/	vitat anocis tave six operation	(cleanap) had on the ourrounding con	11111	anty.							
					•						
	•										
3)		y concerns regarding the site or its ope	eratio	on? If so, please su	mmarize your						
	concerns.										
	·	,									
					j						
4)	Do you feel well informed about	the site's activities and progress?									
	ı										
5)	Do you have any comments, sug	gestions, or recommendations regardi	ng tł	ne site's manageme	ent or						
	operation?										

SEPA

U.S. ENVIRONMENTAL PROTECTION AGENCY

November 2002

EPA To Review United Chrome Cleanup

During the next five months, the U.S. Environmental Protection Agency (EPA) will review the cleanup at the United Chrome Products, Inc. Superfund site. This review will make sure the cleanup is effective, and that people and the environment are protected as the cleanup continues. The review will also help EPA develop a transition plan for discontinuing EPA involvement after cleanup goals are met.

During the review, EPA will answer these kinds of questions:

- Are groundwater extraction, treatment and monitoring systems operating as planned?
- Is fencing at the site continuing to keep people from walking across the property so they are not exposed to contamination?
- · Do the cleanup goals still make sense?
- Is there new information that should cause EPA to rethink parts of the cleanup?

EPA's review will include inspecting the site, interviewing site contacts and reviewing technical data and documents, such as operation and maintenance reports.

Some of this work will be done by EPA's contractor, CH2M Hill.

The upcoming review is the third 'Five-Year Review' since the groundwater extraction and treatment system was installed in 1988. EPA will review the cleanup at United Chrome every five years until contamination levels are low enough to allow for unlimited and unrestricted use of the property.

EPA Welcomes Your Comments

EPA welcomes citizen participation and comments during the Five-Year Review process. If you would like to review draft reports, meet with EPA staff, or get involved in other ways, please contact the EPA staff listed at the end of this fact sheet.

In This Issue ...

EPA Welcomes Your Comments	1
Site Background	2
Cleanup Moves Forward	3
Do Cleanup Goals Still Make Sense?	3
Future Site Use	3
Site Contacts	3
Visit the EPA Website	3

United Chrome Products Site Background

The United Chrome site is a former chrome-plating facility three miles south of Corvallis in the Airport Industrial Research Park. The City of Corvallis owns the 1.5 acre site, but previously leased the property to United Chrome Products, Inc. The company did electroplating at the site from 1956 to 1985. During this time, plating tanks and a disposal pit leaked large amounts of hexavalent chromium to soll, and shallow and deep groundwater aquifers. In 1984, after determining the site posed a threat to human health and the environment, EPA placed the site on the National Priorities List, EPA's list of the nation's most contaminated sites.

In 1987, EPA began an extensive cleanup at the United Chrome site, including removing contaminated debris and hazardous soils, extracting and treating groundwater, and re-routing a drainage ditch to keep contaminated water from entering the local surface water drainage network.



Soll is excavated from the location of former plating tanks, September 18,2000.



Following removal of 1,956 tons of contaminated soil, the excavations are backfilled with dean soil, September 29, 2000.

In 1988, the City of Corvallis began managing cleanup activities at the site under legal agreements with EPA. In 2000, after further studies revealed two additional hot spots with high chromlum levels, the City removed 1,956 tons of soil and disposed of it at a permitted hazardous waste landfill. Since this removal, contamination levels in the upper aquifer have further declined.

In 1992, the U.S. District Court, EPA, the state of Oregon and the City of Corvallis signed a consent

decree which legally binds the City to perform cleanup actions and to continue extracting and treating groundwater until cleanup goals are met.

In addition to treating groundwater, the City is also evaluating off-site sediments in nearby. drainage ditches. The purpose of this evaluation is to make sure birds, fish and plants are not being harmed by contamination from the site. If the City finds that unacceptable risks exist, EPA may require additional cleanup actions.

Cleanup Moves Forward

"The City has done an excellent job managing the site," says EPA Project Manager Alan Goodman. "Cleanup goals will be met around 2004, if all goes as planned."

To date, the City of Corvallis has extracted about 32,000 pounds of chromium and 30.5 million gallons of contaminated groundwater from the shallow aquifer beneath the site. About 120 pounds of chromium and 47 million gallons of groundwater have been extracted from the deep aquifer. As a result, all but three of the 23 upper zone groundwater extraction wells have met cleanup goals, and all but two of the lower zone extraction wells have met cleanup goals.

Because so much of the cleanup has been completed, the City has decommissioned major portions of the groundwater treatment system. The on-site treatment plant has been removed and 39 extraction and monitoring wells have been decommissioned. The remaining portions of the groundwater extraction system are in good condition and have several years of serviceable life.

Do Cleanup Goals Still Make Sense?

Since EPA signed the cleanup plan, or Record of Decision (ROD), in 1986, many things have changed: the federal drinking water standard for chromium has changed from 0.05 parts per million (ppm) to 0.1 ppm; the site conditions and use have changed; and the Airport Industrial Research Park no longer relies on a private well, as public water and sewer were extended to the site in 1988.

Due to these and other changes, as part of the Five-Year Review, EPA will re-evaluate whether the cleanup plan and goals still make sense. EPA will focus on how and where groundwater cleanup goals need to be met, and whether cleanup goals should be changed. One issue up for discussion is whether to measure cleanup success using average, site-wide chromium concentrations or well-by-well concentrations. If major changes are needed, EPA will notify the public and take steps to revise the Record of Decision.

Future Site Use

The United Chrome site is included in the Corvallis Airport 20-Year Master Plan, and is zoned for general industrial use. Airport planners see the site as a prime location for additional fuel storage in the future. A propane storage and distribution terminal was recently constructed on the northeast portion of the site.

Site Contacts

Alan Goodman
EPA Project Manager
503 326-3685 or toll free at 800 424-4372
goodman.alan@epa.gov

Deborah Neal

EPA Community Involvement Goordinator
206 553-0115 or toll free at 800 424-4372
neal.deborah@epa.gov

Dan Hanthorn
City of Corvallis Project Manager
541.754-1757
dan:hanthorn@ci.corvallis.or.us

Visit the EPA Website:

EPA Region 10 website: www.epa.gov/r10earth/ click on "Index" click on "U" for United Chrome

For people with disabilities: Please contact
Deborah Neal at 1 800 424-4372, extension
0115 (voice), if you have any special requests
for reasonable accommodations. For TTY
users, please call the Federal Relay Service at
1 800 877-8339 and give the operator Deborah
Neal's phone number. Please provide one week
notice for special requests not related to ongoing
programs and services.

Attachment 4 - Summary of Significant Site Events

UNITED CHROME SITE CITY of CORVALLIS

CHANGES IMPACTING SITE SAFETY PLAN

WELLS/WELL FIELD

1990- installed infiltration trench NE of Basin #1(June)

1990- Contractor drilled deep wells, networked discharges from wells. No treatment; discharge direct to sewer after metering. Initially pumping 7 wells. Abandoned 2 wells.

Drilled

DW-8, DW-9, DW-10, DW-11, DW-12, DW-13, DW-14, DW-15,

DW-16, DW-17, DW-18, DW-19. DW-9 and DW-10 set up as

injection wells with City water.

Abandoned DW-4, DW-5

Overdrilled/reconstructed SE-2A

1994-Infiltration Basin #2 o/s. (April)

1996- Abandoned 7 upper zone monitoring wells and 1 deep aquifer monitoring well.

Abandoned EW-1, PL-2, PL-3, PL-4, PL-5, BG-2, MW-2A, DW-7. (June)

Converted DW-9, DW-10 to extraction wells; plumbed into deep aquifer network.

1997- Abandoned 9 upper zone monitoring wells.

Abandoned EW-19, EW-22, EW-24, EW-25, EW-26, SW-3, PZ-A, PZ-C, PZ-E (May)

1998- Abandoned 2 upper zone monitoring wells and 3 deep aquifer monitoring wells. Abandoned SW-2A, SW-4, DW-3A, DW-6, DW-19. (May)

2000- Abandoned 3 upper zone extraction wells as part of the contaminated soil removal project.

Abandoned EW-8, EW-28, EW-29.

Demolished concrete walls forming infiltration basins. Both basins o/s.

2001- Abandoned 3 upper zone extraction wells, 6 upper zone monitoring wells, and 4 deep aquifer monitoring wells.

Abandoned EW-17, EW-18, EW-21, EW-20, BG-1, MW-1, PL-1, PZ-D, PZ-F, DW-11, DW-14, DW-16, DW-17. (June)

2002-Modified wellfield for CoEnergy leasing portion of site

Lowered EW-16, DW-12, DW-13 well casings to below grade.

Removed EW-16, EW-23, DW-12, DW-13, DW-15 from pipe networks.

Modified fencing for access/security.

TREATMENT AREA

1989- installed larger air compressor and air dryer in a shed attached to the West end of the treatment building. Then the sludge press was doubled in size with longer rails and more plates. (December)

1990- installed sludge age tanks behind treatment building w/containment, access walkway, piping from treatment plant, to sludge press.(June)

1990- Started getting chemicals in totes, storing reserves in chemical storage building. Feeding sulfuric acid directly from tote; abandoned sulfuric acid day tank.

Pump and treat begins 1/9/92, as permitted by new local limits. By end of 1992, no sludge is being generated.

Person-down alarm (day)/treatment alarm (night) installed 3/2/1992. Modifies the buddy system.

Pump and discharge OK'd 2/28/1995. Used remaining chemical stocks, then pump and discharge implemented 3/2/1995. No treatment, no chemicals, storage tanks o/s.

GENERAL SITE

1988- Ditch sampling started (December). Requires 2 people.

1989-Bypass ditch dug around site by EPA contractor. (November)

1990- Installed catwalk over tank farm with fall protection on access ladder. (March)

1990-built locker/shower facilities. (May)

1990- built chemical storage building. (May)

1991-Ditch sampling discontinued (March)

1991-Removed yellow building (April)

1991-Removed green building (May)

1992- WWRP local limits revised, allowing 7 lb/day chromium allocation from United Chrome.

1992- drainage culvert cleaned out. Culvert plugged at each end to prevent recontamination.

1994- Storage tank catwalk removed, taken to WWRP. (February)

1995- Forklift no longer onsite. (November)

1999- Contractor removed unused equipment/buildings (March, April)

- -chemical building
- -storage tanks
- -treatment plant, sludge press
- -treatment building

2000- Soil removal project removed 1,956 tons of contaminated soil (>6000 mg/kg), transported to a Hazardous Waste landfill in Arlington, OR. Material removed from the site was replaced with concrete from infiltration basins and 1700 tons of clean fill compacted and leveled at grade. (September)

2003- Person-down alarm discontinued due to reduction in risks (January)

No treatment

No treatment chemicals onsite.

No ladders; fall risk greatly reduced.

Fall risk further reduced by a simpler well field; no infiltration basins, 40 fewer wells, and a simpler piping network.

PERSONNEL

A log of personnel with 40-hour hazardous material training and specific site training. Dates represent start of work/visits to the site and end of visits to the site for whatever reason.

NAME	BEGIN	END
Bruce Curtis	7/6/88	
Mike Clark	7/6/88	10/22/89
Dennis Pollock	7/6/88	12/91
Don Boone	7/6/88	12/96
Ed Sutton	7/22/88	2/28/91
Dan Hanthorn	3/89	
Kent Hansen	9/25/89	7/10/93
Mary Camarata	10/22/89	7/3/90
Guy Allen	10/22/89	

Appendix B Upper Zone Groundwater Pumping Data

523.5.97							Total Callora Crist Charles				
	70.00	headall S			evaër:	e Gallons + G Bumbed	Gallone I	Official and			
Aug-88		0	16	8	29	13390	15523	249	0		
Sep-88		0.73	30	15	159	75390	70044	924	0		
Oct-88	<u> </u>	0.14	31	15	97	64360	61353	773	0		
Nov-88		10.87	30	15	83.8	55050	62139 55560	800	0		
Dec-88 Jan-89		3.92 4.18	31 31	13 12	71.3 57.7	72370 59840	50112	755 464	0		
Feb-89		3.21	. 28	0	0	0	0	0	0		
Mar-89		6.8	31	13		92680	70390	761	0		
Apr-89		1.42	30	16	107	85020	73240	865	0		
May-89		1.46	31	18		88390	89750	1008	Ö		
Jun-89		1.14	30	.14	88.8	98547	74760	756	0		
	Upper	0.33 0.87	31 31	10 11	120.9 204	53490 135860	71940 116060	751 950	0		
Aug-89 Sep-89	Upper	0.87	30	9		64350	44580	269	0		
	Upper	2.66	31	27	618.8	264400	218480	1232	o		
Nov-89		3.9	30	28	651.7	271900	253880	1059	o		
Dec-89		3.07	31	30	613.1	344090	366210	1760	O		
Jan-90		9.5	31	29	519	385810	384350	1615	0		
	Upper	5.79	28			310720	302490	1229	0		
Mar-90	Upper	2.21	31	25	565.9	356980	357500	1210	0		
	Upper	2.38	30	30 30	716.1	423110	444720 427800	1137	0		
May-90	Upper	1.43 1.53	31 30	30		410730 461290	427800	893 739	0 0		
	Upper	0.45	31	31	707.7	582650	520650	978	0		
Aug-90		1.72	31	31	727.8		490740	722	o		
	Upper	0.83		30	<u> </u>	<u></u>	363840	520	0		
Oct-90	Upper	4.56		31	723.9	441690	454100	728	0		
	Upper	4.87	30	28			474330	717	0		
	Upper	3.59	31	19	1	350010	370540		0		
	Upper	2.68		20		345250	240340		0		
	Upper	3.22				560530	513290		<u> </u>		
	Upper Upper	5.85 3.47	31 30	31 30		550450 629160	537150 593740		0		
	Upper	3.91	31	29			573970		0		
	Upper	1.52					551960				
	Upper	0.38		31	740.3	488870	467360		o		
Aug-91	Upper	0.72		31	744	402660	384280		o		
	Upper	0.19				154090	126550	67	0		
	Upper	2.55	31	31			261310		0]		
	Upper Upper	5.12		1							
	Upper	4.38 4.52		30 31			502730 526120		0		
	Upper	4.54					445910		0		
	Upper	1.04							0		
Apr-92	Upper	1.52					471260	202	O		
May-92	Upper	0							0		
Jun-92	Upper	1.18					327000				
	Upper	1.18					340170				
	Upper Upper	0.44 0.55				304950	304950		0		
	Upper	3.52		30 31			307030 281410		0		
	Upper	4.99					300380	105	0		
	Upper	7.38					351950				
Jan-93	Upper	4.15	31	15		161140	161140		0		
	Upper	2.2	28	15	345.3	151960	151960	46	0		
	Upper	4.05					348790		0		
	Upper	5	30				370740		0		
May-93	Upper Upper	4.25	The state of the s	31	744.5 723.5		344880		0		
	Upper	1.25 1.25							0 0		
Juraa	inhhai	1.20			/30.3	292/80	∠a∠/80	46	<u>Uj</u>		

er Pumping Data

		्रहरूम् । शहरते । हिल्लाहा एउटा १००० । उट					
10	াগের সামান্ত্র	Tabedine e arecon a fac					
0			45820		and the second second second second		33.4
594			153090				113
115		·····	113660				53.6
00		· · · · · · · · · · · · · · · · · · ·	137550 125700			i	87.1 71.1
0		Non-control of the second seco	115210				70.1
0			0				70.1
0			145360			L	81
0		The same are a sum or a second control of the same of	148230	1131.00			75.9
384		The second secon	179630	1147.00			77.4
316			120660				65.2
700			88210				48.1
000			151690		College Street College Street College Street		74.1
200			52940		t		28.4
900			288480		<u> </u>		
100 575			290680 361330	500.00 576.00			
200			301330 400820	576.00	Loron		201.9 201.4
140			308220		<u> </u>		146.3
375		 	348760				161.4
300			430800				195.5
750			410410				183.6
506			459120				*********
364			563130	225.00	12.30		
328			487760	176.00	11.20	727.8	207.3
875		4	344250	171.00	8.70	694.9	132.5
015			425880	192,00	10.50	723.9	188.8
000			453610		San and the san areas and the san areas are		187.9
000			332840				116.7
775			371500				111
425			515700		<u> </u>	1	
925			511230 582830				
300			oo∠osu 561890	90.00	}		197 128.9
200 850			514190			1	
450			479630		<u> </u>		····
450			376060	the same of the sa	<u></u>	744	
375			141980			<u> </u>	
225			207900		5.84		
245		***************************************	302900	64.04	9.22	693.7	71
300			456610				
060			477810				
635	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		422420				94.2
350			481740	<u> </u>			
025		***************************************	439940 417100			<u> </u>	
925			346010				719.6
850 850		**************************************	340170			<u> </u>	746
1575			304950	<u> </u>			741
375	***************************************		307030				
150			281410	A			THE PERSON NAMED IN COLUMN 2 I
325			300380				
050			351950		<u> </u>		
100	OMBOL SOCIEMENTO FOR MOTOR SHOWS FORMED OF HER RE		161140		8.17	328.6	328.6
650			151960				
675			348790				
275	(24000000000000000000000000000000000000		370740	<u> </u>			
1975	A A A A A A A A A A A A A A A A A A A	(a	344880				
475			348740	*******************			
675			292780	19.00	6.63	736.3	736.3

	erio de Arresa.								
					76 TH	POLICE			
Aug-93 l	Zemerauca Japan	0.2	onlink Oi 31	31	747.4	276860	276860	42	0
Sep-93 (0.2	30	30	722.5	243360	243360		<u>-</u>
Oct-93 (0.7	31	31	740.4	235240	235240	X + > 7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	Ö
Nov-93 I		1	30	20	438.7	157630	157630	<u> </u>	Ŏ
Dec-93		6.1	31	31	735.6	323820	323820		ol ol
Jan-94		3.4	31	31	745.5	338480	338480		0
Feb-94	Upper	4.05	28	28	674.4	285940	285940	45	0
Mar-94		3.15	31	31	744.2	280780	280780		0
Apr-94		1.3	30	30	715.3	230970	230970		O)
May-94		0.7	31	28	668.5	159470	159470		0
Jun-94		0.7	30	25	583	130300	130300		0
Jul-94 (Upper	0	31	31	744.7	127300	127300		0
Aug-94		0	31	31	741.4	93670	93670		
Sep-94		0.65 6.65	30 31	30 31	720 745.2	75880 81840	75880 81840		
Oct-94 Nov-94		7,25	31	30	724.2	226850	226850		
D€C-94		5.9	31	31	738.3	258860	258860		<u> </u>
Jan-95		10.85	31	31	744.2	304840	304840		
Feb-95		2.9	28	20	459.4	175150	175150		Ö
Mar-95		5.05	31	31	761.7	250410	250410		
Apr-95		5.3	30	30	1	227090	227090		
May-95		1.43	31	31		217160	217160		O
Jun-95	Upper	2.36	30	28		163200	163200		O
Jul-95		0.52	31			150520	150520		0
Aug-95		0.82	31			105020	105020		0
Sep-95		3.14	30			81200	81200	A	
Oct-95		3,96	31			140100	140100		
Nov-95		7.72	30	<u></u>		176380	176380	Z.,	
Dec-95		10.12	31			254350	254350		
Jan-96 Feb-96		10.37 13.63	31 29			194400	194400		
Mar-96		3.54	31			145720 163380	145720 163380	<u> </u>	
Apr-96		4.93	30			138430	138430	Te - C - C - C - C - C - C - C - C - C -	Colored Control of the Control of th
May-96		3.98	31			129850	129850		
Jun-96		0.85	30			63990	63990	12	
Jul-96	Upper	0.92	31		 	87320	87320		
Aug-96		0.14	31	1	i	63700	63700		
Sep-96	Upper	2.22	30			58570	58570		
Oct-96	Upper	5.32	31			67690	67690	11	0
Nov-96		10.2	30			55640	55640	8	O
Dec-96		17.11	31	1		127730	127730		
Jan-97	Upper j	9.08	31	30	711.6	391820	391820		
Feb-97		2.2	28	28	676.5	-	336840		
Mar-97 Apr-97	upper	6.43 3.6	31	31	740	-	148960		
May-97	Upper	2.2	30 31	30 31	723 739.6	-	104450 95440		
Jun-97		2.42	30	30	718.7	-	95440 81800	3	
Jul-97		0.38	31	31	744.1	-	57760		
Aug-97 (Upper	1.25	31	31	742.4	ŀ	52080		
Sep-97		3.39	30	30	720.8	1	56080		
Oct-97	Upper	5.5	31	31	747.5	r	75100	13	
Nov-97 (Upper	5.18	30	30	720.1	ľ	93060	16	
Dec-97 l		3.02	31	31	742		111640	18	
Jan-98 (8.8	31	31	746		128590		
Feb-98 (8.35	28	28	671.7		135450		
Mar-98		×*************************************	31	31	745.3		134060		
Арг-98 (30	30	719.6	E	146430		
	CIPTEDE (•	31	31	744.6	į	97480	17	. 1
May-98 l Jun-98 l		0.75	30	30	720.4	ì-	61120		

ar Pumping Data

									2.03 A 5.25
	Francisco	er en e		e de la compa	ndorpulpulpulpulpul Produce Vision Leighi	6 616 ± 42	Estreblen.		Teambent.
303	grates in in	Piè (Family)			PERSONAL DEVE				
300		· · · · · · · · · · · · · · · · · · ·	**************************************	276860 243360		18.00 19.00		747.4 722.5	747.4 722.5
300	·····		<u>.</u>	235240		19.00	5.30	740.4	740.4
375				157630		19.00	5.99	438.7	438.7
0				323820		18.00	7.34	735.6	735.6
350				338480		20.00		745.5	745.5
250				285940		19.00	7.07	674.4	674.4
350) 300	······································			280780 230970		20.00 25.00	6.29 5.38	744.2 715.3	744.2 715.3
200		Marine C.		159470		26.00	3.98	668.5	668.5
300	YEST			130300		27.00	3.72	583	583
300	***************************************			127300		22.00	2.85	744.7	744.7
900				93670		26.00	2.11	741.4	741.4
900	****			75880		25.00	1.76	720	720
200 300			<u> </u>	81840 226850	·	23.00 23.00	1.83 5.22	745.2 724.2	745.2 724.2
500				258860		22.00	5.22 5.84	738.3	738.3
0		<u> </u>		304840		19.00	6.83	744.2	744.2
100				175150	1	18.00	6.35	459.4	459.4
200				8080		17.00	5.48	761.7	24
900	·			0		16.00	5.22	725	0
900	·*····			0		15.00	4.90	738.9	0
700 700	····			0		18.00 17.00	4.05 3.18	671.4 789.9	0 0 0 0
000	***************************************			. 0		17.00	2.33	750.6	
000	***************************************			0		17.00	1.89	717	0
400	***************************************		(0		19.00	3.16	738.9	0
400				0		19.00	4.06	723.6	0
625				0		15.00	5.72	740.8	0 0 0 0 0 0
0		· · · · · · · · · · · · · · · · · · ·	<u> </u>	0 0		17.00	4.35 4.63	744.7 524.8	
375				0		15.00 18.00	4.03 3.65	745.3	
800				0		17.00	3.21	717.9	
200				0		20.00	2.91	742.7	ol
600				0		23.00	2,46	433.9	0 0
900	**************************************	والمراجعة		0		21.50	1.95	748	O
300	~~,			0		20.50	1.43	742.7	0 0 0
200	·			0		22.50 19.50	1.35 1.52	721.4 743.3	
500				0		18.00	1.90	489	
0			1	ō		21.00			0
0	0				O	7.00			
670	30670				30670	3.20			
300	17300			 	17300	18.00			**********************
300	36300 41900		<u> </u>		36300 41900	20.00 18.00	«(::::::::::::::::::::::::::::::::	***************************************	
5900	41900 55900				55900	19.00			1
3400	68400				68400	18.00			
5500	75500				75500	16.00			
3200	63200				63200	16.00			
3200	43200				43200	20.00			
3800 4900	29800				29800 4800	20.00			
4800 0	4800 0				4800	19.00 16.00			
0	0	y aa	_	**************************************	0	17.00			
0	Ŏ		*		Ō	18.50			
0	O		1	The second secon	0	15.50			
0	0		1		0	20.50		-	
0	0		<u> </u>		0	18.00		***************************************	·
0	0		<u></u>	L,	0	18.00	жинкин М. СМС-ун _{ан} и-унции-инсин	······································	***************************************

1.555					e e e e e	N. Leones	Sugar.	Carrier S.	
						a significan	480jaja		
		isonal i				e CAN Date	Kranikate di. Evitante	ere like	
Aug-98	Unner		31	31	749.5	er en	21370	3	
Sep-98		0.6	30	30	593.2		8010	1	
Oct-98		1.35	31	31	744		14200	2	
Nov-98		13.4	30	30	719.7		68470	10	
Dec-98			31	31	455.8		83370	13	
Jan-99		9.2	31	31	742.8		96630	13	
Feb-99		12.5	28	28	673		108550	. 17	
Mar-99		4.4	31	31	745		87840	12	
Apr-99	Upper	0.5	30	30	713		56800	7	
May-99	Upper	2.05	31	31	743.3		45030	5	
Jun-99		0.55	30	30	717.6		38350	5	
Jul-99			31	31	745.6		47250	7	
Aug-99		0.85	31	31	745.9		55500	8	
Sep-99			30	30	723.8		44720	5	
Oct-99		2.5	31 30	31 30	742		51260 173170	5 18	
Nov-99		7.3	31	31	719.6 744.3		187820	16	
Dec-99 Jan-00		6	31	31	744.3		178570	13	
Feb-00		5.65	29	29	696.2		162360	14	-
Mar-00		2.75	31	31	740		142050	12	
Apr-00		1.55	30	30	718.4		92080	7	
May-00		1.95	31	31	747.3		91660	8	
Jun-00		0.7	30	30	719.5		62040	5	
Jul-00		0.1	31	31	740		62310	<u> </u>	
Aug-00		0	31	31	742.1		40660	4	7.4
Sep-00		0.85	30	7	152.4		5170	0	
Oct-00		2.7	31	0	0		0	0	
Nov-00		2.1	30	28	679.3		13594	2	6.6
Dec-00		4.75	31	24	585.1		25912	3	6.8
Jan-01	Upper	2.25	31 .	31	739.1		45178	6	
Feb-01		1.45	28	28	673.1		28593	3	6.5
Mar-01	Upper	2.75	31	31	740		28493	3	6.8
Apr-01		1.55	30	30	723		37905	. 5	7
May-01		0.95	31	31	739.7		59653	7	6.6
Jun-01		1.8	30	30	715.9		21360	3	
Jul-01		0.35	31	31	747.5		15790	2	7.1
Aug-01		0.8	31	31	741.9		37550	1	7.2
Sep-01		0.85	30	30	725		11520	1	7.3
Oct-01		2.85	31	31	741		13770	2	7
Nov-01	Upper	6.7	30	32	768.2		36970	5	
Dec-01		7.6	31	29	692.7		69550	4	
Jan-02		7.4	31	31	745.4		87640	10	
Feb-02 Mar-02		3.3 5.15	28 31	28 31	674.5		47590	5 3	
Apr-02		1.95	30	30	740.6 713.2		52000 39960		
May-02		1.15	31	31	713.2	,	33920	4	
Jun-02		0.55	30	30	719.8		29040	3	6.9
Jul-02		0.55	31	31	744.7		1080	0	
Aug-02		0	31	31	741.3	***************************************	1420	0	
Sep-02		0.95	30	30	723.9		60	0	
Oct-02		0.25	31	30	719.8		10	0	
Nov-02	Upper	4.3	30	31	740.5		1840	0	
Dec-02		13.25	31	31	744.6		24675	3	

r Pumping Data

							Shirles T. T.	
	AA				7) \$1.755	្ត្រី (ស្រី) ទីទី (ស្រី) (ស្រី)	3 5 5 - E	
			<mark>Mangapatan</mark> 272 ka					
0	0			0	14.50 15.50	A		
0	0			Ö	16.50			<u> </u>
0	o o			Ŏ	17.50		***************************************	1
0	0			O	19,00			
0	0		1	0	16.00			
0	0			0	19.00			**************************************
0	0			000	17.00		<u> </u>	
0	0			0	14.00 12.50		404440.44	Tanka ana ana ana ana ana ana
125	0	17325		17325	16.00			
ю0	132900	Ö		132900	18.00	***************************************		•
500	123500	0		123500	16.50			
900	141900	O.		141900	14.50			
125	130200	60225		190425	11.50			
75	82800	26775		109575	12.50		ļ	
0	<u> </u>	<u> </u>		0	10.00			
0	0	0 0		0	8.60 10.50			
0	0	<u>V</u>			10.50			
Ö	<u>0</u>	<u>o</u> l			8.50			
0	o o	Ŏ		Ŏ	11.00		1	<u> </u>
O.	o o	o o		0	10,50			
150	82200	58950	0	179210	11.00			O COMPOSITOR OF THE COMPOSITOR
0	o	o	O, i	181160	11.00			
0	0	0	0	260770	11.00			
0	0	0	O	0	0.00		<u> </u>	·
750	24750	0	0	24750	19.00		ļ	
300	27300	0		27300 188078	15.00 15.50		 	
0	0	0	0 0	291793	13.00		·	
0	0	0	0 :	346793	14.00			<u> </u>
0	0	Ŏ	Ŏ	359905	14.50			
ō	ō	Ö	o t	360753	13.50			
0	0	o	0	315660	15.00			
0	0	_0	0	290690	14.50	COLUMN TOWNS TO THE PARTY OF TH		
410	0	0	174410	321950	4.00			
570	0	0	100570	304720	14.50			<u> </u>
450	0	0	28450	189370	16.00		 	
0	0	0	<u> </u>	256870 318650	16.00 7,50	Į		
0	O[0	<u>0</u>	359940				
0	0	0		289390				<u> </u>
0		0	o	317100			1	
0	0	0	o i	260860	13.00			1
0	0	O)	0	263920				1
0	O	0	0	250040	13.50			<u> </u>
0	0	0	0	216680			ļ	<u></u>
0	0	0	0	210520			<u> </u>	<u> </u>
0	0	0	0 3	192760 187210	20.00 39.00		-	
0	0	<u> </u>	0	211540	39.00 16.00		<u> </u>	<u> </u>
0	0	0	0	246375	15.00		<u> </u>	

April Column Co			ORZS:	HWZ 80			EK XX		96 v 26 s 1	Tallia	EVANYAL		NE I	S V K ES			742/075	38/3/2/	
Color Colo	Aug-88	53	31	144	21	148	45	320	5220	6860	205	197	107	1050	1010	2750	3220	86	120
Prop. 19	Oct-88	60	290	500	230	600	370	700	9000	7000	500	500	510	500	4500	3050	3100	80	120
Table 18																			
May 10 15 16 16 17 17 18 18 19 18 18 18 18 18																			
March 1989 266 66 67 67 67 67 67 6		67.5	13	380	12	430	400	490	4200	6333	210	175	245	1034	0	2400	3200	32	34
The color 16																			
Color Colo	Jun-89	163	580	410	134	783	683	1117	3100	6333	217	380	425	900	4000	2150	2900	54	22
Sept										6500				580	5833		2900	36	33
	Sep-89		600																
Table Tabl	Nov-89	310	467	350	135	650	600	2550	1900	4833	3100	250	500	370	3900	3400	3500	36	33
Max																			
Color Colo																			
Dec 157 60 157 60 14 80 500 200 507 505 160 160 160 160 10	Apr-90	100	240	96	27.5	120	340	875	775	3800	210	60	330	360	2900	1700	1700	15.6	6.6
Autol 74 100 20 150 20 110 20 20 20 20 20																			
Section Tell 156	Jul-90	74																	
West Str. Print Sep-90	76	155	64	26	73	190	950	400	1175	720	52	155	260	3500	1150	1500	8	13.2	
Depth 19																			
Feb	Dec-90	57	97	42	20	48	220	380	383	360	163	39	320	350	1200	650	950	11.6	15
Aug-9 15.5 502 23 103 34 143 770 1510 330 105 311 150 130 410 400 700 6.4 4.4 Aug-9 17 94 17 15 10.5 30 100 6.8 770 77 17 17 24 155 117 390	Feb-91	33	123	33	23	41	165	165	450	425	125	35	150	350	480	860	760	8.4	8
May																			
Aug. 17 94 17 10 30 10 68 270 27 17 10 10 10 30 10 68 270 27 17 10 10 10 30 200 300 46 6 6 6 270 77 17 17 10 10 30 30 30 30 46 6 270 77 17 17 10 10 30 30 30 30 46 6 30 77 77 77 77 77 77 77	May-91	24	98	20	12.5	31	153	210	400	380	320	25	173	123	540	400	488	6	4.2
Sep-91 17 94 175 10.68 30 107 68 270 27.5 173 24 155 117 1904 500 300 2.4 3.5											173	24							6
Corp. 22 168 23 14 44 50 72 566 27.5 215 25 200 70 160 240 120 2.4 5.7																			2
Dec-6	Oct-91	22	108	23	14	44	90	72	260	27.5	215	25	200	70	180	240	120	2.4	3.7
Jame 18 70 20 10.8 40 110 55 250 27.5 120 23 65 78 150 170 220 22 5.3 160 251				23															
May 52 19 70 20 10.8 40 110 56 250 27.5 120 23 68 78 160 170 220 1.3 1								5 6										2.2	
May 92 13 56 13 4.7 27 73 36 190 27.5 76 15 76 66 60 120 110 1.3 0.6	Mar-92	19	70	20	10.8	40	110	56	250	27.5	120	23	65	78	160	170	220	1.3	1
Jun 98																			
Aug. Sc. 11 26 6.2 3.6 16 58 34 130 27.5 50 11 64 32 76 50 63 0.6 0.7								36			75	15	76			120	110	1.3	0.31
Oct 92	Aug-92	11	26	8.2	3.6	18	58	34	130	27.5	90	11	64	32	76	90	63	0.8	0.17
Nov-92																			
Jan											95				66	110	56	0.44	0.46
Mars 7.5 77 9.4 9.6 17 42 20 125 0.23 2.8 13 20 20 56 56 38 0.3 0.1 Mary 30 6.6 36 8 7.2 17 41 19 107 37 20 11 33 16 2.8 38 28 0.22 0.1 Jun 30 6.6 36 7.5 6.4 17 41 19 107 37 20 11 33 16 2.8 38 28 0.22 0.1 Jul 31 6.6 36 7.2 6.4 17 41 19 107 37 20 11 33 16 2.8 38 28 0.22 0.1 Jul 31 6.6 36 7.2 6.4 17 41 19 107 37 20 11 33 16 2.8 38 28 0.22 0.1 Jul 31 6.6 36 7.2 6.4 17 41 19 107 37 20 11 33 16 2.8 38 28 0.23 0.1 Aug 31 7.6 37 7.5 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 37 7.5 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 37 7.5 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 37 7.5 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 37 7.5 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 38 7.6 37 7.5 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 38 7.6 37 7.5 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 38 7.6 37 7.5 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 38 7.6 37 7.5 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 38 7.6 37 7.5 6.8 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 38 7.6 37 7.5 6.8 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Otto 38 7.5 7.	Jan-93	11	19	9.8	9.2	21	64	37	115	27.5	95	13	52	24	66	110	56	0.44	
Apr. 45 7.5 17 9.4 8 17 45 20 110 0.23 28 13 20 20 56 58 38 0.3 0.1															66 36				
Jun-93 6.6 36 7.5 6.4 17 41 19 107 37 20 11 33 16 28 88 78 0.23 01 Aug-93 7.6 37 7 7 7 6.4 11 19 107 37 20 11 33 16 28 88 78 0.23 01 Aug-93 7.6 37 7 7 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 0.1 0.1 0.1 0.1 0.1 0.1 0.1 0.1 0.1					. 8		45	20	110	0.23	28	13	20	20	36	56	38	0.3	0.1
Jul-93 6.6 36 7.2 6.4 17 41 19 107 37 20 11 33 16 28 38 26 023 01 Sep 39 7.6 37 7 6.4 18 36 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Sep 39 7.6 37 7 5 6.4 18 36 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Sep 39 7.6 37 5 8.8 6.4 18 36 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Nov. 30 7.6 37 8.8 6.4 18 36 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Nov. 30 7.6 37 8.8 6.4 18 36 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Nov. 30 7.6 37 8.8 6.4 18 36 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Nov. 30 7.6 37 8.8 6.4 18 36 17 87 41 29 7.6 39 11 49 29 18 0.15 0.1 Nov. 30 7.6 37 9.5 0.55 18 36 17 87 41 29 7.6 39 11 49 29 18 0.05 0.05 0.04 Jan-84 8.8 13 9.5 3.9 18 35 17 85 0.55 0.55 12 18 4 17 9.5 50 30 17 0.18 0.05 0.04 Jan-84 8.8 13 9.5 3.9 18 35 17 85 0.55 0.55 12 18 4 17 9.5 50 30 17 0.18 0.05 0.04 Jan-84 8.8 13 9.5 3.9 16 35 17 85 0.55 17 85 0.55 12 10 24 25 18 0.23 0.04 May 34 13 1.5 7.3 7.3 16 30 12 106 0.13 7 5.5 12 10 24 25 18 0.23 0.04 May 34 3 1.5 7.3 7.3 16 30 12 106 0.13 7 5.5 12 10 24 25 18 0.23 0.04 May 34 3 1.5 7.3 7.3 16 30 12 106 0.13 7 9.6 12 10 24 25 18 0.23 0.04 May 35 12 1.5 10 10 24 25 18 0.23 0.04 May 35 12 12 12 12 12 12 12 12 12 12 12 12 12	Jun-93	6.6	36	7.5	. 6.4	17	41	19		37					28		26		
Sep-93 7.6 37 7.5 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.18 0.11 Cob-93 7.6 37 8.8 6.4 18 38 17 87 41 29 7.6 39 11 49 29 18 0.16 0.11 Nov-93 7.6 37 8.9 5.0 35 18 38 17 87 41 29 7.6 39 11 49 29 18 0.06 0.04 Jan-94 8.8 13 9.5 3.9 18 35 17 85 0.34 21 8.4 17 9.5 50 30 17 0.18 Jan-94 8.8 13 9.5 3.9 18 35 17 85 0.34 21 8.4 17 9.5 50 30 17 0.18 Jan-94 5.3 13.5 7.3 7.3 16 30 12 108 0.13 7 5.5 12 10 24 25 18 0.23 0.04 May-94 5.3 13.5 7.3 7.3 16 30 12 108 0.13 7 5.5 12 10 24 25 18 0.23 0.04 May-94 3.6 13.5 7.3 7.3 16 30 12 106 0.13 7 5.5 12 10 24 25 18 0.23 0.04 May-94 3.8 17 6.4 4 31 32 14 78 36 19 7.3 32 5 38 21 12 0.13 0.02 Jun-94 3.8 17 6.4 4 31 33 14 75 36 19 7.3 32 5 38 21 12 0.13 0.02 Jun-94 3.8 17 6.4 4 31 33 14 75 36 19 7.3 32 5 38 21 12 0.13 0.02 Jun-94 3.8 17 6.4 4 31 33 14 75 36 19 7.3 32 5 38 21 12 0.13 0.02 Jun-94 3.8 17 6.4 4 31 33 14 75 36 19 7.3 32 5 38 21 12 0.13 0.02 Jun-94 3.8 17 6.4 4 31 33 14 75 36 19 7.3 32 5 38 21 12 0.13 0.02 Jun-94 3.8 17 6.4 4 31 33 14 75 36 19 7.3 32 5 38 21 12 0.13 0.02 Jun-94 3.8 17 6.4 4 31 33 14 75 36 19 7.3 32 5 38 21 12 0.13 0.02 Jun-94 3.8 17 6.4 4 31 33 14 75 36 19 7.3 32 5 38 21 12 0.13 0.02 Jun-94 3.8 17 6.4 4 31 33 14 75 36 19 7.5 36 19 7.3 32 5 38 21 12 0.13 0.02 Jun-94 3.8 3.7 3.7 3.7 3.7 3.7 3.7 3.7 3.7 3.7 3.7 3.7 3.7															28 40	38	26		
Nov-93	Sep-93	7.6			6.4	18	38	17	87	41	29	7.6	39	11	49	29	18	0.15	0.1
Dec-93 8.8 13 9.5 3.9 18 35 17 85 0.34 21 8.4 17 9.5 50 30 17 0.18 0.04 Feb-94 5.3 13.5 7.3 7.3 16 30 12 108 0.13 7 5.5 12 10 24 25 18 0.23 0.04 Apr-94 3.6 13.5 7.3 7.3 16 30 12 108 0.13 7 5.5 12 10 24 25 18 0.23 0.04 Apr-94 3.6 13.5 7.3 7.3 16 30 12 108 0.13 7 5.5 12 10 24 25 18 0.23 0.04 Apr-94 3.6 13.5 7.3 7.3 16 30 12 108 0.13 7 5.5 12 10 24 25 18 0.23 0.04 Apr-94 3.6 13.5 7.3 7.3 16 30 12 108 0.13 7 9.6 12 10 24 25 18 0.23 0.04 Apr-94 3.6 17 6.4 4 31 32 14 78 36 19 7.5 32 5 38 21 12 0.13 0.02 Jul-94 3.6 17 6.4 4 31 33 14 75 36 19 7.5 32 5 38 21 12 0.13 0.02 Aug-94 3.8 17 6.4 4 31 33 14 75 36 19 7.3 32 5 38 21 12 0.13 0.02 Aug-94 3.8 12 6.6 4.8 33 33 16 65 12 27 5.6 27 0.9 60 22 4 0.13 0.01 Oct-94 6 12 6.5 4.8 33 33 16 65 12 27 5.6 27 0.9 60 22 4 0.13 0.01 Oct-94 5.4 1.1 7.8 1.2 26 28 18 65 0.26 20 5.6 14 3 52 24 11.5 0.13 0.01 Oct-94 5.4 1.1 7.8 1.2 26 28 18 65 0.26 20 5.6 14 3 52 24 11.5 0.13 0.01 Oct-94 5.4 5.1 7.7 5 1.2 26 28 18 65 0.26 20 5.6 14 3 52 24 11.5 0.13 0.01 Oct-94 5.4 5.1 7.7 5 1.2 26 27 11 60 0 0 0 0 0 0 0 0	Nov-93	7.6	37	9.5		18													
Feb-94 5.3 13.6 7.3 7.3 16 30 12 108 0.13 7 5.5 12 10 24 25 18 0.23 0.04																30	17		0.04
Apr.94 3.6 13.5 7.3 7.3 16 30 12 108 0.13 7 9.6 12 10 24 25 18 0.23 0.04	Feb-94	5.3	13.5	7.3	7.3	16	30	12	108	0.13	7	5.5	12	10	24	25	18	0.23	0.04
May-94 3.8 17 6.4 4 31 32 14 78 36 19 7.5 32 5 38 21 12 0.13 0.02 Jul-94 3.6 17 6.4 4 31 33 14 76 36 19 7.3 32 5 38 21 12 0.13 0.02 Jul-94 3.8 17 6.4 4 31 33 14 76 36 19 6.2 32 5 38 21 12 0.13 0.02 Aug-94 3.8 12 6.5 4.8 33 33 16 65 12 27 5.6 27 0.9 60 22 4 0.13 0.01 Sep-94 5.2 12 6.5 4.8 33 33 16 65 12 27 5.6 27 0.9 60 22 4 0.13 0.01 Ccl-94 6 12 6.5 4.8 33 33 16 65 12 27 4.8 27 1.3 60 22 4 0.13 0.01 Nor-94 5.4 1.1 7.8 1.2 26 29 18 65 0.26 20 5.6 14 3 52 24 11.5 0.13 0.03 Dec-94 4.8 1.1 7.8 1.2 26 29 18 65 0.26 20 5.6 14 3 52 24 11.5 0.13 0.03 Jan-95 4.6 0 0 0 23.5 24.5 14.5 60 0 0 5 0 2.5 0 0 0 0 0 0	Apr-94	3.6	13.5	7.3	7.3	16	30	12	108	0.13	7	9.6	12		24		18		
Jul-94 3.8 17 6.4 4 37 33 14 75 36 19 6.2 32 5 38 211 12 0.13 0.02 Aug-94 3.8 12 6.5 4.8 33 33 16 65 12 27 5.6 27 0.9 60 22 4 0.13 0.01 Oct-94 6 12 6.5 4.8 33 33 16 65 12 27 4.8 27 1.3 60 22 4 0.13 0.01 Nov-94 5.4 1.1 7.8 1.2 26 29 18 65 0.26 20 5.6 14 3 52 24 11.5 0.13 0.01 Dec-94 4.8 1.1 7.8 1.2 26 29 18 65 0.26 20 5.2 14 2.4 62 24 11.5 0.13 0.03 Dec-94 4.8 1.1 7.8 1.2 26 29 18 65 0.26 20 5.2 14 2.4 62 24 11.5 0.13 0.03 Jan-95 4.6 0 0 0 0 23.5 24.5 14.5 60 0 0 5 0 2.5 0 0 0 0 0 May-95 0 0 0 0 0 20.7 20.7 11 55 7 16 4.8 11 2.4 48 15 6 0 0 May-95 0 0 0 0 0 20.7 20.7 11 55 0 0 0 0 0 0 0 0																21	12	0.13	0.02
Sep-94 5.2 12 6.5 4.8 33 33 16 65 12 27 5 27 0.9 60 22 4 0.13 0.01	Jul-94	3.8		6.4	4	31	33	14	75	36	19	6.2	32	5	38	21	12	0.13	0.02
Oct-94	Sep-94	5.2	12	6.5	4.8	33	33	16	65	12	27	5	27	0.9	60	22		0.13	0.01
Dec-94																			0.01
Feb-95	Dec-94	4.8	1.1	7.8	1.2	26	29	18	65	0.26	20	5.2	14	2.4	52	24	11.5	0.1	0.01
May-95	Feb-95	5	11	6.8	0.9	21	20												
May-95 3.4 14 6.4 1.6 20 22 11 70 0 14 5.6 14 22 40 12 4 0 0 Jun-95 0 0 0 0 0 0 0 0 0																	0		O}
Jul-95 O O O O O O O O O	May-95	3.4	14	6.4	1_6	20	22	11	70	0	14	5.6	14	2.2	40	12	4	0	0
Sep-95 0 0 0 0 0 0 0 0 0	Jul-95	Ö	0	0		0	0												
Oct-95 O <td></td> <td></td> <td></td> <td></td> <td>0</td> <td></td> <td></td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>O O</td> <td>0</td> <td>0</td> <td>O O</td>					0			0	0	0	0	0	0	0	0	O O	0	0	O O
Dec-95 0 0 0 0 0 0 0 0 0	Oct-95	0	0	0	. 0	0	_0	0	0	0	0	0	0	Ö	0	0	O	0	0
Nov-96 14.5 64 17 2.1 4.2 0.2 Nov-96	Dec-95																		
Dec-96 2.1 4.6 0.17																			
May-97	Dec-96													2.1			4.6	0.17	
Jun-97 1.8 3.6 0.18 Jul-97 22 21																			
	Jun-97									J.,/			3.3	1.8			3.6	0.18	
						17	13	3.4	48	25		-	6.6			6			

and a green way was	erote with the s		No. of the last of		o grafika samanga p						entry (Englant)	NO PERSONAL PROPERTY OF THE PERSON PROPERTY O		Annango granda marte de Mareiro.	
318	163	92.2	706	4310	CALUERY CARGO	- MAG		denote: Consulo		Carlot Marie	Aldi Gazar A				
2050;	170	850	1400	3700						A - 71, Education - 7					
2050 850	170 180	1400	1900	4300						*******		***********			
700	60	2000	1000	2100							,				
657) , 657	. 67 67	1750 1750	1567 1567	1.850 1.850							1				<u> </u>
640	96	1350	1300				***************************************								
563	108	1320	1325				·								**************************************
488 513	97 83			1700 1300	· ·X'''''''''' MARINING	·	··········			·			Ĺ——		
525	64	1467	693	1100		*************									haddaningshaushaushar vir ussuannessyir ar vir sannessnessannessy
563 563	52 52	840 840	525	760							L				······································
550	160	450		760 363			···				-				
550	160 160 33.3	340	290	390											
476 390	33.3 17	190 153									-				
150	10.8	180	105	145				-							
123 80	6.5	206	117	165								***			
45	7.4 5.1	72	68	83 60								**********			
45	5.1	72	68	60											
48 45	3.2	70 64	42 43							ļ		-	ļ.,		
47.5	3,1	76	42	66											
51	3.3	56	66	66											
38 41	2.7	42	44 42	52 48					· · · · · · · · · · · · · · · · · · ·						
33	2.4	40	35	51											
24 18	2.4 1.5	43 33	48	54						ļ					
15	1.5	29	363 36	36				, , , , , , , , , , , , , , , , , , ,		-					
15	1.1	23	31	45			,,								
11.5	0.9 1.3	24 94	40 46	36 34	<u> </u>					 				***************************************	**************************************
11.5	1.8	24	40	34											h////annyann.anns.46.775
11.5 13.5	1.8 4.1	24	40								ļ				****
13.5	0.7	32 32 32 23 23	37.5 37.5	27.5					··		<u> </u>	***************************************			······································
13.5	0.2	32	37.5 43	27.5	<u> </u>										
5.6 4.6	0.9 0.7	23	43 43	52 52	ļ			ļ		<u> </u>	<u> </u>				
3.6	0.9	23	43	52	,							***************************************		····	
23 8.9	1.2	13.5	26	23											
0.95	0.7 0.7	13.5 13.5	25 25 20	23 23						<u> </u>	<u> </u>	**************************************			
0.95 1.2 1.3	1.5	13	20	15											
1.3 1.5	1.5 1.5	13 13	20 20					<u> </u>			ļ	455K g			
1.7	0.1	14	23	16								47, 41.			***************************************
1.8	0.1		23	16								**********			` <u>`</u>
1.6) 0.9;	0.1 0.1	14	29 23	16 16				<u> </u>	<u> </u>	ļ	ļ <u>.</u>		 		
0.9	0.1	14	23	16				mark netsets.							
0.9	0.1 0.1	11.5 11.5	24 24	19.5 19.6					 	 	<u> </u>		 		***************************************
0.6	0.1		21	17.5											***************************************
0.19	0.1	10.5	21	17.5								ļ	ļ		
0.19	0.1 0.1			17.5 12				 		 	1		 	<u></u>	
0.1	0.1	9	19	12											
0.12	0.1 0.01		19	12 12				· · ·	 	·	<u> </u>		}		
0.12	0.01	10	17	15				<u> </u>	<u> </u>			CEN		***************************************	
0.12	0,01	10	17					<u> </u>	 	ļ	ļ			<u> </u>	<u> </u>
0.3 0.3	0.03 0.03				<u> </u>				<u> </u>	<u> </u>			-		
0.3	0.03	17	27						1		-	ļ		<u> </u>	
0.06	0.03							 	1	<u> </u>	<u> </u>	<u> </u>		<u> </u>	
0.09	0.02	. 8	10	12	1			ļ <u> </u>	Ţ	Ţ <u> </u>	Ţ <u>.</u>				
0.07	0.02			8.5 8.5		·	<u> </u>	<u> </u>	-	 	 	t	 -	<u> </u>	<u> </u>
0.07	0.02		. 9	6.5				}	1	1		<u> </u>	1		
0.16 0.07	0.02			8.5 8.6					1	-	 	ļ	 		<u></u>
0.07	0.19	2.5			1		}	<u> </u>	·	<u> </u>	1		1		****
0.49	0 0 0	1.8	15	9		*****				<u> </u>		ļ			
0	0	2.2) O	0	.		ļ	<u></u>	<u> </u>		-	**************************************	 	1	**************************************
0.05	0 0 0		19	11				<u> </u>							**************************************
0	0		i, 0	0	•							ļ.,		<u></u>	<u> </u>
0	0 0 0				i.	<u> </u>	 	 	 -	-	 	 	 		
O.	ŏ) O	0									T		
<u> </u>	, o		Y O	G					1	-	ļ	<u> </u>	<u> </u>		
0	0			0		 -		 	-			1	 		1
ļ		I			0.01	0.02		1			0.02		ļ		<u> </u>
ļ		-	17	11	0.01	0.01			 		0.05	, 1	ļ		
<u> </u>		}	20	14.5		V.V.							<u> </u>		
			18	12.5	1		Ļ						ļ		
		t Š	 	<u> </u>	0.02	0.01		 	1	·	0.04	T	<u> </u>	;	
		<u> </u>	17	10			<u> </u>	A ST.	1		j	!		<u> </u>	<u> </u>

MINE COLUMN	ASTRONOMIC	3) 20/20			建造层层	23 A C	48,4572	SAMOSE	#57#45M		ANADE H	WAL THE		SANY	(5)/7(VE)		54 72 Pr \$ 1	BANGE PAR
Sep-97	1.									34				20				
Oct-97										19				10	1			
Nov-97					12	15	4,5	50	20	13		4.5		3.5	4		L	
Dec-97										7.5			2	1.5	- 1	3.2	0.26	1
Jan-98								1		6.5				5				
Feb-98				1	15	11	2.6	52	11	3.2		2.2		19	. 9			
Mar-98					-			-	1	2				14				
Apr-98										2.4	1			9				
May-98		1			17	9.5	1.6	60	18.5	1.9		3.2		8	10.8			
Jun-98								1	-	1.1	7		2.2	4.2		4.4	0.32	
Jul-98						8	 †	54	40	2				7				
Aug-98					35		1,6			2.8		4		8.4	8.6			
Sep-98					- 30		1.0			3.6				10	0.0		-	
	+									4				11.5		-		
Oct-98						8			32			4.6					 -	
Nov-98					36	- 8	1.8	58				4.6		12.5	8.5			
Dec-98										0.6			1.8	2		0.03	0.21	
Jan-99										0.6				0.43			<u>-</u> -	
Feb-99					19	6	1.7	68	0.09	0.8		1.6		2	7.5			
Mar-99								i		0.2				0.4				
Apr-99	L								1	0.5				3				
May-99					19	6.5	1.4	60	35	0.04		2.7	1	0.06	10			
Jun-99				j			1	-	}	0.7			1.8	2		2	0.24	
Jul-99		4	6		19			4		1.7				4.1				-
Aug-99					13.5	12.5	1.9	56	29	2.5		5	1	6	9.4			
Sep-99					i					3.4	1		1	5.8				
Oct-99		11	20		1			1	_	4.7				6.8				1
Nov-99		1.6	20		9	15		50	54	4.6				7.6				
Dec-99		0.37	10.5				3.6	1		0.52		1.8	1.9	0.35	5.2	2.8	0.47	
Jul-00	2.5	4.6	8.6	0.04	9	5.5	1.5	44	34	1.4	0.6	2.3	2	6.2	11.5	2.6	0.33	0.09
Aug-00	2.5	6	10	0.04	12		1.8	40	62	2	0.6	3.4	2	7.8	10.4	2.6	0.33	0.09
Sep-00	2.5	6	10	0.1	12		1.8	40	62	2	0.6	3.4	2	7.8	10.4	2.6	0.33	0.09
Oct-00	2.5	6	10	0.04	12				62	<u>2</u>	0.6	3.4		7.8	10.4	2.6	0.33	0.09
Nov-00	3	6	10	0.1	13	7	1.8		31	1.8	0.6	3.4	2	7.3	10.4	2.6	0.33	0.09
Dec-00	3	6	10	0.1	13		1.8		31	1.8	0.6	3.4	2	7.3	10.4	2.6	0.33	0.09
Jan-01	2.5	1.3	5	0.15	11		1.6		30	0.6	1.2	2.8	2.1	2.8	6	- 20	0.33	0.08
Feb-01	2.5	1.3	5	0.15	11	4.75	1.6		60	0.6	1.2	2.8	2.1	2.8	6	3	0.29	0.08
Mar-01	2.5	1.3	5	0.15	9		1.6		22	0.6	1.2	2.8	2.1					0.08
Apr-01	2.5	1.3	- 5	0.15	11.5		1.6		50	0.6	1.2	2.8	2.1	2.8	6	3	0.29	
					12.5									2.8	- 6	3.4	0.39	0.08
May-01	2.5	1.3	5	0.15		4	1.7		32	0.25	1.2	5.9	2.1	0.85	7.6	3.4	0.39	0.08
Jun-01	2.8	1.3	5	0.18	12.5	3.5	1.4		44	0.41	1.2	5.4	2.1	1.8	10.5	3.8	0.39	0.08
Jul-01	2.8	1.3	5	0.18	12.5	3.5	1.4		48	0.41	1.2	5.4	2.1	1.8	12.5	3.8	0.39	0.08
Aug-01	2.8	1.3	5	0.18	12	. 3	2.2		0.02	0.5	1.2	3.8	2.1	0.05	14	3.8	0.39	0.08
Sep-01	2.8	1.3	5	0.18	12		2.2		20	0.5	1.2	3.8	2.1	0.05	15	3.8	0.39	0.08
Oct-01	2.8	1.3	5	0.18	12		2.2		20	0.5	1.2	3.8	2.1	0.05	17	3.8	0.39	0.08
Nov-01	2.8	1.3	5	0.18	12				17	0.75	1.2	2.9	2.1	0.59	18.5	3.8	0.39	0.08
Dec-01	3	1.4	3	0.09	11.5				0.7	0.15	1.4	1.3	1.6	0.4	9.5	2.2		
Jan-02	3	1.4	3	0.09	11.5	3.5			21	0.15	1.4	1.3	1.6	0.4	14	2.2		
Feb-02	3	1.4	3	, 0.09	11	5			17	0.45	1.4	4.1	1.6	2.3	12	2.2		
Mar-02	3	1.4	3	0.09	11.5	5		•	0.8	0.45	1.4	4.1	1.6	2.3	11.5	2.2		
Apr-02	3	1.4	3	0.09	11	5			19.5	0.45	1.4	4.1	1.6	2.3	12.5	2.2		
May-02	3	1.4	3	0.09	11	3.8			26	0.4	1.4	5	1.6	2.5	13	2.2		
	2.7	2.1	3.5	0.25	12		2.3		19.5	0.34	0.95	5.3	1.7	1.5	13	0.02	 +	
JUD-UZ:			3.5	0.25	11.5	4.4	2.3		16	0.34	0.95	5.3	1.7		13.5	0.02		
Jun-02 Jul-02														1.5				
Jul-02	2.7	2.1		0.25	12	A 4	22	1										
Jul-02 Aug-02	2.7 2.7	2.1	3.5	0.25	12 10.5		2.7		20.5	0.46	0.95	5.5	1.7	1.5	10	0.02		
Jul-02 Aug-02 Sep-02	2.7 2.7 2.7	2.1 2.1	3.5 3.5	0.25	10.5	4.4	2.7		20	0.46	0.95	5.5	1.7	1.5	. 8	0.02		
Jul-02 Aug-02 Sep-02 Oct-02	2.7 2.7 2.7 2.7	2.1 2.1 2.1	3.5 3.5 3.5	0.25 0.25	10.5 10	4.4 4.4	2.7 2.7		20 39	0.46 0.46	0.95 0.95	5.5 5.5	1.7	1.5 1.5	8 5	0.02 0.02		
Jul-02 Aug-02 Sep-02	2.7 2.7 2.7	2.1 2.1	3.5 3.5	0.25	10.5	4.4	2.7		20	0.46	0.95	5.5	1.7	1.5	. 8	0.02		

						*				,					
			FW 287-4		WILEDIA	700	有品质企業的				A Copyright	TX OF THE	- 16 727	er i de la completa d	STANDARD STANDARD
			17)		0.51										
					0.01	0.02				3	0.05				
			18	10			<u> </u>					ļ			
		<u>_</u>	1435	10			<u></u>		L	<u> </u>		ļ			
														······································	
			19	12											
	j		19		0.01	0.01				L	2.54	L			
······································	——— <u> </u>		18	13	0.01	0.011					0.04	<u> </u>		44.400	
			10	10				<u> </u>				 _			
				**************************************						<u> </u>		<u> </u>			
												<u> </u>			<u> </u>
			22	416			ļ ,			<u> </u>			,		
	·····			14.5	73.02		***************************************	·				<u> </u>			
					0.61	0,01	**************************************	~			0.04				
								·							
			20.5	12	L					<u>_</u>					
												<u> </u>		Participation	
								•							
			19	13		 -				,.,,					
					0.01	0.01					0,04	 			
			13.5	5.5					***************************************			L			
			12	6						i					
					0.01	0.14					0.05				
0.6	0.03	0.42	16.5												
0.6 0.6 0.6	0.03	0.42	/3 15	9.5			}			/				11	
0.6	9.03 0.03	0.42 0.42	15	9.5			0.04		1.5					11	
0.6	0.03	0,42								i i					
0.6	0.03	0.5 0.5												19	
0.6	0.03	0.5												15	
0.32	0.31 9.31	0.43 0.43			0.01	0.02	0.01	0.56	1.1		0.05			15.5	
0.6 0.6 0.32 0.32	9.31	0.43												13	
0.32 0.31	0.91	0.43													
0.31	0.31	0.47					0.01	400		0.19	0.03		14.5		
0.91	0.31	0.47	ł		0.01			0.47					13.5		
0.31	0.1	0.54 0.54				0.03			0.44			5.3	15		
0.31	0.1	0.54											14.5		****
0.31	0.1	0.54											4		
0.31	0.1	0.54											14.5		
0.31	0.1	0.54											16		
0.31	0.1	0.54											16		
	D.01	0.72				0.02			0.6			8 !	7.5		
	0.01	0.72												19.5	
	0.01	0.72								1				13	
	0.01	0.72 0.72 0.72												7.5 13	
	0.01	0.72	1									<u> </u>		13	
	0.01	0.72												14	
	0.01	0.6 0.6				0.02		***************************************	1.1			3.3		13.5	
	0.01	0.6	***************************************						- Committee					16	16
1	0.01	0.6	****				-			1				20.5	20.5
~	0.01	0,6				-			,	,	***************************************	ļ		20 39 16	16 20.5 20 39 16 15
	0.01	0.6								***************************************		Ţ		39	39
1	0.01	0.6										7		16	16
	0.01	0.56	<u> </u>					le				1		15	15
										L.,				The William Property of the Control	

Appendix C – Deep Aquifer Pumping Data

a Alexandra								
		New Joseph Conduction				Jeral≅ Erolalis Gallons [‡] Calkors. Sanciped Ektracter		
	And to the same			Operation		s aborded laskiracier		
May-90	Deep	1.43	31	30			0	O
Jun-90		1.53	30	30			0 } j	0
Jul-90		0.45	31	31		1178		<u> </u>
Aug-90		1.72	31	31		4830		0
Sep-90		0.83	30	30			O j	0
Oct-90		4.56	31	31			0	0
Nov-90		4.87	30			remeters and the second	0	0
Dec-90		3.59 2.68	3 1 31	19 20	and the confession of the second	kanaga itt var om sengs mes inne men melle grande francesser men senger av s	0	0
Jan-91 Feb-91		3.22		∠0 28			0	O O
Mar-91		5.85	<u>∠o</u> 31	20 31	and Water annual Contract of the Contract of t	CALL TO THE OWNER OF THE OWNER OWNER OF THE OWNER OWNE	0 <u>.</u>	
Apr-91		3.47	30		C		0	0
May-91		3.91	31	29			0	0
Jun-91		1.52	30				ŏ	ŏ
Jul-91		0.38	31	31		3650	<u>-,</u>	Ŏ
Aug-91		0.72	31	31	745.8		Arra Commission McMM conservation and arrange	
Sep-91		0.19	30		717.2			
Oct-91		2.55	31	31	740		The state of the s	The second secon
Nov-91		5.12	30	30	719.2	68667	9.28	0
Dec-91	Deep	4.38	31	30	740.1	70738	0 5.11	0
Jan-92		4.52	31	31	742	I		
Feb-92		4.54	29		690.3			
Mar-92		1.04	31		743.6	<u> </u>		
Apr-92		1.52	30		718.6	in the second	maga haran wang managan baran	
May-92		0	31		745.4	2	A. A	
Jun-92		1.18	30		722.5			
Jul-92		1.18	31		746.5			The second secon
Aug-92 Sep-92		0.44 0.55	31 30	Acres (1803) annual ann	737.3 717.8	Branch and the best of the second control of the second control of the second control of the second control of		l o
Sep-92 Oct-92		3.52	31		717.0	dennant programmer of the second of the seco		
Nov-92		4.99	30	£	744.1			Contract of the contract of th
Dec-92		7.38	31		744.1			
Jan-98		4.15	31					
Feb-93	THE REAL PROPERTY AND PERSONS ASSESSED.	2.2	28	Accessed the second sec		Commander	a de la composición del composición de la composición de la composición de la composición del composición de la composición del composición de la composición de la composición de la composición de la composición del composición de la composición de la composición del composición de la composición de la composición d	Amany Surphesential Control of the Participation
Mar-93		4.05	31		742.7			<u> </u>
Apr-93		5	30	The second second second second	717.3	The same of the sa	The state of the s	0
May-93		4.25	31	31	744.4	74040	0 1.11	o
Jun-93	Deep	1.25	30	30	723.1		0 1.05	O
Jul-93		1.25	31		736.1			
Aug-93		0.2	31					0
Sep-93		0	30					
Oct-93		0.7	31					
Nov-93		1	30				The same of the sa	
Dec-93		6.1	31					
Jan-94		3.4						0
Feb-94 Mar-94		4.05 3.15	28 31					
Apr-94		1.3	30					
May-94		0.7	31					
Jun-94		0.7	30					
Jul-94		0	31				the state of the same of the s	I
Aug-94		i o			THE PARTY OF THE P			
Sep-94		0.65	30			·		
Oct-94	The state of the same of the same of	6.65	Account of the Commercial Commerc	Carlo	The second second second second second		Charles and the contract of th	
	Deep	7.25						

ater Pumping Data

2.00	Section 2		12.8500003 <i>0</i> .994		CONTRACTOR DE			ne sana	
				e Total	total-g-			Ediación	
ad.	10.6 Km	File Parties				agGro+es ∰ ma/l*s	Exiterion	Hrs	. F. Den
	~~		1		PROBER NO SERVICE SERV		······································		
	·*************************************				//		*1 *17. J. M. 1884 J		
Short entitletin renaun r	A pair a l'internation imprime transfer de la constitución de la c			en en ra n. e e umare var unununganya MPPMMUMU	W bellen bestemmer en		TV-TTT AND TAKEN AND THE COLUMN AND	na vuurun/**********************************	KTRANAL AND
			National Contraction of the Cont	toneronor enciseus cues de la company			······································	1888 - 1884 - 1884 - 1884 - 1884 - 1884 - 1884 - 1884 - 1884 - 1884 - 1884 - 1884 - 1884 - 1884 - 1884 - 1884	· · · · · · · · · · · · · · · · · · ·
PER	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~								**************************************
			O-secol-debasesmassassass	PMC1 LL1 William Barrier March	PTTTC/TTTC/EDCI/OCCIO/OCCIONAL MANAGEMENT AND		Mily Mily on common commence and the second of the second	····	
Again transfer east of	No								A section of the same and an and
TVIOTERORE		The state of the s			PROPERTY AND ADDRESS OF THE PROPERTY OF THE PR			NIV CARV	NEWS 2200
	W. 1815 T. 1717 ST. 1879 T. T. 1874 ST. 1874 ST	***************************************	***************************************		data and a second a		······································		
	HERE III. AND CONTRACTOR OF THE PERSON OF TH		n skake nakabawa kuman na mana na mililih (1974) na pangapa di a	detect deficient transmission of the second					
HALL STATE OF THE		***************************************	**************************************						
			A. WAACAMA						
:760 :580			and the second of the second o	7.00		1.40 1.30	14.00 16.40		
230			16-4			1.70	15.60		
510			A think for historical section and a second section in the second section in the second section is a second section in the second section in the second section is a second section in the second section in the second sec			1.60	15.90	W. W. S. W.	
150						0.90	15.90		
1400						0.39 0.33	16.00 16.20		
950						0.33	16.20		
580					***************************************	0.28	***************************************		
680		**************************************			**************************************	0.26	16.40		
210 250						0.29	16.30 17.40		
620			**************************************			0.40 0.50	17.40		
420			erect (At 1000 and the first that a contract of the second second second second second second second second se		THE REAL PROPERTY OF THE PROPE	0.63			
750					~~~~	0.61	16,30		
:990 690	L					0.58 0.34	15.20 16.10		
090	THE RESERVE OF THE PROPERTY OF THE PARTY OF	**************************************		4, 4,	Maria da de la companio de la compa	0.24	14.50	and the second s	The state of the s
370				*** **********************************		0.29	14.20		
950		Ì				0.22	15.70		
270 560		**************************************	*			0.18 0.18	(N. 4-1-4		······································
260						0.18			
580					**************************************	0.17			***************************************
770 1100		The contract to the contract t	Accommendation to the second s	** ***********************************	n na managanan na nanagan angan na managan na managan na handi na managan na managan na managan na managan na	0.17 0.18			Annua control : 70 - 400000 meneral me
670		<u> </u>			**************************************	0.18	14.40		
660	W 2500 The Art & was the construction of the C				H-(**AAAA0730******************************	0.19	13.30		
090					***************************************	0.20			elek eleksőt Jánk, Pá kospanyogo eleksőteren
000				<u> </u>	A-4	0.14 0.20			
0	**************************************		**************************************	THE STREET, ST	(* 1880 - 1880 - 1881 - 1880 - 1880 - 1880 - 1880 - 1880 - 1880 - 1880 - 1880 - 1880 - 1880 - 1880 - 1880 - 18	0.20			
0						0.15	13.00		
0						0.15			
0				**************************************	***************************************	0.15 0.14			***************************************
0			<u> </u>		**************************************	0.14			
0	ger i in Anthon views exemplated Aggg., 4000000041, adulated as		7 2			0.14	12.30		
0	ANGER MANGEMENT AND ANGER PROPERTY AND ANGER MANGEMENT OF THE	2 2 2 3 3 4 3 4 4 4 4 4 4 4 4 4 4 4 4 4	Total commence of the commence	ger p jum gr. denniken man yn pyr yn VINSSUUNSS		0.13			-rwwsaga Madalata
Ó	and the second second		<u>}</u>	**************************************		0.14	12.00	in the second contract of the second contract	

	enty papateursea				ide 24 50 (tr			961 1 (1774), 25 1 467 9 1772	
				Operation					er og fallen For og 17 den en gjorger For og skrivet for 1
Dillo +	Zennynesi			Operation			Extracted		371
Dec-94		5.9 10.85	31 31	31	739.7 745.7		619000 493100	ט.סבי	0
Jan-95 Feb-95		2.9	28	31 20	651.8		493100		0 <u>i</u> 0
Mar-95		5.05	31	20 31	762.2		478800		0
Apr-95		5.3	30		702.2		455000	0.3	0
May-95		1.43	31		738.9		463200	0.27	0
Jun-95		2.36	30		672		436400		o o
Jul-95		0.52	31		789.9		469700		0
Aug-95		0.82	31		750.8	A COMPANY OF THE PARTY OF THE P	430600	0.29	0
Sep-95	Deep	3.14	30		717.2		409100		0
Oct-95		3.96	31		739		414700		0
Nov-95		7,72	30		723.6		405600		
Dec-95		10.12	31		740.8		458700		0
Jan-96		10.37	31		745		417100		0
Feb-96		13.63	29	···	526.7		392700		0
Mar-96		3.54	31		745.1 717.9		399100		0
Apr-96 May-96		4.93 3.98	30 31		742.7		377800 271100		0
Jun-96	The second secon	0.85	30		433.9	<u> </u>	232700	Complete the Annual Ann	
Jul-96		0.92	31	3	747.7		387400		0
Aug-96		0.14	31	*******************	742.8	š	215100		0
Sep-96		2.22	30		721.4		188800		
Oct-96		5.32	31		738.7		194900		o
Nov-96		10.2	30		489.4	1	134000		
Dec-96		17.11	31		712.6		194900		
Jan-97	Deep	9.08	31	30	716.5		186300	0.11	
Feb-97	Deep	2.2	28	28	676.6		110000	0.09	
Mar-97		6.43	31		739.7		120600		
Apr-97		3.6	30				119760		
May-97		2.2	31		739.9		123400		English of the control of the contro
Jun-97		2.42	30				133600		
Jul-97		0.38	31		744	i	122400	SACON WINNESS COLUMN AND ASSESSED FOR THE PARTY OF THE PA	
Aug-97		1.25	31		713 720.7		116900		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Sep-97		3.39 5.5	30 31		747.5		112100 121900		
Oct-97 Nov-97		5.18	30				119200		
Dec-97		3.02	31		742		128900		
Jan-98	t en	8.8	<u> </u>				276600		
Feb-98		8.35	28				262900		
Mar-98		!	31				291700		
Apr-98			30				280600	5-4 harmon and a second a second and a second a second and a second a second and a second and a second and a	
May-98	Deep		31	31	721.8		278700		
Jun-98		0.75	30				292900		
Jul-98			31				161500		
Aug-98			31				120300		
Sep-98		0.6	30				113500		
Oct-98		1.35	31				117800		
Nov-98		13.4	30				114900		
Dec-98 Jan-99		<u> </u>	31				125500		
Jan-99 Feb-99		9.2 12.5	31 28		742.6 673.1		123970 111500	A CONTRACTOR OF THE PARTY OF TH	
Mar-99		4.4	31				123000		
Apr-99		0.5	30		<u> </u>		117300		
May-99		2.05	31				120600		
	Deep	0.55	30				141200		

ater Pumping Data

			Alegada (a) Alegada (a)			CARTE NE CO			N. S. Osakin
64	a de la companya de La companya de la companya de l	Evidoses		e dalibiis	La Galleri Sast		Haloko		TE more
		<u> </u>			. Of played		Exitéction	Operated	Julius 1
0		The second secon				0.12 0.09		·	
0					**************************************	0.09	11.00 10.30		
Ω				EAT-Charlesonand		0.09	10.50		
0	and the second s					0.08	10.50		
O						0.07	10.40		
0	and the state of t	**************************************				0.06	10.80		
0	arms, W. S. on the same many control of the control of the same of		-			0.08	9.90		
0						80.0	9.60		
0					**************************************	0.07	9.50	***************************************	**************************************
0						0.09	9.40		
0		enne. La Light et distriction - manners de la parte de la commence	in the second se			0.09	9.30	· · · · · · · · · · · · · · · · · · ·	
0					**************************************	0.08 0.07	10.30 9.30	***************************************	tonbumus ===================================
0			<u></u>			0.07	12.40		
0			***************************************	·*************************************	A	0.07	8.90	***************************************	
<u>ō</u>	was to the state of the same case					0.07	8.80		
0				#A/	***************************************	0.11	6.10		[
0		and the state of t				0.06	8.90		
0						0.06	8.60		
0						0.10	4.80	1	
0						0.12	4.40		
0		danes and a succession of the	-			0.12	4.40	7 / 200 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
0		manusus at the territories of the state of t				0.13	4.60		
0						0.11	4.60	***************************************	
						0.07			
/		- A CONTRACTOR OF CASE				0.10			
None .			**************************************		of construction of the state of	0.11			A PERSONAL PROPERTY OF THE PERSON NAMED IN COLUMN 1
MATERIAL PROPERTY.			i i		######################################	0.12			
www.co.						0.12			
**********						0.12			l de la company
***************************************				•		0.13	1910 PRINCE		
***************************************			i		-	0,12		~~~	
reamann	CONTRACTOR OF THE PROPERTY OF		\$ 			0,15			
,						0,14 0,15			
*********						0.13	A STATE OF THE STA	. #74 714 dawii dan amaanii	
						0.18			
					and the same of th	0.17	**************************************		
	and a part of the second secon	- 10° 10° 40° 40° 40° 40° 40° 40° 40° 40° 40° 4		erverseverseer ded total total	,	0.18			
			-			0.23			
				***************************************		0.22			
WATER SW.						0.27			
			<u> </u>		~ ~~ ~~ ~~	0.28	\$		
	and the same and t		-		***************************************	0.27 0.27	h Danish Market and Art of the Art of Francis and Art of the Art o		
*********	- papa Phar and community or specifical decisions		<u> </u>			0.27 0.26			
annia, p			-			0.20		,	
	**************************************	**************************************	5	<u> </u>		0.27	THE WILLIAM .		
-	The second secon	Constant Con				0.26	· · · · · · · · · · · · · · · · · · ·	***************************************	
en bu bilane.		(Addisonment or other contribution de dissesse Print III (1886)	\$			0.25			***************************************
						0.18	PERSONAL PROPERTY OF THE STATE		
<u></u>	41444				***************************************	0.26		7	XIIII.
						0.26			

Deep Aquifer Groun

					Takon ka				
				British Segretter	55,Ve1616	io III di Pannista	68163		
	Zone erre			Die elotton		Sinaitii.			
Jul-99	Deep		31	31	745.4		119300	0.29	
Aug-99	Deep	0.85	31	31	745.9		117400	0.27	
Sep-99	Deep		30	30	723.8		112600	0.29	
Oct-99	Deep	2.5	31	31	744.1	Ī	115300	0.28	
Nov-99	Deep	7.3	30		719.8		112500	0.29	
Dec-99	Deep	6	31	31	745.3		147400	0.42	
Jan-00	Deep		31	31	743.1		122400	0.36	
Feb-00		5.65	29		696.1		114100	0.34	
Mar-00		2.75	31	31	740		120000	0.37	
Арг-00		1.55	30		718.5		115300	0.36	
May-00		1.95	31	31	747.2	}	120500	0.41	
Jun-00		0.7	30		719.7		130300	0.47	
Jul-00		0.1	31		740		116900	0.47	7.3
Aug-00		0	31	31	743.6		140500	0.57	7.8
Sep-00		0.85	30		336		255600	0.11	7.5
Oct-00		2.7	31	0	0		0	0	. 0
Nov-00		2.1	30		0	1	0	0	0
Dec-00		4.75	31	24	508.6	4 1	106410	0.47	7.2
Jan-01	Deep	2.25	31	31	740.8	3 1	142900	0.72	7.9
Feb-01		1.45	28		673	<i>t</i> 1	263200	0.33	7.4
Mar-01		2.75	31	31	738.6	1 1	318300	0.5	7.5
Apr-01		1.55	30		724.5		322000	0.43	7.9
May-01		0.95	31	31	739.7		301100	0.48	7.7
Jun-01		1.8	30		715.5		294300	0.54	7.6
Jul-01		0.35	31		747.6		274900	0.57	7.7
Aug-01		0.8	31	.i	733.7		284400	0.71	7.7
Sep-01		0.85	30		724.9		293200	0.8	7.6
Oct-01		2.85			741		175600	0.48	7.8
Nov-01		6.7	30		768.2		219900	0.51	7.6
Dec-01		7.6	31		694.8		249100	0.71	7.8
Jan-02	;		31	<u> </u>	744.7		272300	0.7	7.7
Feb-02			28		674.4	t	241800	0.6	7.9
Mar-02			31		740.8		265100	0.69	7.6
Apr-02			, 30		713.1		220900	0.59	7.9
May-02			31	31	743.8		230000	0.59	7.7
Jun-02			30		720.1		221000	0.53	7.6
Jul-02			31	31	744.6		215600	0.52	7.3
Aug-02		<u> </u>	31	31	741.3		209100	0.54	7.8
Sep-02			30	<u> </u>	725.3		192700	0.5	7.5
Oct-02			31	30	718.7	<u> </u>	187200	0.5	7.5
Nov-02			30		741	ž	209700	0.63	7.3
Dec-02	neeb	L	31	31	744.5	<u> </u>	221700	0.65	7.4

ater Pumping Data

				7 (F)			7. 17. XX		
	Februari de u			77 Au					erus pu Pius le cus
	an integration	eni (ag ule j e)		şuerber	39 Sq. (1992)				
	······································		g			0.29			
						0.28			
						0.31			
						0.29		``	
				<u></u>		0.31			1
	· · · · · · · · · · · · · · · · · · ·		<u> </u>			0.34			}
	**************************************		-			0.35			
**********	Accompany of the second se					0.36			
***********	The state of the s					0.37			
			. 2			0.37			
		**************************************	- 3			0.41			
******						0.43			
						0.48			
			99			0.49			1
			Ł,			0.49		i	
	·								
0									
0			į			0.53			
			į.			0.60			
				·		0.15			
						0.19			
						0.16			1
						0.19			
			37			0.22			
				1		0.25			
			5.	1		0.3			
			i,			0.33			
I						0.33			
			4	4.		0.28			
						0.34			
			- 2	-		0.31			
	Annual Control					0.30		road Military and a string to make a second	
						0.31		Sec. 4	1
						0.32			
						0.31			
			: 12			0.29			
		,			,	0.29			
						0.31			
I			-			0.31			
						0.32			
						0.36			
J						0.35		······································	

Deep Aquifer Chromium (

E de la companya de l	file tak				4			
Jul-91	7.35	2.23		1611 47.00 M.C.O	######################################	0	0	
Aug-91	4.12	4.7		***************************************		0.145	0.37	AND DESCRIPTION OF THE PERSON
Sep-91	o	4.1				i O	0.39	
Oct-91	2.3	6.9				0.12	0.55	
Nov-91	Ō	0			***************************************	0	0	-
Dec-91	0	0				0	ol o	W-WILL-U.A.
Jan-92	0	0				O	0	300,000,000
Feb-92	0	0				O	0	
Mar-92	0.33	1.4		1		0.12	0.1	
Apr-92	0	0				0	0	
May-92	0	0				0	Ō,	
Jun-92	l ol	0				0	0	
Jul-92	0	0				0	0	M <u>. 202_</u>
Aug-92	i o	0			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	0	0	
Sep-92	0.1	3		***************************************		0.1	0.1	
Oct-92	0.1	3.3	armae - 100 inim secono mett 1889			0.1	0.1	
Nov-92	0.1	3.4				0.1	0.1	Marcaga TUM
Dec-92	0.1	3.1	and the same of th		ļ.	0.1	0.1	
Jan-93	0	0				0	0	-
Feb-93	0	0			<u> </u>	0	0	
Mar-93	0.1	0.74	The second secon	-	• • • • • • • • • • • • • • • • • • •	0.1	0.1	*********
Apr-93	0	0				0	0	
May-93	0	0			<u> </u>	0	0	- 44 <u>6</u> 2 : 3,5000000.
Jun-93	0.1	0.86	***************************************			0.1	0.1	
Jul-93	0	0.72			<u> </u>	0	0	at makes a second
Aug-93	0	0.74		<u> </u>		0	0	
Sep-93	0.02	0.66		<u> </u>		0.03	0.01	**********
Oct-93	<u> </u>	0.84				0	0	indinantana si sa
Nov-93	0	0		<u> </u>	<u> </u>	0	0	
Dec-93	0.01	0.8				0.03	0.01	
Jan-94	0	0 0		<u> </u>	<u> </u>	0	<u>O</u>	·
Feb-94	0	The state of the s				0	0	
Mar-94	0			<u> </u>		0.01	<u> </u>	W\$************************************
Apr-94 May-94	0	<u>0</u> 0		Marine modes A.C. C. L. Printer Properties and C. L.	<u> </u>	0	0	
		0.56		<u> </u>		0	0	
Jun-94 Jul-94	0.01	dae o o mano esta a companya a mana sa canada	AND THE PERSON NAMED IN COLUMN TWO			0.01	0	***************************************
Aug-94	0	0		-		0	0	
Sep-94	0			1	<u> </u>	0.01	0	notonements.
Oct-94		0.0	CONTRACTOR OF THE PROPERTY OF THE PARTY OF T	<u> </u>		0.01	The same of the sa	remease of
Nov-94		0	The second secon		<u> </u>	0	The second secon	KHOGEANA: TEE
Dec-94	0.01	0.38		<u> </u>	<u> </u>	0.01	0.01	
Jan-95	0.01	0.36			<u> </u>	0.01	0.01	
Feb-95				**************************************	<u> </u>	0	0	
Mar-95	1 0			***************************************	<u> </u>	0.01	0	pprocesses with the
Apr-95	O	0.20	The same of the sa	<u> </u>		0.01	0	******
May-95	0	0		<u> </u>	<u> </u>	0	وموممونين وأروي ومعاصمون والمعاصيين	******************
Jun-95	0.01	0.29	X	-	<u> </u>	0.01	and the second s	Alaman de Av
Juiradi	J U.U.)	V.23	T	E H T-F-M-Cucuscan area - Militeration (Material	1	U.U1)	V.V I	*******

centration Results (mg/L)

i ka ji			The Tar				Deep *	
				DW-		Deep aquiler	aquifer discharged/	1946
DW 15.	₩ 16	DWAR	NEW S	- Combined	Control of the contro	discharged		Deep/DW-09
0	0		0	0				
0.1	0.1		0.18	1.9	**************************************	Company of the Compan		
0.1	0.1		0.16	1.2				
0.1	0.1		0.14	1.6	المنافقة الم		~~1	
0	0	and the second s	0	1.4	· be-lance of the second secon		Market	
0	0		0	8.0			MINICH INC.	
0 0	0		0 0	0.38 0.34	manuscologic staticity communication of the decision of the second	7		
0.1	0.1		0.1	0.34	anna a saidh air air air an ann an air ann air air fhan		managana (1900) (kanagana ana 1901) (kanagana ana ana ana ana ana ana ana ana	ACTIVITY LICENSE AND THE PROPERTY OF THE PROPE
0.1	0.1		0.1	0.29				
0	0		0	0.27				
0	0		0	0.27				
0	0		0	0.39	e diene, generalise in many generalise in militarise			
0	0		0	0.44	***************************************		400 m	
0.1	0.1		0.1	0.56				
0.1	0.1		0.1	0,6				
0.1	0.1		0.1	0.6	menocono de Paramento de 1980 d			
0.1	0.1		0.1	0.26	····			
0	0		0	0.24				
0	0		0	0.29				,
0.1 0	0.1		0.1	0.22 0.18	na ann an an an Aireann ann an an an Aireann ann an Aireann an Aireann ann an Aireann ann an Aireann ann an Ai		······································	
0	0 0		0 0	0.18				
0.1	0.1		0.1	0.18				
0.1	0.1	<u> </u>	0.1	0.17	taan kendangan penggapat di Seberah di Andrika di Andri			
0	0	The same of the sa	0	0.17				
0.07	0.07		0.01	0.18				
0	0		0	0.17	**************************************	İ		
0	0		0	0.19				
0.13	0.07		0.01	0.2				
0	0		. 0	0.14				
0	0		0	0.2				
0.06			0					
0		<u></u>	0	0.15				
0.07		<u></u>	0					
0.07		And the second s	0.01 0	0.15 0.14				
0		\$	0					
0.1	0.03		0					
0.1	And the second section of the second		0	and the second section and the section and the section	Emma			
0			0	The same of the sa	A CONTRACTOR OF THE PARTY OF TH		The state of the s	
0.07	0.02		0.01	0.12				
0			0	The second secon				
0	The second secon		0	THE PERSON NAMED IN COLUMN PARTY AND ADDRESS OF THE PERSON NAMED IN COLUMN PAR	NAME OF TAXABLE PARTY OF THE PARTY OF TAXABLE PARTY.			
0.06			0					
0		<u> </u>	0	The state of the s				
0	Total state and the second state of the second	I was a second of the second o	0	The second secon	The second secon	anger - manaffert (d. Affersanders som menses) ^{er e} (*1000) (*1000) (*1000) (*1000)		
0.08	0.02		0.01	0.06	arananany state was recommended to 10000 a		C. S.	

Deep Aquifer Chromium C

		andres more ser in the					entage comment to the comment of the		488.
Jul-95		0	<u>। विशेष</u> 0	AND AND AND EASING				0	aavay
Aug-95		0	0			A SPECIAL SECURITY OF SPECIAL SECURITY	0 0	0	Thermos of the second second
Sep-95	······································	0	0.27				0.01	0	
Oct-95		0) 0)	0.27				0.01	0	COMPANIE CONTRACTOR
Jun-96				0.2	0.01			0.01	
Dec-96			0.11	0.07	0.01		· · · · · · · · · · · · · · · · · · ·	0.01	
Jan-97			0.12						
Mar-97		***************************************	0.12						A DES PROPERTIES DE L'ANGEL DE L'
Apr-97		·····	0.11		and the second s				
May-97			0.12				· · · · · · · · · · · · · · · · · · ·		
Jun-97		**************************************	0.12	0.02	0.01			0.01	
Jul-97			0.12				**************************************		
Aug-97			0.13	····-					
Sep-97			0.12						, MTM.
Oct-97	~~~	·	0.15					1	
Nov-97			0.14						manyana na adalah terdangan mem
Dec-97	· · · · · · · · · · · · · · · · · · ·		0.15	0.17	0.01			0.01	Popular Vincian Vincia
Jan-98			0.13		programma de la companya y processo de la recognicación de la companya de la companya de la companya de la comp	N. A. C. T. C.			pellitte Mensonen menson Hillian om
Feb-98			0.18						
Mar-98		·	0.17						
Apr-98			0.18	1					
May-98			0.23						ng M. W. Kindonsong paga Milakin
Jun-98			0.22	0.02	0.01			0.01	
Jul-98			0.27	***************************************					
Aug-98			0.28	***************************************	<u> </u>				
Sep-98			0.27	***************************************				Î	
Oct-98			0.27	····	ption by the transfer of the state of the st				
Nov-98			0.26		,				
Dec-98	-		0.27	0.05	0.01			0.01	and the same of th
Jan-99			0.27		ezakon ir ministronin en erikisti , kon				
Feb-99			0.26						
Mar-99			0.25						
Apr-99			0.18						
May-99			0.26						
Jun-99			0.26	0.05	0.01			0.01	
Jul-99			0.29		Statement Williams				
Aug-99			0.28						
Sep-99			0.31			Sinks up 194 WHO has a supply grant of the supply	**************************************		
Oct-99		,	0.29		processor was one of the second	Manhamat Manhamat Anna A Mathaman	arataa Walio		
Nov-99			0.31						· · · · · · · · · · · · · · · · · · ·
Dec-99			0.34	0.12	0.01			0.01	·····
Jul-00						THE OWNER OF THE OWNER OF THE OWNER OF THE OWNER OF THE OWNER OWNER OWNER OWNER OWNER OWNER OWNER OWNER OWNER			
Aug-00		~*************************************				**************************************			- Marie and a single of the second
Sep-00	0.01		<u> </u>	······		0.01			NO.NO. TOWNS 4000 ~ COSTS
Dec-00					parameter and the state of the				· ·
Jan-01	0.01		0.61	0.07	0.01	0.01		0.01	na non' Wallio anno anno anno anno anno anno
Feb-01	-Au		0.46	0.13		talanna e ^{tri} iri talanna en en e e e e e e e e e e e e e e e	manacaran Militar Militaria de la marca		and a supplied the control of the supplied the control of the supplied the control of the supplied the suppli
Mar-01			0.45	0.05	رود درود درود درود درود درود درود درود	элгэн он эт тайгаан та	property and the contract of t	1	

centration Results (mg/L)

						Stage Stage	Deeb	
				. DW-		Deep aquifer	aquirer discharged/	Deep/DW-09
		ai Di Walio		Gombined	Deep	discharged	_DW-08	Deep/DW-09
0	0 0		0	80.0				
0.05	0.02		0	0.08 0.07	<u> </u>		W	
0.03	0.02		0	0.07			- Particular of the Control of the C	and the second s
		0.01	0.01	0.00		Annual State Company of the Company	mileminesementementementementementementementem	**************************************
		0.01	0.01					
	The state of the s			***************************************	THE OWNER OF THE OWNER OF THE OWNER.			Communication of the Communica
		0.01	0.01					
		<u> </u>						
							**************************************	,
					The second secon			
		0 04	0.04		and the same of th			,
		0.01	0.01		THE RESERVE THE PROPERTY OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS		and the second s	
							***************************************	, , , , , , , , , , , , , , , , , , ,
		0.01	0.01					W

							······································	
		0.01	0.01					
				, , , , , , , , , , , , , , , , , , ,	~			
				·	<u> </u>			
		0.01	0.01					
**************************************	gan gangaya gayaka walina asan da asan asan da asan galiyabil bili di sa kan asan asan			And the state of t				
					,			
***************************************		~ ~ ~ ~	A A4					
		0.01	0.01	·			0.48	
					·		0.49	
	anaga, mangabatta bili dalah mangan, na panaga, dalah	The second section of the second section of the second second second second second second second second second		**************************************	Anny a. a. A Sid-141001100) or ying personne at a filled the 1 mills of	<u> </u>	0.49	
							0.53	
		0.01	0.01				0.6	
heate and the second				Mark Lance William Company of the Company		0.15		
		<u> </u>				0.19		

Deep Aquifer Chromium C

	2000 2000 21(e)//20	5 00 00 00 00 00 00 00 00 00 00 00 00 00		segge en 2008 Segge Later (Mexica		igina (1977) Santanan Santanan			Apple 5	
Apr-01	0.01		0.38	0.05		0.01	-	0.01	0.	
May-01		ĺ	0.43	0.05						
Jun-01		***	0.33	0.18						
Jul-01			0.38	0.2	-					
Aug-01	and the same of th		0.37	0.31						
Sep-01		0.01	0.37				0.03	0.01		
Oct-01			1.1	0.33						
Nov-01			1.1	0.28						
Dec-01			0.16							
Jan-02			0.28				·			
Feb-02			0.26	0.42						
Mar-02		0.01	0.28	0.26	0.01		0.01	0.01		
Apr-02			0.31	0.47			·	-		
May-02			0.29	0.37						
Jun-02			0.23							
Jul-02			0.24	£	<u> </u>					
Aug-02			0.23							
Sep-02		0.01	0.26		0.01		0.01	0.01		
Oct-02			0.24	0.44						
Nov-02			0.17	0.38						
Dec-02			0.23	0.37						

entration Results (mg/L)

		EWE 7		DW- Combined		Deep aquijer discharged	Deep aquiler discharged/ DW-08	Deep/DW-09
	0.01	0.01	0.01		0.16			
					0.19		Company of the control of the contro	
					0.22			
					0.25			
					0.3			
0.08					0.33			
								0.33
								0.28
	~ <u></u>				0.34		and the second s	
						0.31		
						0.3		
0.02						0.31		
						0.32		
						0.31		
		<u> </u>				0.29		
	·					0.29		
						0.31		
0.08	O					0.31		
					<u> </u>	0.32		
					<u> </u>	0.36		
		<u> </u>			<u> </u>	0.35		

Appendix D - United Chrome Groundwater Use Deed Restriction



Public Works 1245 NE 3rd Street P.O. Box 1083 Corvallis, OR 97339-1083 (503) 757-6916 FAX (503) 757-6920

April 2, 1993

Allan Goodman
Oregon Operations Office
Environmental Protection Agency
811 S.W. Sixth Avenue, 3rd Floor
Portland, Oregon 97204

UNITED CHROME DEED RESTRICTION

Attached is the United Chrome deed restriction required by United Chrome Consent Decree, Civil Action No. 92-6232-HO. Please review the deed restricting groundwater use or pumping wells and approve it as required by the Decree.

If you have any questions, please contact me 757-6916. Thank you.

Norman Hepner

Environmental Engineer

NH/ms

cc:

Rolland Baxter, Public Works Director


Tom Penpraze, Operations Division Manager

Scott McKinley, CH2M Hill

Paul Burnett, ODEO

CITY OF CORVALLIS AIRPORT CHROME TREATMENT SITE OFFSITE GROUNDWATER USE RESTRICTION EASEMENT

Beginning at the southeast corner of the Alfred Rhinehart Donation Land Claim No. 73, located in Township 12 South, Range 5 West of the Willamette Meridian, Benton County, Oregon; thence S 36'27'19'E, 911.51 feet to the TRUE POINT OF BEGINNING; thence WEST, 2224.65 feet; thence NORTH, 2235.38 feet to the south right of way of Airport Road; thence along said south right of way in and easterly direction to a point that is NORTH of the TRUE POINT OF BEGINNING; , thence SOUTH, 1878.40 feet to the TRUE POINT OF BEGINNING.



FILE: \FORE\EMC\SURFET\POBVRES\CHROMEDIG DITE: FER, 1903 BT: W BECLOW